

AD-A105 254

HOSKINS-WESTERN-SONDEREGGER INC LINCOLN NE

F/G 13/13

NATIONAL DAM SAFETY PROGRAM. LAKE THUNDERHEAD DAM (MO 10007), G--ETC(U)

MAY 80 R S DECKER, G JAMISON, G ULMER


DACW43-80-C-0071

NL

UNCLASSIFIED

1 of 3

AD-A
10-254



AD A105254

LEVEL II

①
BS

GRAND-CHARITON BASIN

LAKE THUNDERHEAD DAM
PUTNAM COUNTY, MISSOURI
MO 10007

DTIC
ELECTE
OCT 09 1981
S **D**
E

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



United States Army
Corps of Engineers
... Serving the Army
... Serving the Nation

St. Louis District

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.
THE COPY FURNISHED TO DDC CONTAINED A
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.

MAY, 1980

This document has been approved
for public release and sale; its
distribution is unlimited.

This document has been approved
for public release and sale; its
distribution is unlimited.

81 10 7 062

DISCIPLE COPY

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER	
	AD-A105254		
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Lake Thunderhead (MO 10007) Putnam County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report.	
7. AUTHOR(s) Hoskins-Western-Sonderregger, Inc. Rey S. /Decker Gordon /Jamison Garold /Ulmer Harold P. /Hoskins		6. PERFORMING ORG. REPORT NUMBER	
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-80-C-0071	
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 21037	
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) National Dam Safety Program. Lake Thunderhead Dam (MO 10007), Grand - Chariton Basin, Putnam County, Missouri. Phase I Inspection Report.		12. REPORT DATE May 80.	
16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) Approved for release; distribution unlimited.		13. NUMBER OF PAGES Approximately 200	
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report) UNCLASSIFIED	
18. SUPPLEMENTARY NOTES		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams			
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.			

DD FORM 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

LAKE THUNDERHEAD DAM
PUTNAM COUNTY, MISSOURI
MISSOURI INVENTORY NO. MO 10007

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY
HOSKINS-WESTERN-SONDEREGGER, INC.
CONSULTING ENGINEERS
LINCOLN, NEBRASKA

UNDER DIRECTION OF
ST. LOUIS DISTRICT, CORPS OF ENGINEERS

FOR
GOVERNOR OF MISSOURI
MAY, 1980

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Avail and/or	
Dist	
A 23	



REPLY TO
ATTENTION OF

DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 TUCKER BOULEVARD, NORTH
ST. LOUIS, MISSOURI 63101

LMSD-P

SUBJECT: Lake Thunderhead Dam Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Lake Thunderhead Dam (MO 10007).

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- a. Spillway will not pass 50 percent of the Probable Maximum Flood without overtopping the dam.
- b. Overtopping of the dam could result in failure of the dam.
- c. Dam failure significantly increases the hazard to loss of life downstream.

SIGNED

SUBMITTED BY:

Chief, Engineering Division

17 SEP 1980

Date

SIGNED

APPROVED BY:

Colonel, CE, District Engineer

18 SEP 1980

Date

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

TABLE OF CONTENTS

<u>PARAGRAPH NO.</u>	<u>TITLE</u>	<u>PAGE NO.</u>
	Assessment Summary	
	Overview Photograph	
	SECTION 1 - PROJECT INFORMATION	
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	3
	SECTION 2 - ENGINEERING DATA	
2.1	Design	6
2.2	Construction	6
2.3	Operation	6
2.4	Evaluation	6
	SECTION 3 - VISUAL INSPECTION	
3.1	Findings	8
3.2	Evaluation	11
	SECTION 4 - OPERATIONAL PROCEDURES	
4.1	Procedures	12
4.2	Maintenance of Dam	12
4.3	Maintenance of Operating Facilities	12
4.4	Description of Any Warning System in Effect	12
4.5	Evaluation	12
	SECTION 5 - HYDRAULIC/HYDROLOGIC	
5.1	Evaluation of Features	13
	SECTION 6 - STRUCTURAL STABILITY	
6.1	Evaluation of Structural Stability	15
	SECTION 7 - ASSESSMENT/REMEDIAL MEASURES	
7.1	Dam Assessment	16
7.2	Remedial Measures	17

APPENDIX A - MAPS

Plate A-1	Vicinity Topography
Plate A-2	Location Map
Plate A-3	Drainage Area Map

APPENDIX B - PHOTOGRAPHS

Plate B-1	Photo Index	
Plate B-2	Photo No. 2	Overview of Dam from Upstream on Left
	Photo No. 3	Emergency Spillway Crest from Left
Plate B-3	Photo No. 4	View Upstream in Emergency Spillway
	Photo No. 5	View Downstream in Emergency Spillway
Plate B-4	Photo No. 6	Emergency Spillway and Sewage Lagoons
	Photo No. 7	Erosion on Upstream Slope
Plate B-5	Photo No. 8	Upstream Face from Left End
	Photo No. 9	Upstream Face and Crest
Plate B-6	Photo No. 10	View Upstream with Principal Spillway Inlet in Foreground
	Photo No. 11	Downstream Bay of Principal Spillway Inlet
Plate B-7	Photo No. 12	Upstream Bay of Principal Spillway Inlet Showing Slide Gate
	Photo No. 13	Crest of Dam
Plate B-8	Photo No. 14	Crest of Dam
	Photo No. 15	View Downstream Showing Old Channel
Plate B-9	Photo No. 16	Upstream Face from Right End
	Photo No. 17	Downstream Face from Right End
Plate B-10	Photo No. 18	Gully Eroded in Right Abutment Trough
	Photo No. 19	Concrete Lined Ditch in Right Abutment Trough
Plate B-11	Photo No. 20	Cattails and Willow Tree Growing in Ditch in Berm
	Photo No. 21	Small Rodent Hole in Downstream Slope
Plate B-12	Photo No. 22	View Downstream in Old Channel
	Photo No. 23	Seep Area Around and to Left of Sewage Lift Station
Plate B-13	Photo No. 24	Manhole on Sanitary Sewer Crossing Berm
	Photo No. 25	Seep Area Around Lift Station
Plate B-14	Photo No. 26	Seepage Discharge from Lift Station Area
	Photo No. 27	Seepage Around Upstream Side of Lift Station
Plate B-15	Photo No. 28	Principal Spillway Outlet
	Photo No. 29	Tree and Rodent Hole at Right Side of Spillway Chute
Plate B-16	Photo No. 30	Downstream Slope
	Photo No. 31	Spalling of Concrete in Principal Spillway Outlet

APPENDIX B - PHOTOGRAPH (CONTINUED)

Plate B-17	Photo No. 32	Scour and Slumps in Right Side of Principal Spillway Scour Hole
	Photo No. 33	Outlet of Principal Spillway
Plate B-18	Photo No. 34	Weep Holes in Left Wall of Spillway Outlet Channel
	Photo No. 35	Lower End of Outlet Channel for Principal Spillway
Plate B-19	Photo No. 36	Seep in Outlet Channel of Emergency Spillway
	Photo No. 37	Seepage from Sewage Lagoons
Plate B-20	Photo No. 38	Surface Drain Ditch along Berm
	Photo No. 39	Connection of Sewer Line under Dam with Lift Station
Plate B-21	Photo No. 40	Outlet for Drain in Bottom of Lift Station
	Photo No. 41	Farmstead about 1 Mile Downstream on Left Side
Plate B-22	Photo No. 42	Farmstead shown in Photo No. 41
	Photo No. 43	Farmstead on Right Side Approximately 1 Mile Downstream

APPENDIX C - PROJECT PLATES

Plates C-1 through C-25	Construction Plans by W. H. Klingner and Associates dated March, 1965.
Plates C-26 through C-29	Sanitary Sewer plans by W. H. Klingner and Associates dated June, 1966
Plate C-30	Plate C-5 Modified to show Sanitary Sewer and Water Main Layout and Deficiencies observed during Phase I Inspection
Plate C-31	Phase I - Maximum Cross Section
Plate C-32	Phase I - Centerline Profile along Top of Dam
Plate C-33	Phase I - Profile along Emergency Spillway Centerline

APPENDIX D - HYDRAULIC AND HYDROLOGIC DATA

Plates D-1 & D-2	Hydrologic Computations
Plate D-3	Principal Spillway Rating Curve
Plate D-4	Emergency Spillway Rating Curve
Plate D-5	PMF Ratio-Discharge Curve
Plates D-6 to D-49	Computer Input and Output for Ratios of PMF

APPENDIX E - FOUNDATION, EMBANKMENT AND INSPECTION REPORTS

Division I	Soils Report, Putnam County Lake, October, 1964
Division II	Soil Analysis, Log of Soundings, Dated August and September, 1964
Division III	Geologic Report on Proposed Putnam County Lake Site, Missouri Geological Survey, 1963 Inspection Report, Missouri Geological Survey, 1972 Engineering Geologic Report, Missouri Geological Survey, 1978

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM
ASSESSMENT SUMMARY

Name of Dam	Lake Thunderhead Dam
State Located	Missouri
County Located	Putnam County
Stream	North Blackbird Creek
Date of Inspection	May 6, 1980

Lake Thunderhead Dam was inspected by an interdisciplinary team of engineers, ~~from Hoskins-Western-Sonderregger, Inc.~~ The purpose of the inspection was to make an assessment of the general conditions of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

Lake Thunderhead Dam has a height of fifty-four (54) feet and a storage capacity at the minimum top elevation of the dam of twenty-seven thousand four hundred (27,400) acre-feet. In accordance with the guidelines, an intermediate size dam has a height greater than or equal to forty (40) feet but less than one hundred (100) feet and a storage capacity greater than or equal to one thousand (1,000) acre-feet but less than fifty thousand (50,000) acre-feet. The size classification is determined by either the storage capacity or height, whichever gives the larger size category. Lake Thunderhead Dam is classified as an intermediate size dam.

In accordance with the guidelines and based on visual observation, the dam is classified as having a high potential for damage and loss of life. Failure would threaten life and property. The estimated damage zone extends approximately twenty (20) miles downstream of the dam to the confluence of North Blackbird Creek and South Blackbird Creek. Within the first six miles of the damage zone are six dwellings and some outbuildings. Missouri Highway 5 is immediately downstream; Missouri Highway 129 is approximately four miles downstream; and U.S. Highway 136 is about eleven miles downstream. The valley is extensively farmed for its full length.

Our inspection and evaluation indicates that the spillways do not meet the criteria set forth in the recommended guidelines for an intermediate dam having a high hazard potential. The Probable Maximum Flood is the appropriate spillway design flood. The spillways will pass the 100-year flood (1% probability flood - a flood having a one percent chance of being exceeded in any year) without overtopping the dam. The Probable Maximum Flood (PMF) is defined as the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.

Construction plans, a soils report and a geological report were available for this dam and are included in this report. Based on the information available from the plans and reports and the observations made during the field inspection, the following remedial measures and maintenance procedures are recommended. All remedial measures should be performed under the guidance of a registered professional engineer experienced in the design and construction of earth dams.


a. Alternatives.

- (1) The spillway size and/or the height of dam should be increased to pass the probable maximum flood without overtopping the dam.

b. Operation and Maintenance Procedures.

- (1) Stability and seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" should be performed for appropriate loading conditions including seismic forces. These analyses should be performed by a professional engineer experienced in the design and construction of dams.
- (2) Studies should be conducted to determine the source and effects of seepage discharging around the sewage lift station. This may require installation of piezometers and/or closed circuit television inspection of the sanitary sewer line which passes under the reservoir and the dam. This should be done under the guidance of a professional engineer experienced in the design and construction of dams. Remedial measures may be required.
- (3) The trees growing on the upstream slope as well as the tree growing along the right wall of the principal spillway should be removed under the guidance of a professional engineer experienced in the design and construction of dams.
- (4) Additional riprap should be placed on the left end of the dam.
- (5) The headcut and gully erosion in the right abutment trough downstream from the berm should be repaired and measures taken to control future erosion in this area.
- (6) The slumps and/or slides in the right bank of the scour hole downstream from the principal spillway outlet should be repaired and stabilized.
- (7) The concrete deterioration in the headwall of the principal spillway outlet should be repaired.
- (8) The grass on the downstream slope should be mowed and measures taken to control the growth and amount of litter that accumulates. Rodent holes or other surface scars revealed by the mowing should be repaired.

- (9) The rodent hole along the right wall of the principal spillway outlet should be repaired.
- (10) A program of periodic inspection and maintenance should be initiated in order to protect the integrity of the dam.




Rey S. Decker
E-3703



Gordon Jamison



Garold Ulmer
E-19246



Harold P. Hoskins, Chairman of the Board
Hoskins-Western-Sonderegger, Inc.
E-8696



PHOTO NO. 1 - OVERVIEW

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
LAKE THUNDERHEAD DAM - MO 10007
PUTNAM COUNTY, MISSOURI

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority. The National Dam Inspection Act. Public Law 92-367, authorized the Secretary of the Army through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of Lake Thunderhead Dam be made.
- b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.
- c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams," Appendix D to "Report of the Chief of Engineers on the National Program of Inspection of Dams," dated May, 1975, and published by the Department of the Army, Office of the Chief of Engineers.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances.
 - (1) The dam is an earth fill approximately 1700 feet in length and 54.4 feet in height. The dam impounds the flow from North Blackbird Creek to form a reservoir covering about 1050 acres. The maximum water storage at the minimum top of dam elevation is 27,400 acre-feet. The dam is located about 3.5 miles north of Unionville, Missouri.
 - (2) The principal spillway consists of a 7' x 18' reinforced concrete drop inlet (riser) which is connected to a 6' x 7' reinforced concrete box conduit. The spillway is located toward the left end of the dam (Sta. 6+50). The spillway outlets into a reinforced concrete St. Anthony Falls (S.A.F.) type energy dissipator.

- (3) A vegetated earth uncontrolled emergency spillway is cut through the left abutment. The crest or control section of the spillway is the asphalt surfaced road that crosses the dam. The width of the emergency spillway at the crest is approximately 200 feet. The spillway outlets into North Blackbird Creek about 450 feet downstream from the toe of the dam.
- (4) Pertinent physical data are given in paragraph 1.3 below.
- b. Location. The dam is located about 3.5 miles north of Unionville in the north central part of Putnam County, as shown on Plate A-2. The dam is located in Sections 10 and 15, T66N, R19W, as shown on Plate A-1.
- c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Lake Thunderhead Dam has a height of 54 feet and a storage capacity of 27,400 acre-feet. This dam is classified as an intermediate size dam. An intermediate size dam has a height greater than or equal to 40 feet but less than 100 feet and a storage capacity greater than or equal to 1,000 acre-feet but less than 50,000 acre-feet. The size classification is determined by either the storage or height, whichever gives the larger size category.
- d. Hazard Classification. Guidelines for determining hazard classification are presented in the same guidelines as referenced in paragraph 1.1c above. Based on referenced guidelines, this dam is in the High Hazard Classification. The estimated damage zone extends approximately twenty miles downstream to the confluence of North Blackbird Creek and South Blackbird Creek. Visual inspection verifies that within the first six miles of the damage zone are six dwellings and some outbuildings. Missouri Highway 5 is immediately downstream; Missouri Highway 129 is approximately four miles downstream, and U.S. Highway 136 is about eleven miles downstream. The valley is extensively farmed for its full length.
- e. Ownership. The dam is owned by Chillicothe Properties, Inc., Garry Dickinson, President, Box 784, Chillicothe, Missouri 64601.
- f. Purpose of Dam. The dam impounds a 1050 acre recreational reservoir. It also provides flood protection on North Blackbird Creek.
- g. Design and Construction History. The dam was designed by W. H. Klingner & Associates, Quincy, Illinois. Portions of the construction plans for the dam are included with this report in Appendix C. The dam was constructed in 1965 by Howard Construction Co., Sedalia, Mo. According to Ms. Quigley, Unionville City Clerk, this project was financed by a loan from the U.S.D.A. Farmers Home Administration (FHA) to the Putnam County Lake Association, Inc.

- h. Normal Operating Procedure. The spillways are uncontrolled. According to Mr. Cawley, former Lake Association Manager, the reservoir level is lowered 4 feet every fall to provide additional flood storage and to protect shoreline facilities.

1.3 PERTINENT DATA

- a. Drainage Area. 15,580 acres (24.34 square miles). Includes area of Unionville City Reservoir (1.4+sq. mi.).
- b. Discharge at Damsite.
- (1) All discharges at the damsite are through an uncontrolled reinforced concrete drop inlet (riser) with a reinforced concrete box conduit through the dam and an uncontrolled vegetated earth spillway cut through the left abutment with a bituminous covered road normal to the spillway acting as a weir control.
 - (2) Estimated maximum flood at damsite - just below crest of emergency spillway according to report by Mr. Cawley.
 - (3) The principal spillway capacity varies from 0 c.f.s. at elevation 969.0 feet to 1,170 c.f.s. at the crest of the emergency spillway (elevation 973.0 feet) to 1,370 c.f.s. at the minimum top of dam (elevation 977.4 feet).
 - (4) The emergency spillway capacity varies from 0 c.f.s. at its crest elevation 973.0 feet to 6,900 c.f.s. at elevation 977.4 feet (minimum top of dam).
 - (5) Total spillway capacity at the minimum top of dam is 8,270 c.f.s. ±.
- c. Elevations. (Feet above M.S.L.)
- (1) Observed pool - 968.2
 - (2) Normal pool - 969.0
 - (3) Spillway crests
 - Principal - 969.0
 - Emergency - 973.0 (Minimum, top of roadway)
 - (4) Maximum experienced pool - 972+
 - (5) Top of dam (minimum) - 977.4 (Minimum on left end)
 - (6) Stream bed at centerline of dam - 923±
 - (7) Maximum tailwater - Unknown
- d. Reservoir. Length (feet) of pool.
- (1) Principal spillway - 28,000+
 - (2) Emergency spillway - 32,000±
 - (3) Top of dam (minimum) - 36,000±

e. Storage (acre-feet).

- (1) Observed pool - 15,700+₋
- (2) Normal pool - 16,500+₋
- (3) Spillway crest(s)
 - Principal - 16,500 +₋
 - Emergency - 21,100 +₋
- (4) Maximum experienced pool - 20,000 +₋
- (5) Top of dam (minimum) - 27,400 +₋

f. Reservoir Surface (Acres).

- (1) Observed pool - 1,000 +₋
- (2) Normal pool - 1,050 +₋
- (3) Spillway crest (s).
 - Principal - 1,050 +₋
 - Emergency - 1,300 +₋
- (4) Maximum experienced pool - 1,250 +₋
- (5) Top of dam (minimum) - 1,570 +₋

g. Dam.

- (1) Type - Rolled earth fill
- (2) Length - 1,700 feet +₋
- (3) Height - 54.4 feet
- (4) Top width - 30 feet
- (5) Side slopes.
 - (a) Downstream-1V on 3H (plans) 1V on 3H to 3.4H (measured)
 - (b) Upstream-1V on 3H (plans) 1V on 3.3H (measured)
- (6) Zoning - Homogeneous impervious fill with downstream shell of random fill.
- (7) Impervious core - Homogeneous
- (8) Cutoff - Located under upstream berm, bottom width = 10 feet, depth varies from 5 feet to 70 feet.
- (9) Grout curtain - None
- (10) Wave protection - Durable rock riprap
- (11) Drains - Blanket and trench drain with perforated corrugated metal pipe.

h. Spillways.

- (1) Principal (uncontrolled)
 - (a) Type. Reinforced concrete drop inlet (riser) with inside dimensions 7 feet wide and 18 feet long (including 8" anti-vortex wall). The reinforced concrete outlet conduit box is 7 feet wide and 6 feet high.
 - (b) Crest (invert) elevation - 969.0 feet (M.S.L.)
Invert conduit entrance elevation - 954.0 feet (M.S.L.)
Invert conduit outlet elevation - 927.0 feet (M.S.L.)
 - (c) Length of conduit - 200 feet
 - (d) Energy Dissipator - St. Anthony Falls (S.A.F.) type

(2) Emergency.

- (a) Type - Vegetated earth, uncontrolled, cut through left abutment. Bottom width and side slopes are not well defined.
- (b) Control Section - Bituminous road running normal to spillway channel centerline, approximately 20 feet wide.
- (c) Crest elevation (minimum top of road) - 973.0 feet (M.S.L.).
- (d) Upstream channel - Centerline channel approach to road, 3.7% grade.
- (e) Downstream channel - Centerline channel exit from road, 3.1% grade.

i. Diversion Channel and Regulating Tunnel. None.

j. Regulating Outlet. Reinforced concrete box with 14 foot entrance and 4' x 4' conduit. Operated by use of slide gate.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Plans for construction of the dam were supplied by the Lake Owner's Association and are included in Appendix C of this report.

Copies of Geologic Reports, Logs of test holes and Soil Engineering report were provided by W. H. Klingner & Associates and are included with this report in Appendix E.

2.2 CONSTRUCTION

No construction data were available. It was reported by Mr. Cawley, Lake Owner's Association's former manager, that the dam was constructed in 1965 by Howard Construction Co., Sedalia, Missouri. Mr. Cawley worked for the contractor at the time of construction. He reported that the dam was constructed according to the plans and specifications except that the core trench was extended to as much as 70 feet in depth in some areas in order to bottom out in blue glacial clay.

2.3 OPERATION

No data were available on spillway operation. It was reported by Mr. Cawley that the emergency spillway has never operated. The highest reservoir level occurred in 1976 or 1977 when the water reached the level of the roadway across the emergency spillway. Mr. Cawley also reported that the reservoir level is lowered about 4 feet during the fall of each year, by operation of the drawdown facility. Prior to lowering the lake level, the Association alerts about 15 landowners downstream so that they can move equipment and/or animals across North Blackbird Creek before the water comes down.

2.4 EVALUATION

- a. Availability. All data was readily available from W. H. Klingner & Associates, the Lake Owners' Association and The Missouri Geological Survey.
- b. Adequacy. The available data, field surveys, and visual observation presented herein are considered adequate to support the conclusions of this report. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

- c. Validity. All data provided appears to be valid. However, many of the design recommendations and conclusions presented in Dr. Fry's Soils Report are not supported by test data or engineering analyses.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

- a. General. A visual inspection of the Lake Thunderhead Dam was made on May 6, 1980. Engineers from Hoskins-Western-Sonderegger, Inc., Lincoln, Nebraska making the inspection were: R. S. Decker, Geotechnical; Gordon Jamison and Garold Ulmer, Hydrology. Mr. Harold Cawley, former Lake Owners' Association manager, accompanied the inspection team part of the time.
- b. Dam.
 - (1) Geology & Soils (abutment & embankment) Soils in the area consist of a thin mantle of loess (CL) overlying thick deposits (up to 100 feet) of glacial till. Materials in the abutments consist of stratified glacial till varying in texture from clay (CL-CH) to clayey sands (SC) to sands and gravels. Materials in the valley section consist of alluvial silts and silty clays to depths of 10 to 20 feet, underlain by glacial silty sands and sands to depths of 50 or 60 feet which is underlain by glacial clays (CL-CH). The cutoff across the valley section extends to depths of 70 feet in some places in order to land in CL-CH materials. The embankment is composed of good CL materials borrowed from both abutment areas.
 - (2) Upstream Slope - The upstream slope looks good. It is well protected with durable limestone and quartzitic sandstone riprap as shown in Photo's 9 and 16. There is some erosion of the abutment at the left end of the riprap that extends 2 or 3 feet above the normal water line as shown in Photo's 7 and 8. A few small trees are growing on the upstream slope. No abnormal deformations or slumps were observed on the slope. Measurements of the exposed portion indicate that the slope is slightly flatter than the 3H on 1V shown on the plans.
 - (3) Crest. The crest is paved with asphaltic concrete as shown in Photo's 13 and 14. No cracks or abnormal deformations were observed on the crest. Measurements along the crest, shown on Plate (C-32), show crest elevations equal to or slightly higher than shown on the plans. This indicates that anticipated foundation consolidation occurred during construction.
 - (4) Downstream Slope - The downstream slope, shown in Photo's 17 and 30, is covered with a dense growth of adapted grasses. The cover and vegetative litter is so dense that it obscures most surficial evidence of rodent activity or minor erosions.

One small rodent hole was observed (Photo No. 21), but others could be present. Measurements of the slope presented on Plate C-31 indicate that it is slightly flatter than the 1V on 3H shown on the plans. There is some indication of wetness in the surface drainage ditch along the upstream edge of the berm as shown in Photo's 20 and 38. However, this wetness on the berm appears to be due to imperfect discharge of surface drainage. There were no indications of erosion, bulges, slips or other deformations on the slope. There were no indications of seepage on the slope or along the toe of the principal embankment. However, there is considerable seepage outcropping around the walls of the sewer lift station located downstream from about station 8+00 and about 100 feet right of the principal spillway outlet structure (S.A.F. basin). Plates C-28, C-29 and C-30 show the location and plans for the lift station which will serve the sewer line passing under the reservoir and dam from the west side of the lake. Photo's Nos. 23, 25, 26, 27, and 28 show the seepage around the lift station. The seepy area is very spongy and semi-bouyant. Seepage discharge from the area, part of which is shown in Photo 26, is estimated at about 1 g.p.m. The sewer line into the lift station is not in use and is capped at its termination in the bottom of the station as shown in Photo No. 39. The floor of the lift station is essentially dry as shown in Photo No. 40.

Mr. William's reports, (Appendix E - Division III) in 1972 and 1978, mentions seepage from a terrace on the left abutment. The location of Mr. William's seeps is not known. He may be referring to seeps in the outlet of the emergency spillway channel adjacent to the sewage lagoons as shown in Photo's 36 and 37. (Most of this seepage appears to come from the north lagoon). The seepage outcrops around the lift station at about elev. 940. If this seepage was discharging through the left abutment, it would appear that the weep holes in the principal spillway outlet at elevation 928 and below, would be flowing since the spillway is located between the left abutment and the lift station. It seems likely that the seepage around the lift station originates from or around the sewer line that passes under the dam.

The outlet for the foundation drainage system was not visible (covered with rocks). Discharge from the drain is ponded in the old channel, downstream from the outlet and it was not possible to estimate the quantity (See Photo No. 22).

There was no indication of seepage in the abutment troughs. However, there is a headcut about 6 feet deep and a gully in the right abutment trough that extends from the berm to the toe of the dam. The concrete surface drain down the right abutment trough extends only from the top of the dam to the berm and not to the valley floor as shown on the plans. The sewer line which traverses the berm is exposed in the gully head cut in the right abutment trough as shown in Photo No. 18. Photo No. 19 shows the end of the concrete lined ditch and the headcut at the upper end of the gully.

c. Appurtenant Structures.

- (1) Principal Spillway. Measurements of the principal spillway indicate that it was constructed according to the plans. The inlet riser structure, trash rack and drawdown valve appear to be in good condition. No spalling or deterioration was observed in the inlet structure. The inlet is shown in Photo's 10, 11 and 12. The outlet structure shown in Photo's 28 and 33, is generally in good condition. Some spalling was noted in the concrete headwall of the spillway conduit as shown in Photo No. 31. Weep holes in the outlet structure are operating as shown in Photo No. 34. A cottonwood tree is growing immediately adjacent to the right wall of the S.A.F. basin. A large rodent hole was observed adjacent to the tree on the right wall of the S.A.F. basin. Photo's 28 & 29 show the tree and rodent hole. Some slumping and seepage was noted in the right bank of the earth channel just downstream from the outlet structure as shown in Photo No. 32. All seepage was clear and no boils were observed. This seepage could be associated with the seepage described around the lift station.
- (2) The emergency spillway is well vegetated with adapted grasses as shown in Photos 3, 4, 5 and 6. (No slumps, erosion or deformations were noted in the spillway). The asphaltic roadway across the dam crosses the spillway and serves as the crest or control section of the spillway. The spillway has never operated. Some seep areas were observed toward the lower end of the outlet channel as shown in Photo No. 36. Discharge was clear and too small to estimate. A considerable amount of seepage was observed along the left side of the outlet channel, adjacent to the north sewage lagoon. Most of this seepage appears to originate from the lagoon(s). Seepage discharge from this area was clear and estimated at 2 to 3 g.p.m. The emergency spillway channel discharges into the exit channel for the principal spillway. Emergency spillway discharges should not encroach upon the dam.

- (3) Drawdown Facilities. The drawdown facility consists of a 4 ft. x 4 ft. conduit outletting into the principal spillway riser. It is controlled by a rising stem slide gate located in the upstream wall of the riser. The facility appears to be in good condition. It is operated every fall of the year to draw down the reservoir level. The drawdown gate valve is shown in Photo No. 12.
- d. Reservoir Area. The reservoir is surrounded by grassland and woods. Some erosion is evident around the shoreline, but it does not appear to be serious.
- e. Downstream Channel. The old stream channel has been partially filled and now serves only as an outlet for the toe drain. The two spillways outlet into an excavated channel which is clear of obstructions and pretty well stabilized with rock riprap as shown in Photo No. 35. This channel enters the old North Blackbird Creek channel about 450 feet downstream from the toe of the dam.

3.2 EVALUATION

This structure appears to be constructed as shown on the plans presented in Appendix C. The structure is generally in good condition. It appears to be structurally stable against shear failure. The source and potential detrimental effects of seepage around the lift station should be investigated. Deterioration of the concrete headwall around the principal spillway outlet could become serious unless it is repaired. The tree and rodent hole observed along the principal spillway outlet structure should be removed and the area restored. The headcut and gully in the right downstream abutment trough could ultimately result in considerable damage to the dam if not repaired. The few small trees should be removed from the upstream face and the erosion at the left end of the riprap should be controlled. Tree removal should be done under the guidance of a professional engineer experienced in the design and construction of dams.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The pool level is primarily controlled by rainfall, infiltration, evaporation, and the capacity of the uncontrolled spillways. However, the drawdown facility is opened during the fall of each year, and the reservoir level is lowered about 4 feet below the principal spillway crest elevation. This provides additional flood protection and reduces potential damage to shore installations during the winter and spring runoff periods. Some 15 landowners and/or operators are notified prior to lowering the lake level so that livestock and equipment can be transferred across the North Blackbird Creek before the creek rises.

4.2 MAINTENANCE OF DAM

At the present time there does not appear to be any regular maintenance on the structure. Mr. Cawley reported that up until about four (4) years ago the downstream slope and emergency spillway was mowed twice a year, trees were removed, and other general maintenance work was performed.

4.3 MAINTENANCE OF OPERATING FACILITIES

The drawdown facility appears to be maintained in satisfactory condition.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no warning system in effect for this dam.

4.5 EVALUATION

A program of regular maintenance needs to be established so that corrective measures can be taken prior to problems becoming major in scope. Most of the deficiencies observed during the field inspection can be attributed to the lack of regular maintenance. The lowering of the lake each fall should be continued.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data. Plans for the dam, as prepared by W. H. Klingner and Associates, Consulting Engineers, Quincy, Illinois, were obtained from the Lake Owners' Association.
- b. Experience Data. The drainage area, reservoir surface area, and elevation-storage data were developed from the USGS Lake Thunderhead and Unionville West, Missouri 7 1/2 minute topographic quadrangle maps and other data prepared by W. H. Klingner & Associates and presented in the Plans shown in Appendix C. The hydraulic computations for the spillway and dam overtopping discharge ratings were based on plan specifications and data collected in the field at the time of the field inspection.
- c. Visual Observations.
 - (1) The principal spillway appears in good condition except for the spalling of the concrete at the headwall at the downstream end of the reinforced concrete box conduit. There is some shoreline erosion at the entrance to the emergency spillway. Otherwise it appears to be in good condition.
 - (2) The emergency spillway, exit channel and the transverse asphalt surfaced road across the spillway channel appear to be in good condition. Spillway releases will not endanger the integrity of the dam.
 - (3) Riprap on the upstream face of the dam is excellent.
- d. Overtopping Potential. The spillways are too small to pass the probable maximum flood without overtopping. The spillways will pass the 1% probability flood as well as 40% of the probable maximum flood without overtopping the dam. Overtopping by the probable maximum flood could be expected to result in erosion of the crest and embankments and subsequent failure of the dam.

The results of the routings through the dam are tabulated in regards to the following conditions:

Frequency	Inflow Discharge c.f.s.	Outflow Discharge c.f.s.	Maximum Pool Elevation	* Maximum Depth Over Dam Feet	Duration Over Top Hours
1/2 PMF	29,200	12,600	978.4	1.0	7
PMF	58,600	45,400	981.6	4.2	13
0.40 PMF	23,500	8,100	977.4	0	--

*Minimum top of dam elevation - 977.4

According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, this dam is classified as having a high hazard rating and an intermediate size. Therefore, the Probable Maximum Flood is the test for the adequacy of the dam and its spillway.

The estimated damage zone is described in Paragraph 1.2d in this report.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observation. This dam appears to be structurally stable from the standpoint of shear strength. The side slopes are slightly flatter than planned, and there are no signs of distress. The source of seepage around the lift station and its effect on stability is not known. If the source of the seepage is related to the placement and/or the integrity of the sewer line under the embankment, this seepage could impair the integrity of the dam through piping and excessive uplift if it is left uncontrolled.
- b. Design and Construction Data. The structure appears to be constructed in accordance with the plans provided by W. H. Klingner & Associates. Shear strength and other analytical parametric data were not available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency. Construction data were not available. However, Mr. Cawley, who worked for the contractor at the time of construction, reported that the contractor followed the construction specifications. The specifications for Class I fill called for 95% of maximum ASTM D698 at moisture contents of optimum \pm 2%.
- c. Operating Records. No operating records were available. Mr. Cawley reported that the reservoir is lowered 4 feet each fall through the drawdown facility. He also reported that the emergency spillway has not operated.
- d. Post Construction Changes. A 6-inch cast iron pipe waterline and a 10-inch clay pipe sewer line were installed along the downstream berm of the embankment in 1968 or 1969. Plans for these lines are shown on Plates C-27, C-28, C-29 and C-30. Installation of these service facilities on the berm do not appear to have any adverse affect upon the stability of the dam. Photo No. 24 shows one of the manholes for the sewer line across the berm.
- e. Seismic Stability. This dam is located in Seismic Zone 1. An earthquake of the magnitude predicted in this area is not expected to cause structural failure of this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Safety. This structure appears to be in relatively good condition. Stability and seepage analyses were not available which is considered a deficiency. The source and effects of seepage discharging around the lift station downstream from about station 8+00 should be determined. Several deficiencies in maintenance were noted and should be corrected. These include: lack of mowing (or other control) of the heavy grass cover on the downstream slope; erosion in the right abutment trough downstream from the berm; concrete deterioration in the outlet headwall of the principal spillway; tree growth and rodent activity along the right wall of the principal spillway outlet; tree growth on the upstream face; and some erosion in the abutment at the termination of the riprap on the left end of the dam and apparent accumulation of surface drainage along the upstream side of the berm. Analyses performed for this report indicate that the spillways will pass the 1% probability flood and about 40% of the PMF without overtopping the dam. These analyses include inflow that would result from breaching the Unionville City Reservoir, located just upstream from this reservoir. Overtopping by the probable maximum flood could be expected to result in erosion of the crest and embankments and subsequent failure of the dam.
- b. Adequacy of Information. The conclusions in this report are based upon performance history and visual observations. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency.
- c. Urgency. A program should be developed as soon as possible to monitor at regular intervals the deficiencies described in this report. The remedial measures recommended in paragraph 7.2b should be accomplished in the near future. The item recommended in paragraph 7.2a should be pursued on a high priority basis.
- d. Necessity for Further Investigations. The additional studies and analyses recommended in paragraph 7.2 should be accomplished by the owner in the near future.
- e. Seismic Stability. This dam is located in Seismic Zone 1. An earthquake of this magnitude is not expected to be hazardous to this dam. It is recommended, however, that the prescribed seismic loading for Seismic Zone 1 be applied in any stability analyses performed for this dam.

7.2 REMEDIAL MEASURES

The following remedial measures and maintenance procedures are recommended. All remedial measures should be performed under the guidance of a registered professional engineer experienced in the design and construction of earth dams.

a. Alternatives.


- (1) The spillway size and/or the height of dam should be increased to pass the probable maximum flood without overtopping the dam.

b. Operation and Maintenance Procedures.

- (1) Stability and seepage analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" should be performed for appropriate loading conditions, including seismic forces. These analyses should be performed by a professional engineer experienced in the design and construction of dams.
- (2) Studies should be conducted to determine the source and effects of seepage discharging around the sewage lift station. This may require installation of piezometers and/or closed circuit television inspection of the sanitary sewer line which passes under the reservoir and the dam. This should be done under the guidance of a professional engineer experienced in the design and construction of dams. Remedial measures may be required.
- (3) The trees growing on the upstream slope, as well as the trees growing along the right wall of the principal spillway, should be removed under the guidance of a professional engineer experienced in the design and construction of dams.
- (4) Additional riprap should be placed on the left end of the dam.
- (5) The headcut and gully erosion in the right abutment trough downstream from the berm should be repaired and measures taken to control future erosion in this area.
- (6) The slumps and/or slides in the right bank of the scour hole downstream from the principal spillway outlet should be repaired and stabilized.
- (7) The concrete deterioration in the headwall of the principal spillway outlet should be repaired.
- (8) The grass on the downstream slope should be mowed and measures taken to control the growth and amount of litter that accumulates. Rodent holes or other surface scars revealed by the mowing should be repaired.

- (9) The rodent hole along the right wall of the principal spill-way outlet should be repaired.
- (10) A program of periodic inspection and maintenance should be initiated in order to protect the integrity of the dam.

APPENDIX A
MAPS



Scale in feet

2000 1000 0 2000 4000

Contour Interval - 10'





VICINITY TOPOGRAPHY

LAKE THUNDERHEAD DAM

PUTNAM COUNTY, MISSOURI

MO 10007


PLATE A-1



VICINITY MAP

ID NO. MO 10007
PUTNAM COUNTY, MISSOURI

Scale in miles




LOCATION MAP

PLATE A-2

QUADRANGLE
SHEET INDEX

- 1 - LAKE THUNDERHEAD
- 2 - UNIONVILLE WEST



LAKE THUNDERHEAD DAM
PUTNAM COUNTY, MISSOURI
MO 10007

DRAINAGE AREA MAP
PLATE A-3

APPENDIX B
PHOTOGRAPHS



LAKE THUNDERHEAD DAM
PUTNAM COUNTY, MISSOURI
MO 10007

PHOTO INDEX

PLATE B-1



PHOTO NO. 2 - OVERVIEW OF DAM FROM UPSTREAM ON LEFT
ABUTMENT




PHOTO NO. 3 - EMERGENCY SPILLWAY CREST TAKEN FROM LEFT END



PHOTO NO. 4 - VIEW UPSTREAM IN EMERGENCY SPILLWAY




PHOTO NO. 5 - VIEW DOWNSTREAM IN EMERGENCY SPILLWAY




PHOTO NO. 6 - EMERGENCY SPILLWAY CHANNEL AND SEWAGE
LAGOONS FROM LEFT END OF DAM



PHOTO NO. 7 - EROSION ON UPSTREAM SLOPE NEAR BEND IN
CENTERLINE ON LEFT END



PHOTO NO. 8 - UPSTREAM FACE FROM LEFT END



PHOTO NO. 9 - UPSTREAM FACE AND CREST TAKEN FROM LEFT OF
CURVE IN CENTERLINE LOOKING SOUTH




PHOTO NO. 10 - VIEW UPSTREAM WITH PRINCIPAL SPILLWAY
INLET IN FOREGROUND




PHOTO NO. 11 - DOWNSTREAM BAY OF PRINCIPAL SPILLWAY INLET




PHOTO NO. 12 - UPSTREAM BAY OF PRINCIPAL SPILLWAY INLET
SHOWING SLIDE GATE




PHOTO NO. 13 - CREST FROM CURVE TOWARD LEFT END LOOKING
SOUTH




PHOTO NO. 14 - CREST FROM CURVE IN DAM LOOKING NORTH




PHOTO NO. 15 - VIEW DOWNSTREAM SHOWING OLD CHANNEL AND
HIGHWAY BRIDGE IN BACKGROUND




PHOTO NO. 16 - UPSTREAM FACE FROM RIGHT END



PHOTO NO. 17 - DOWNSTREAM FACE FROM RIGHT END




PHOTO NO. 18 - GULLY ERODED IN RIGHT ABUTMENT TROUGH
DOWNSTREAM FROM BERM



PHOTO NO. 19 - CONCRETE LINED DITCH IN RIGHT ABUTMENT
TROUGH. GULLY BEGINS AT END OF LINED DITCH



PHOTO NO. 20 - CATTAILS AND WILLOW TREE (BACKGROUND)
GROWING IN DITCH IN BERM




PHOTO NO. 21 - SMALL RODENT HOLE IN DOWNSTREAM SLOPE



PHOTO NO. 22 - VIEW DOWNSTREAM IN OLD CHANNEL. WATER IS
THE DISCHARGE FROM TOE DRAIN



PHOTO NO. 23 - SEEP AREA AROUND AND TO LEFT OF SEWAGE
LIFT STATION



PHOTO NO. 24 - MANHOLE ON SANITARY SEWER CROSSING THE BERM




PHOTO NO. 25 - SEEP AREA AROUND LIFT STATION. VIEW LOOKING EAST



PHOTO NO. 26 - SEEPAGE
DISCHARGE FROM LIFT
STATION AREA. LIFT
STATION IN BACKGROUND



PHOTO NO. 27 - SEEPAGE AROUND UPSTREAM SIDE OF LIFT STATION



PHOTO NO. 28 - PRINCIPAL SPILLWAY OUTLET WITH LIFT STATION AND
SEWER LINE TO RIGHT



PHOTO NO. 29 - TREE AND RODENT HOLE AT RIGHT SIDE OF SPILLWAY
CHUTE



PHOTO NO. 30 - DOWNSTREAM SLOPE FROM EMERGENCY SPILLWAY
CHANNEL. LIFT STATION AND SEWER LINE ON LEFT



PHOTO NO. 31 - SPALLING OF CONCRETE IN PRINCIPAL SPILLWAY
OUTLET



PHOTO NO. 32 - SCOUR AND SLUMPS IN RIGHT SIDE OF PRINCIPAL
SPILLWAY SCOUR HOLE. PIPE IS DRAIN FROM
LIFT STATION



PHOTO NO. 33 - OUTLET OF PRINCIPAL SPILLWAY



PHOTO NO. 34 - WEEP HOLES IN LEFT WALL OF PRINCIPAL SPILLWAY
OUTLET CHANNEL



PHOTO NO. 35 - LOWER END OF OUTLET CHANNEL FOR PRINCIPAL
SPILLWAY




PHOTO NO. 36 - SEEP IN OUTLET CHANNEL OF EMERGENCY SPILLWAY.
CATTAILS GROWING ALONG BASE OF SEWAGE LAGOONS



PHOTO NO. 37 - SEEPAGE FROM SEWAGE LAGOONS



PHOTO NO. 38 - SURFACE
DRAIN DITCH ALONG BERM



PHOTO NO. 39 - CONNECTION OF SEWER LINE UNDER DAM WITH
LIFT STATION



PHOTO NO. 40 - OUTLET FOR DRAIN IN BOTTOM OF LIFT STATION.
DRAIN PIPE OUTLET SHOWN IN PHOTO NO. 32




PHOTO NO. 41 - FARMSTEAD ABOUT 1 MILE DOWNSTREAM ON LEFT SIDE
OF NORTH BLACKBIRD CREEK. PHOTO TAKEN LOOKING
NORTH FROM CREEK.



PHOTO NO. 42 - FARMSTEAD SHOWN IN PHOTO NO. 41. PHOTO
TAKEN LOOKING SOUTH TOWARD FLOOD PLAIN



PHOTO NO. 43 - FARMSTEAD ON RIGHT SIDE OF NORTH BLACKBIRD
CREEK APPROXIMATELY 1 MILE DOWNSTREAM.

APPENDIX C
PROJECT PLATES

PUTNAM COUNTY LAKE

UNIONVILLE, MD

RECREATIONAL

DIRECTORS

LLOYD NORRIS	PRESIDENT
HENRY FELDMAN	VICE PRESIDENT
W. E. ROSS	TREASURER
DON SHUEY	SECRETARY
FLOYD ANDERS	MEMBER
PAUL CLARK	MEMBER
ELBERT STAGGS	MEMBER
GLEO WEBBER	MEMBER
H. WILLARD ARNAMAN	MEMBER

1000
P. 1000

LAKE ASSOCIATION, INC.

LE, MISSOURI

TIONAL LAKE

INDEX OF SHEETS


<u>SHEET NO.</u>	<u>DESCRIPTION</u>
1	COVER SHEET
2	HYDRAULIC DESIGN DATA
3-4	SITE PLAN-CLEARING
5	LOG OF TEST BORINGS
6	GENERAL PLAN OF DAM SITE
7	TOE DRAIN - PLAN AND PROFILE
8-10	DAM CROSS SECTIONS
11	ROAD THROUGH BORROW AREA - PLAN AND PROFILE
12-15	ROAD THROUGH BORROW AREA - CROSS SECTIONS
16	EMERGENCY SPILLWAY - CROSS SECTIONS
17	PLAN OF SPILLWAY DITCHES
18	SPILLWAY DITCHES - CROSS SECTIONS
19	MISCELLANEOUS DETAILS
20	MECHANICAL SPILLWAY AND OUTLET WORKS
21-23	OUTLET STRUCTURE
24-25	OUTLET CONDUIT
26-27	INLET STRUCTURE
28	INLET CONDUIT

PROPOSED
DAM

UNIONVILLE

THIS PAGE IS BEST QUALITY PRINT
FROM COPY FURNISHED TO SON

PREPARED BY
W. H. KLINGNER
CONSULTING ENGINEER



NAME
SURVEY
NO.

NAME
SURVEY
NO.

FEET ABOVE SPILLWAY
ACRES
FEET ABOVE SPILLWAY
ACRES

TOP OF SPILLWAY

ELEVATION

MAXIMUM FLOW 1000 CFS

MAXIMUM STAGE 3700 FEET

CURVE II - ACRES FEET

CURVE II - CFS

CURVE I - CFS

DERIVATION OF CURVES

GRAPH FROM UNIT HYDROGRAPH METHOD USING TOTAL RUNOFF EQUAL RAINFALL

BASE FROM PLANIMETER OF CONTOURS WITHIN LAKE AREA



CHARGE FROM 0.34 IN/H BUT NOT TO EXCEED 12.5 IN/H OR PLUS EMERGENCY SPILLWAY ABOVE ELEVATION 2150.0 ± 2.0 (100+200) HYDRAULIC SPILLWAY FOR EACH TIME INTERVAL IS A GRAPHICAL PLOT OF THE BETWEEN THE INFLOW AND OUTFLOW FOR THAT TIME

HYDROGRAPH, IN CUBIC FEET PER SECOND IS A GRAPHICAL PLOT OF THE PLOT ON CURVE III FOR EACH STAGE OF STORAGE ABOVE THE SPILLWAY.


CURVES SEE U.S. DEPARTMENT OF AGRICULTURE, SOIL CONSERVATION ENGINEERING HANDBOOK DESIGN DATA #2



POTOMAC COUNTY LAKE ASSOCIATION
MONTICELLO, MISSOURI
HYDRAULIC DESIGN DATA

RAINFALL
FROM ILLINOIS STATE WATER SURVEY



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC





DESIGNED BY
WESTERN AIR MAPS, INC
LENEXA, KANSAS

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

PUTNAM COUNTY LAKE ASSOCIATION UNIONVILLE, MISSOURI	
SITE PLAN - CLEARING SECTION II	
W. H. KLINGNER & ASSOCIATES, CONSULTING ENGINEERS 617 BROADWAY QUINCY, ILLINOIS	
SHEET NO. 4 OF 8 SHEETS	

PLATE C-3

STATE ROUTE 5

CREEK

EMERGENCY DAM

ORIGINAL SURVEY

BLANKED

BLANKED

BLANKED

N

SCALE 1:200

ROUTE 5

CENTER NE 1/4 SEC 5

SECTION 15

PROJECT FOR
EAST OF LEBAN, MISSOURI
PART OF PROJECT

THIS PROJECT IS QUANTITY PRACTICABLE
FROM COPY FURNISHED TO DDC

SEE SPECIFICATIONS FOR SOIL PROFILE
A COMPLETE LOG OF SOIL BORING IS AVAILABLE
AT THE UNIONVILLE CITY HALL OR AT THE OFFICE
OF W. H. KLINGNER AND ASSOCIATES, CONSULTING
ENGINEERS, 111 BROADWAY, QUINCY, ILLINOIS

SOIL BORING LOCATION MAP			
PUTNAM COUNTY LAKE ASSOCIATION, INC.			
UNIONVILLE, MISSOURI			
W. H. KLINGNER AND ASSOCIATES, ENGINEERS			
617 BROADWAY QUINCY, ILLINOIS			
DATE	DRAWN	CHECKED	SHEET NO. 8
OCT 1964	A. B. H.	EC	OF 28 SHEETS

PLATE C-4

CURVE DATA

P1 STA 1197
 Δ = 21°00'
 D = 10°36'
 T = 100.9
 R = 5405
 L = 198
 E = 521

CURVE DATA

P1 STA 1113
 Δ = 35°30'
 D = 12°15'
 T = 48.75
 R = 467.76
 L = 283.80
 E = 23.38

B.M. SPILLWAY DRAIN
 ELEV 545.45

PAVED VALLEY
 SEE DETAIL SHEET 15

EMERGENCY SPILLWAY
 SEE SHEET NO 17

SPILLWAY ELEVATION 973.00

4" COMPACTED CRUSHED
 STONE SEE SHEET NO 8

SEE SHEET NO 17
 SEE SHEET NO 18

SEE SHEET NO 18

BENCH MARK CHSELED SQUARE ON
 CONC. BRIDGE PILEH AT 11.400
 ELEVATION 939.00

FILL WITH
 WASTE MATERIAL

TOE DRAIN
 SEE SHEET NO 7

PAVED AREA
 SEE DETAIL SHEET NO 10

ELEVATION 940.00
 SEE SHEET NO 20

TOE OF FILL

TO BERM
 ELEV. 932.00
 AT STA. 11.400

TOE OF DRAINAGE FILL

0.50%

DOWNSTREAM BERM
 SEE DETAIL SHEET NO 2

0.50%

RIPRAP

TOE OF TRENCH

TO BERM
 ELEVATION 932.00
 AT STA. 11.400

TOE OF SURVEY LINE

TOE OF FILL

THIS IS THE MOST PRACTICABLE
 AREA FOR THE DAM TO LOG



PUTNAM COUNTY LAKE ASSOCIATION
 UNIONVILLE, MISSOURI

GENERAL PLAN OF DAM SITE

W. H. KLINGNER & ASSOCIATES, CONSULTING ENGINEERS
 617 BROADWAY QUINCY, ILLINOIS

DRAWN BY A. B. HARMAN CHECKED BY E. G. HUNTER DATE MAY 14, 1965

SHEET NO 6 OF 24 SHEETS

PLATE C-5






DIAGRAM FOR DAMBER ON WEST OF DAM



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DMC




12

PLATE C-6

DATE	BY	CHECKED	APPROVED

DATE	BY	CHECKED	APPROVED









Diagram showing a cross-section of a dam structure. The dam is labeled "DAM" and "COMPACTED, CRUSHED STONE". The dimensions are as follows:

- Upstream face width: 30.00'
- Crest width: 15.00'
- Downstream face width: 10.00'
- Foundation width: 10.00'
- Height: 100.00'

~~DETAIL - TOP OF DAM~~

NOTE SECTIONS AS SHOWN INCLUDE 5% FOR
SETTLEMENT AFTER CONSTRUCTION.

**THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG**



POTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI
CROSS SECTION PERPENDICULAR
TO L. DAM STA. 9+50 TO STA. 12+00

CORNER ELEVATION 1262
CLASS II FILL 9362
CLASS II FILL 984

CORN EXCAVATION 835
CLASS II FILL 10334
CLASS II FILL 984



CORNER ELEVATION 1224
CLASS I FILL 9272
CLASS II FILL 808

THIS PAGE IS BEST QUALITY AVAILABLE
FROM COPY FURNISHED TO DDC

SHEET NO. 13 OF 28 SHEETS
PLATE C-8

FINAL	DATE	BY
SURVEY		
NOTEBOOK		
NO.		

DATE	BY




POTNAM COUNTY LAKE ASSOCIATION
 UNIONVILLE, MISSOURI
 CROSS SECTIONS PERPENDICULAR
 TO THE DAM STA 12+50 TO STA 16+50

CORE EXCAVATION 728
 CLASS I FILL 7600
 CLASS II FILL 824

CORE EXCAVATION 2476
 CLASS I FILL 9962
 CLASS II FILL 800

CORE EXCAVATION 1884
 CLASS I FILL 10048
 CLASS II FILL 762

THIS PAGE IS BEST VIEWED IN LANDSCAPE
 FROM COPY FURNISHED TO DDG



1. TOTAL
 2. TOTAL
 3. TOTAL
 4. TOTAL
 5. TOTAL
 6. TOTAL
 7. TOTAL
 8. TOTAL
 9. TOTAL
 10. TOTAL
 11. TOTAL
 12. TOTAL
 13. TOTAL
 14. TOTAL
 15. TOTAL
 16. TOTAL
 17. TOTAL
 18. TOTAL
 19. TOTAL
 20. TOTAL
 21. TOTAL
 22. TOTAL
 23. TOTAL
 24. TOTAL
 25. TOTAL
 26. TOTAL
 27. TOTAL
 28. TOTAL
 29. TOTAL
 30. TOTAL
 31. TOTAL
 32. TOTAL
 33. TOTAL
 34. TOTAL
 35. TOTAL
 36. TOTAL
 37. TOTAL
 38. TOTAL
 39. TOTAL
 40. TOTAL
 41. TOTAL
 42. TOTAL
 43. TOTAL
 44. TOTAL
 45. TOTAL
 46. TOTAL
 47. TOTAL
 48. TOTAL
 49. TOTAL
 50. TOTAL
 51. TOTAL
 52. TOTAL
 53. TOTAL
 54. TOTAL
 55. TOTAL
 56. TOTAL
 57. TOTAL
 58. TOTAL
 59. TOTAL
 60. TOTAL
 61. TOTAL
 62. TOTAL
 63. TOTAL
 64. TOTAL
 65. TOTAL
 66. TOTAL
 67. TOTAL
 68. TOTAL
 69. TOTAL
 70. TOTAL
 71. TOTAL
 72. TOTAL
 73. TOTAL
 74. TOTAL
 75. TOTAL
 76. TOTAL
 77. TOTAL
 78. TOTAL
 79. TOTAL
 80. TOTAL
 81. TOTAL
 82. TOTAL
 83. TOTAL
 84. TOTAL
 85. TOTAL
 86. TOTAL
 87. TOTAL
 88. TOTAL
 89. TOTAL
 90. TOTAL
 91. TOTAL
 92. TOTAL
 93. TOTAL
 94. TOTAL
 95. TOTAL
 96. TOTAL
 97. TOTAL
 98. TOTAL
 99. TOTAL
 100. TOTAL

EARTH
 SHOWN TOP
 CONT. TO BE INC.

1. TOTAL
 2. TOTAL
 3. TOTAL
 4. TOTAL
 5. TOTAL
 6. TOTAL
 7. TOTAL
 8. TOTAL
 9. TOTAL
 10. TOTAL
 11. TOTAL
 12. TOTAL
 13. TOTAL
 14. TOTAL
 15. TOTAL
 16. TOTAL
 17. TOTAL
 18. TOTAL
 19. TOTAL
 20. TOTAL
 21. TOTAL
 22. TOTAL
 23. TOTAL
 24. TOTAL
 25. TOTAL
 26. TOTAL
 27. TOTAL
 28. TOTAL
 29. TOTAL
 30. TOTAL
 31. TOTAL
 32. TOTAL
 33. TOTAL
 34. TOTAL
 35. TOTAL
 36. TOTAL
 37. TOTAL
 38. TOTAL
 39. TOTAL
 40. TOTAL
 41. TOTAL
 42. TOTAL
 43. TOTAL
 44. TOTAL
 45. TOTAL
 46. TOTAL
 47. TOTAL
 48. TOTAL
 49. TOTAL
 50. TOTAL
 51. TOTAL
 52. TOTAL
 53. TOTAL
 54. TOTAL
 55. TOTAL
 56. TOTAL
 57. TOTAL
 58. TOTAL
 59. TOTAL
 60. TOTAL
 61. TOTAL
 62. TOTAL
 63. TOTAL
 64. TOTAL
 65. TOTAL
 66. TOTAL
 67. TOTAL
 68. TOTAL
 69. TOTAL
 70. TOTAL
 71. TOTAL
 72. TOTAL
 73. TOTAL
 74. TOTAL
 75. TOTAL
 76. TOTAL
 77. TOTAL
 78. TOTAL
 79. TOTAL
 80. TOTAL
 81. TOTAL
 82. TOTAL
 83. TOTAL
 84. TOTAL
 85. TOTAL
 86. TOTAL
 87. TOTAL
 88. TOTAL
 89. TOTAL
 90. TOTAL
 91. TOTAL
 92. TOTAL
 93. TOTAL
 94. TOTAL
 95. TOTAL
 96. TOTAL
 97. TOTAL
 98. TOTAL
 99. TOTAL
 100. TOTAL






PLATE 1 - PLAN PROFILE
 THE PRESENT ROAD

HANCOCK COUNTY LAKE ALLOCATION
 CONSTRUCTION
 MAP OF THE LAKE ALLOCATION AREA
 PLAN AND PROFILE


EARTH FILL
 5.00% TOP 24.00 FT
 COST TO BE INCLUDED IN BIDDING




THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDG



PUTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI
CROSS SECTIONS
ROAD THROUGH BORROW AREA



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



PUTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI
CROSS SECTIONS
ROAD THROUGH BORROW AREA

1012.16

3827

F-0

1040

1020

MATCH LINE

340

320

380

410

420

410

400

480

510

520

540

540

580

600

012 17

3715

F-0

1040

1020

MATCH LINE

340

320

380

410

420

410

400

480

510

520

540

540

580

600

1009.26

60' 18" M.P. @ 1.00% E 1009.86

38410

F-0

1040

1020

MATCH LINE

340

320

380

410

420

410

400

480

510

520

540

540

580

600

1009.81

38413

F-0

1040

1020

MATCH LINE

340

320

380

410

420

410

400

480

510

520


540

540


580

600


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



POTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI
CROSS SECTIONS
ROAD THROUGH BORROW AREA



THIS PAGE IS OF QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



24.72'

C-51

C-96

C-60

C-100

C-400

C-600

2' FLAT BOTTOM DITCH
2:1 SIDE SLOPES

1.00%

C-874


C-625

2' FLAT BOTTOM DITCH
WITH 2:1 SIDE SLOPES

C-1218


PLATE 1 OF 15 SECTION 11.00 00.00
AT STATION 11+00.00

PUTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI
CROSS SECTIONS
ROAD THROUGH BORROW AREA



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC


2' FLAT BOTTOM DITCH
WITH 2:1 SIDE SLOPES



附：1. 1985年12月25日，中共中央、国务院、中央军委、中国人民解放军总政治部，授予李向群“模范共青团员”称号。

PUTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI
EMERGENCY SPILLWAY
CROSS SECTIONS

HOUSE



THIS PAGE IS BEST QUALITY FRACITABLE
FROM COPY FURNISHED TO DDG

11-100000

20 FT. FLAT BOTTOM DITCH
WITH 5:1 SIDE SLOPES

EMERGENCY SPILLWAY DITCH

9 M SPIKE IN 12" OAK
ELEVATION 949.45

PAVED VALLEY
SEE DETAIL SHEET 015

MECHANICAL SPILLWAY

RT. 2+34.92

PC 2+28

INLET STRUCTURE

PT. 2+17.78


PT. 2+17.78

CURVE DATA

P.I. STA. 2+00
 $\Delta = 40^{\circ}00'$
 $D = 22^{\circ}05'$
 $R = 259.56'$
 $T = 150.03'$
 $L = 272.11'$
 $E = 40.20'$

CURVE DATA

P.I. STA. 6+69.11
 $\Delta = 54^{\circ}00'$
 $D = 19^{\circ}25'$
 $R = 294.55'$
 $T = 149.95'$
 $L = 277.40'$
 $E = 36.01'$



PUTNAM COUNTY LAKE ASSOCIATION
 UNIONVILLE, MISSOURI

PLAN OF SPILLWAY DITCHES


W. H. KLINGNER & ASSOCIATES, CONSULTING ENGINEERS
 517 BRADSHAW QUINCY, ILLINOIS

DRAWN
 E. H. S.


CHECKED
 E. H. S.

SURVEY	
DATE	BY
TIME	BY
LOCATION	BY
REMARKS	BY


SURVEY	
DATE	BY
TIME	BY
LOCATION	BY
REMARKS	BY



EMERGENCY SPILLWAY DITCH





PUTNAM COUNTY LAKE
UNIONVILLE, MISSOURI
CROSS SECTIONS FOR
SPILLWAY DITCHES




THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDO

12

END SECTION



CONNECTION OF RAIL TO POST



FRONT ELEVATION

DETAIL OF STEEL POST




PLAN FOR END OF GUARD RAIL





NOTES:

1. THE RAIL ELEMENTS, STEEL POSTS AND ALL OTHER MATERIALS AND ACCESSORIES SHALL BE GALVANIZED.
2. THE COST OF END SECTIONS SHALL BE ADDED TO THE UNIT PRICE BID PER LINEAL FOOT FOR STEEL PLATE BEAM GUARD RAIL.

STEEL PLATE BEAM GUARD RAIL BASE PLAN



DETAIL OF RAIL



AD-A105 254

HOSKINS-WESTERN-SONDEREGGER INC LINCOLN NE
NATIONAL DAM SAFETY PROGRAM. LAKE THUNDERHEAD DAM (NO 10007), G--ETC(U)
MAY 80 R S DECKER, G JAMISON, G ULMER
DACW43-80-C-0071


F/G 13/13



UNCLASSIFIED

NL

2 of 3

AD-A
105 254





ALL DIMENSIONS ARE IN FEET
 SMALL DIMENSIONS ARE IN INCHES
 1/4" = 1' SCALE
 1/4" = 1' SCALE
 1/4" = 1' SCALE
 1/4" = 1' SCALE

ALL WATER CONDUITS
 SHALL BE CONSTRUCTED
 TO THE FOLLOWING
 SPECIFICATIONS
 ALL EXPOSED SURFACES

N

PAVED VALLEY
SEE DETAIL SHEET 1A

PLAN
SCALE 1"=100'

EMERGENCY OVERFLOW ELEV. 313.0

6" CMP
FOR DRAIN

10' WIDE
BERM

EXISTING GROUND

ELEV. 313.0

SLOPE 3.5%

ELEV. 314.0

ELEV. 317.0

ELEV. 317.0



ELEV. 320.0

OUTLET DRAINAGE DETAIL
SEE DETAIL SHEET 2A & 3A

OUTLET DRAINAGE DETAIL
SEE DETAIL SHEET 2A & 3A


THIS PAGE IS BEST QUALITY PRACTICAL
FROM COPY FURNISHED TO DDC

PUTNAM COUNTY LAKE ASSOCIATION UNIONVILLE, MISSOURI		
MECHANICAL SPILLWAY AND OUTLET WORKS		
W. H. KLINGNER & ASSOCIATES, CONSULTING ENGINEERS 617 BROADWAY GUNCY, ILLINOIS		
DRAWN A. K. Stockton	CHECKED	DATE MARCH, 1955
SHEET NO. 20 OF 25 SHEETS		



NO 18)
ENDING.

EXISTING GROUND
AT FACE OF OUTLET
STRUCTURE



END VIEW

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

PUTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI


OUTLET STRUCTURE

W. H. KLINGNER & ASSOCIATES, CONSULTING ENGINEERS
617 BROADWAY QUINCY, ILLINOIS

DRAWN A. K. ST. 6-10	CHECKED	DATE MARCH, 1966
-------------------------	---------	---------------------

SHEET NO 21 OF 28 SHEETS

PLATE C-20



TYPICAL SECTION OF WALL AND SLAB
SCALE 1/4" = 1'-0"

1. 1/2" BARS @ 12" CTRS.

2. 1/2" BARS @ 12" CTRS.


3. 1/2" BARS @ 12" CTRS.

4. 1/2" BARS @ 12" CTRS.


5. 1/2" BARS @ 12" CTRS.

6. 1/2" BARS @ 12" CTRS.


CONSTRUCTION JOINT




TYPICAL



TYPICAL CONSTRUCTION JOINT
SCALE 1/4" = 1'-0"



REINFORCEMENT BAR DETAIL



TYPICAL SECTION - STA. 0+00 TO STA. 2+00

BILL OF MATERIALS				
CONDUIT - STA. 0+00 TO STA. 2+00				
MARK	NO. REQ'D	LENGTH	SIZE	NOTES
A1	336	6' 2"	#8	STRAIGHT
A2	52	5' 2"	#4	STRAIGHT
A3	348	5' 0"	#7	STRAIGHT
B1	314	4' 6"	#5	SEE DETAIL
B2	328	5' 3"	#5	SEE DETAIL
B3	324	4' 0"	#5	SEE DETAIL
B4	324	5' 4"	#5	SEE DETAIL
B5	2	5' 0"	#5	SEE DETAIL
B6	2	5' 3"	#5	SEE DETAIL
B7	2	5' 3"	#5	SEE DETAIL
B8	2	5' 3"	#5	SEE DETAIL
B9	2	6' 4"	#5	SEE DETAIL
B10	2	6' 5"	#5	SEE DETAIL
B11	2	7' 3"	#5	SEE DETAIL
H1	—	VAR. LG.	#4	SEE DETAIL - 2635 L.F. REQ'D.
H2	—	ARMED	#4	STRAIGHT - 2475 L.F. REQ'D.
H3	—	ARMED	#5	STRAIGHT - 2475 L.F. REQ'D.
H4	—	ARMED	#7	STRAIGHT - 340 L.F. REQ'D.
H5	—	ARMED	#5	STRAIGHT - 450 L.F. REQ'D.
H6	4	5' 3"	#5	STRAIGHT
H7	4	5' 3"	#5	STRAIGHT
H8	4	4' 9"	#5	STRAIGHT
V1	204	7' 3"	#4	STRAIGHT
V2	174	5' 3"	#4	STRAIGHT

REINFORCEMENT - SEE DETAIL

CONCRETE - 35,391 LBS.


BAR RATE - 18.4 CUBIC YDS.

QUANTITIES SHOWN FOR MATERIALS. MARKS DO NOT INCLUDE LABOR AT CONSTRUCTION SITES.

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC




PUTNAM COUNTY LAKE ASSOCIATION UNIONVILLE, MISSOURI		
OUTLET CONDUIT		
W. H. KLINGNER & ASSOCIATES, CONSULTING ENGINEERS 617 BROADWAY QUINCY, ILLINOIS		
DRAWN A. K. STANTON	CHECKED	DATE MARCH, 1968
SHEET NO. 24 OF 28 SHEETS		

PLATE C-31



ELEVATION

AS PER DETAIL




COMBINATION VIEW
JUNCTION OF CONDUIT & INLET

QUANTITIES SHOWN ARE FOR THE ENTIRE PROJECT

MARK	NO.	QTY	LENGTH	UNIT	DESCRIPTION
HI	54	1	10'-0"	EA	STAKE
VI	20	1	10'-0"	EA	STAKE
VL	20	1	10'-0"	EA	STAKE
BI	14	1	10'-0"	EA	STAKE
BL	14	1	10'-0"	EA	STAKE

NEW ORIENTED STEEL
CONCRETE




PLAN

SECTION A-A
CONCRETE WALL
THICKNESS 12 IN.

SECTION B-B
CONCRETE WALL
THICKNESS 12 IN.

SECTION C-C
CONCRETE WALL
THICKNESS 12 IN.

SECTION D-D
CONCRETE WALL
THICKNESS 12 IN.



SECTION

SECTION DETAIL
OUTLET INLET STRUCTURE

THIS PAGE IS BEST QUALITY PRACTICALLY
FROM COPY FURNISHED TO DDG



BENT ENDS OF H BARS
TOTAL OF 4 BARS REQUIRE BENDING.
BENT PORTION MAY BE A SEPARATE
BAR BY PROVIDING 40 BAR DIAMETERS
OF LAP WITH H BARS

4 BARS
4 BARS
4 BARS

4 BARS

PUTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI


OUTLET CONDUIT

W H KLINGNER & ASSOCIATES, CONSULTING ENGINEERS
617 BROADWAY QUINCY, ILLINOIS

DRAWN A. H. STICKLER CHECKED DATE MARCH, 1965

SHEET NO 25 OF 28 SHEETS

PLATE C-22



ISOMETRIC VIEW
OUTLET CONDUIT & INLET STRUCTURE

PORT 240 SERIES HYD CAST IRON
 MOUNTED SLURGE GATE WITH
 BOTTOM CLOSURE, SELF CONTAINED,
 PRESSURE USING 5 OR
 10 WOODS, TYPE F THIMBLE
 SET FRAME, STOP BAR, 2 DIA STEEL
 AND 8-8800A DEANK OPERATED PORT
 OR APPROVED EQUAL

WELDED ANGLE RING GUARD
 SEE DETAIL SHEET NO 27

PORT SUPPORT
 SEE DETAIL SHEET 27

1/2 DIA LG CAST IRON WOODS W/ 1/2 DIA
 AND 1 DIA GALV BOLTS ON EACH END

STEEL CHANNEL 2 DIA

AS BARS 8-8800A


1/2 DIA BARS

CONSTRUCTION JOINT (4 DIA)

CONSTRUCTION
 JOINT

INLET CONDUIT
 SEE DETAIL SHEET 27


8-8800A BARS 8-8800A
 1/2 DIA STEEL




4-1/2 DIA BARS 8-8800A

1/2 DIA BARS 8-8800A

1/2 DIA BARS 8-8800A



1/2 DIA BARS 8-8800A
 1/2 DIA BARS 8-8800A
 1/2 DIA BARS 8-8800A
 1/2 DIA BARS 8-8800A



SECTION B-B

MARK	NO	FREQ	LENGTH	SIZE	NOTES
A	13		7'-2"	#6	SEE DETAILS
A1	4		11'-0"	#5	
A2	1		3'-2"	#4	
A4	1		7'-0"	#4	STRAIGHT
A5	2		11'-0"	#4	
A6	4		4'-6"	#4	
A7	8		3'-0"	#4	
H1	31		15'-6"	#5	
H2	8		10'-0"	#5	
H3	20		15'-0"	#4	
H4	8		11'-2"	#4	
H5	8		4'-3"	#5	SEE DETAIL
H6	6		4'-3"	#5	
V1	43		13'-6"	#5	STRAIGHT
V2	44		14'-2"	#4	
V3	40		8'-3"	#4	
V4	1		4'-3"	#5	
V5	13		4'-3"	#4	
V6	5		10'-0"	#5	
V7	4		10'-0"	#4	
V8	4		3'-0"	#4	
V9	4		2'-0"	#4	
V10	4		1'-0"	#4	
V11	4		1'-0"	#4	
V12	4		1'-0"	#4	

REINFORCEMENT STEEL
CONCRETE

1656 LBS
457 CU YDS

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG



FROM JEFFERSON COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI

INLET STRUCTURE





W. H. KLINGNER & ASSOCIATES, CONSULTING ENGINEERS
617 BROADWAY QUINCY, ILLINOIS

DRAWN A. K. Stokker	CHECKED	DATE MARCH, 1965
------------------------	---------	---------------------

SHEET NO. 20 OF 25 SHEETS



SECTION A-A
STAIRS



NOTES

THE TRASH PICKER REQUIRED, ONE AS SHOWN AND ONE WITHOUT TO BE USED IN PLACE AND IN PLACE.

THE TRASH PICKER SHALL BE FASTENED WITH ONE LOT OF RUST PROOFED NUTS AND WASHERS OF STANDARD SIZE. THE TRASH PICKER SHALL BE FASTENED TO THE TRASH PICKER WITH ONE LOT OF RUST PROOFED NUTS AND WASHERS OF STANDARD SIZE.

THE TRASH PICKER SHALL BE FASTENED TO THE TRASH PICKER WITH ONE LOT OF RUST PROOFED NUTS AND WASHERS OF STANDARD SIZE.

THE TRASH PICKER SHALL BE FASTENED TO THE TRASH PICKER WITH ONE LOT OF RUST PROOFED NUTS AND WASHERS OF STANDARD SIZE.

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG



PUTNAM COUNTY LAKE ASSOCIATION
UNIONVILLE, MISSOURI

INLET STRUCTURE






W.H. KLINGER & ASSOCIATES, CONSULTING ENGINEERS
617 BROADWAY QUINCY, ILLINOIS

DRAWN BY: [Signature] CHECKED BY: [Signature] DATE: MARCH, 1960

FIELD TO MATCHING PART
WHERE NUTS OR TRASH PICKER



BAR NO	REQD LENGTH	SIZE	NOTES
A1	35	2 0	
A2	5	1 4	
A3	7	1 4	
A4	1	2 0	
A5	4	2 0	
A6	2	2 0	
A7	2	2 0	
A8	2	2 0	
A9	2	2 0	
A10	2	2 0	
A11	2	2 0	
A12	2	2 0	
A13	2	2 0	
A14	2	2 0	
A15	2	2 0	
A16	2	2 0	
A17	2	2 0	
A18	2	2 0	
A19	2	2 0	
A20	2	2 0	
A21	2	2 0	
A22	2	2 0	
A23	2	2 0	
A24	2	2 0	
A25	2	2 0	
A26	2	2 0	
A27	2	2 0	
A28	2	2 0	
A29	2	2 0	
A30	2	2 0	
A31	2	2 0	
A32	2	2 0	
A33	2	2 0	
A34	2	2 0	
A35	2	2 0	
A36	2	2 0	
A37	2	2 0	
A38	2	2 0	
A39	2	2 0	
A40	2	2 0	
A41	2	2 0	
A42	2	2 0	
A43	2	2 0	
A44	2	2 0	
A45	2	2 0	
A46	2	2 0	
A47	2	2 0	
A48	2	2 0	
A49	2	2 0	
A50	2	2 0	
A51	2	2 0	
A52	2	2 0	
A53	2	2 0	
A54	2	2 0	
A55	2	2 0	
A56	2	2 0	
A57	2	2 0	
A58	2	2 0	
A59	2	2 0	
A60	2	2 0	
A61	2	2 0	
A62	2	2 0	
A63	2	2 0	
A64	2	2 0	
A65	2	2 0	
A66	2	2 0	
A67	2	2 0	
A68	2	2 0	
A69	2	2 0	
A70	2	2 0	
A71	2	2 0	
A72	2	2 0	
A73	2	2 0	
A74	2	2 0	
A75	2	2 0	
A76	2	2 0	
A77	2	2 0	
A78	2	2 0	
A79	2	2 0	
A80	2	2 0	
A81	2	2 0	
A82	2	2 0	
A83	2	2 0	
A84	2	2 0	
A85	2	2 0	
A86	2	2 0	
A87	2	2 0	
A88	2	2 0	
A89	2	2 0	
A90	2	2 0	
A91	2	2 0	
A92	2	2 0	
A93	2	2 0	
A94	2	2 0	
A95	2	2 0	
A96	2	2 0	
A97	2	2 0	
A98	2	2 0	
A99	2	2 0	
A100	2	2 0	
A101	2	2 0	
A102	2	2 0	
A103	2	2 0	
A104	2	2 0	
A105	2	2 0	
A106	2	2 0	
A107	2	2 0	
A108	2	2 0	
A109	2	2 0	
A110	2	2 0	
A111	2	2 0	
A112	2	2 0	
A113	2	2 0	
A114	2	2 0	
A115	2	2 0	
A116	2	2 0	
A117	2	2 0	
A118	2	2 0	
A119	2	2 0	
A120	2	2 0	
A121	2	2 0	
A122	2	2 0	
A123	2	2 0	
A124	2	2 0	
A125	2	2 0	
A126	2	2 0	
A127	2	2 0	
A128	2	2 0	
A129	2	2 0	
A130	2	2 0	
A131	2	2 0	
A132	2	2 0	
A133	2	2 0	
A134	2	2 0	
A135	2	2 0	
A136	2	2 0	
A137	2	2 0	
A138	2	2 0	
A139	2	2 0	
A140	2	2 0	
A141	2	2 0	
A142	2	2 0	
A143	2	2 0	
A144	2	2 0	
A145	2	2 0	
A146	2	2 0	
A147	2	2 0	
A148	2	2 0	
A149	2	2 0	
A150	2	2 0	
A151	2	2 0	
A152	2	2 0	
A153	2	2 0	
A154	2	2 0	
A155	2	2 0	
A156	2	2 0	
A157	2	2 0	
A158	2	2 0	
A159	2	2 0	
A160	2	2 0	
A161	2	2 0	
A162	2	2 0	
A163	2	2 0	
A164	2	2 0	
A165	2	2 0	
A166	2	2 0	
A167	2	2 0	
A168	2	2 0	
A169	2	2 0	
A170	2	2 0	
A171	2	2 0	
A172	2	2 0	
A173	2	2 0	
A174	2	2 0	
A175	2	2 0	
A176	2	2 0	
A177	2	2 0	
A178	2	2 0	
A179	2	2 0	
A180	2	2 0	
A181	2	2 0	
A182	2	2 0	
A183	2	2 0	
A184	2	2 0	
A185	2	2 0	
A186	2	2 0	
A187	2	2 0	
A188	2	2 0	
A189	2	2 0	
A190	2	2 0	
A191	2	2 0	
A192	2	2 0	
A193	2	2 0	
A194	2	2 0	
A195	2	2 0	
A196	2	2 0	
A197	2	2 0	
A198	2	2 0	
A199	2	2 0	
A200	2	2 0	
A201	2	2 0	
A202	2	2 0	
A203	2	2 0	
A204	2	2 0	
A205	2	2 0	
A206	2	2 0	
A207	2	2 0	
A208	2	2 0	
A209	2	2 0	
A210	2	2 0	
A211	2	2 0	
A212	2	2 0	
A213	2	2 0	
A214	2	2 0	
A215	2	2 0	
A216	2	2 0	
A217	2	2 0	
A218	2	2 0	
A219	2	2 0	
A220	2	2 0	
A221	2	2 0	
A222	2	2 0	
A223	2	2 0	
A224	2	2 0	
A225	2	2 0	
A226	2	2 0	
A227	2	2 0	
A228	2	2 0	
A229	2	2 0	
A230	2	2 0	
A231	2	2 0	
A232	2	2 0	
A233	2	2 0	
A234	2	2 0	
A235	2	2 0	
A236	2	2 0	
A237	2	2 0	
A238	2	2 0	
A239	2	2 0	
A240	2	2 0	
A241	2	2 0	
A242	2	2 0	
A243	2	2 0	
A244	2	2 0	
A245	2	2 0	
A246	2	2 0	
A247	2	2 0	
A248	2	2 0	
A249	2	2 0	
A250	2	2 0	
A251	2	2 0	
A252	2	2 0	
A253	2	2 0	
A254	2	2 0	
A255	2	2 0	
A256	2	2 0	
A257	2	2 0	
A258	2	2 0	
A259	2	2 0	
A260	2	2 0	
A261	2	2 0	
A262	2	2 0	
A263	2	2 0	
A264	2	2 0	
A265	2	2 0	
A266	2	2 0	
A267	2	2 0	
A268	2	2 0	
A269	2	2 0	
A270	2	2 0	
A271	2	2 0	
A272	2	2 0	
A273	2	2 0	
A274	2	2 0	
A275	2	2 0	
A276	2	2 0	
A277	2	2 0	
A278	2	2 0	
A279	2	2 0	
A280	2	2 0	
A281	2	2 0	
A282	2	2 0	
A283	2	2 0	
A284	2	2 0	
A285	2	2 0	
A286	2	2 0	
A287	2	2 0	
A288	2	2 0	
A289	2	2 0	
A290	2	2 0	
A291	2	2 0	
A292	2	2 0	
A293	2	2 0	
A294	2	2 0	
A295	2	2 0	
A296	2	2 0	
A297	2	2 0	
A298	2	2 0	
A299	2	2 0	
A300	2	2 0	
A301	2	2 0	
A302	2	2 0	
A303	2	2 0	
A304	2	2 0	
A305	2	2 0	
A306	2	2 0	
A307	2	2 0	
A308	2	2 0	
A309	2	2 0	
A310	2	2 0	
A311	2	2 0	
A312	2	2 0	
A313	2	2 0	
A314	2	2 0	
A315	2	2 0	
A316	2	2 0	
A317	2	2 0	
A318	2	2 0	
A319	2	2 0	
A320	2	2 0	
A321	2	2 0	
A322	2	2 0	
A323	2	2 0	
A324	2	2 0	
A325	2	2 0	
A326	2	2 0	
A327	2	2 0	
A328	2	2 0	
A329	2	2 0	
A330	2	2 0	
A331	2	2 0	
A332	2	2 0	
A333	2	2 0	
A334	2	2 0	
A335	2	2 0	
A336	2	2 0	
A337	2	2 0	
A338	2	2 0	
A339	2	2 0	
A340	2	2 0	
A341	2	2 0	
A342	2	2 0	
A343	2	2 0	
A344	2	2 0	
A345	2	2 0	
A346	2	2 0	
A347	2	2 0	
A348	2	2 0	
A349	2	2 0	
A350	2	2 0	
A351	2	2 0	
A352	2	2 0	
A353	2	2 0	
A354	2	2 0	
A355	2	2 0	
A356	2	2 0	
A357	2	2 0	
A358	2	2 0	
A359	2	2 0	
A360	2	2 0	
A361	2	2 0	
A362	2	2 0	
A363	2	2 0	
A364	2	2 0	
A365	2	2 0	
A366	2	2 0	
A367	2	2 0	
A368	2	2 0	
A369	2	2 0	
A370	2	2 0	
A371	2	2 0	
A372	2	2 0	
A373	2	2 0	
A374	2	2 0	
A375	2	2 0	
A376	2	2 0	
A377	2	2 0	
A378	2	2 0	
A379	2	2 0	
A380	2	2 0	
A381	2	2 0	
A382	2	2 0	
A38			



REINFORCEMENT BAR DETAILS

THIS PAGE IS BEST QUALITY PRACTICE
FROM COPY FURNISHED TO DDD


PUTNAM COUNTY LAKE ASSOCIATION	
UNIONVILLE, MISSOURI	
INLET CONCRETE	
ALLEN & ASSOCIATES, ENGINEERS	UNIONVILLE, MISSOURI
DATE: 10/1/71	BY: [Signature]

WAM COUNTY LAKE ASSOCIATION UNIONVILLE, MISSOURI THUNDERHEAD SEWERAGE IMPROVEMENTS

INDEX


SHEET NO. 1	COVER SHEET
SHEET NO. 2 & 3	GENERAL PLAN
SHEET NO. 4 - 16	PLAN AND PROFILE
SHEET NO. 17 - 20	WASTE STABILIZATION POND
SHEET NO. 21	INFLUENT CONTROL STRUCTURE
SHEET NO. 22	CELL TRANSFER STRUCTURE
SHEET NO. 23	EFFLUENT CONTROL STRUCTURE & CHLORINATION
SHEET NO. 24	FENCE & EFFLUENT PARSHALL FLUME
SHEET NO. 25	SPECIAL STRUCTURE NO. 1
SHEET NO. 26	LIFT STATION TOPOG & HYDRAULIC PROFILE
SHEET NO. 27	SEWAGE PUMPING STATION NO. 1
SHEET NO. 28	PNEUMATIC EJECTOR LIFT STATIONS
SHEET NO. 29	MISCELLANEOUS DETAILS
SHEET NO. 30	TABULATION OF QUANTITIES

PROJECT NO. 06-1-00481



OCIATION

E MENTS



THIS PAGE IS BEST QUALITY PRAC
FROM COPY FURNISHED TO DDG

PREPARED BY
W. H. KLINGNER & ASSOCIATES
CONSULTING ENGINEERS
QUINCY, — ILLINOIS
JUNE — 1966


PLATE C-26

PUTNAM COUNTY LAKE
UNIONVILLE
SANITARY
PLAN AND
W.H. KLINGNER & ASSOC.
617 BROADWAY
DRAWN
D.E.H.
DESIGNED
W.H.K.
REVISED: 7-16-68 R.R.L.



SPECIAL STRUCTURE NO. 1
SEE DETAIL SHEET NO.

PLAN
SCALE 1" = 40'



THIS PAGE IS BEST QUALITY
FROM COPY FURNISHED

PROFILE SCALE
HORIZONTAL 1" = 40'
VERTICAL 1" = 10'




PLATE C-22 SHEET NO. 2

8" CI PIPE ON PILES
TO LAGOON

1. THE PROPOSED 8" CI PIPE SHALL BE
EXTENDED OUTSIDE THE LAGOON TO
A MINIMUM OF 10 FEET FROM THE
LAGOON EDGE. THE PIPE SHALL BE
SUPPORTED BY PILES AND SHALL BE
ANCHORED TO THE LAGOON WALL.
THE PIPE SHALL BE INSTALLED IN
A TRENCH 12" MIN. DEEP.

PROPOSED 8" CI PIPE
TO LAGOON SEE
DETAIL SHEET NO.

EXIST 8" CI PIPE

PROPOSED 8" CI PIPE
TO LAGOON SEE
DETAIL SHEET NO.

EXISTING LAKE
OUTLET STRUCTURE

DAW PI
STA 6+17.34

GENERAL PLAN

EXISTING LAKE
OUTLET STRUCTURE

2" DIA 2 LG GALV BOL
WELDED TO ANGLE, NO
WASHER, FOUR SETS

2" WIDE CURE

DETAIL


TO THE LAGOON AND TO THE
OUTLET AND WASHER, AT ALL
JUNCTIONS AND STRUCTURE

CAST 2" DIA HOLE STEPS
TO THE LAGOON AND TO THE
OUTLET AND WASHER, AT ALL
JUNCTIONS AND STRUCTURE

INVERT ELEV 52700

PUT EXISTING 8" CI PIPE TWO
FEET OUTSIDE PROPOSED STRUCTURE
CONNECT TO 8" CI PIPE USING
A STYLE OF DRESSER COUPLING


CONCRETE PILE
CONCRETE INVERT



CONCRETE HEADWALL DETAIL

SPECIAL

10" PIPE ON REES
TO LAGOON




1/4 BARS @ 12\"/>

10\"/>


PLAN
SCALE 1/4\"/>

WOOD COVER



WOOD COVER
SCALE 1/4\"/>

WOOD COVER DETAIL THIS SHEET



SECTION A-A
SCALE 1/4\"/>

A1 BARS

H1 BARS

H2 BARS

BAR DETAILS

BILL OF MATERIAL


REINFORCEMENT BARS			
MARK	NO REQ'D	LENGTH	SIZE
A1	20	1'-4"	#4
H1	64	5'-9"	#4
H2	64	7'-11"	#4
V1	64	5'-8"	#4
REINFORCEMENT BARS			1,534.85
CONCRETE			13.1 CU YDS.

THIS PAGE IS BEST QUALITY PRINT
FROM COPY FURNISHED TO DDO

REVISED: 7-18-68 K.R.L.

PUTNAM COUNTY LAKE ASSOCIATION UNIONVILLE, MISSOURI			
SANITARY SEWER SYSTEM SPECIAL STRUCTURE NO. 1			
W. H. KLINGINGER AND ASSOCIATES CONSULTING ENGINEERS QUINCY, ILL.			
DESIGNED:	DRAWN:	CHECKED:	BY:
W.H.K.	W.H.K.	K.R.L.	

SPECIAL STRUCTURE NO. 1



Secondary Cell

Effluent Outfall Line

BENCH MARK CIRCLED SQUARE ON CONC. BRIDGE FLOOR AT N.W. COR.
ELEVATION 999.00 M.S.L.

Slumps & Slides

Special Structure No. 1
(Lift Station)

FILL DITCH WITH
WASTE MATERIAL

Gully Headcut

10" San. Sewer
Seepage

MH 4

10" San. Sewer

TOE DRAIN
SEE SHEET NO. 7

PAVED VALLEY
SEE DETAIL SHEETS

MH 5

C' Water

RIPRAP

S. CUTOFF VERGE

ORIGINAL SURVEY LINE


6" BERM
ELEVATION 962.00
SEE DETAIL SHEET 10

TOE OF FILL

Existing 8" Sanitary Sewer

THIS PAGE IS BEST QUALITY PHOTO
FROM COPY FURNISHED TO DDC

General Plan of Dam Site
Modifications Installed
and Deficiencies Noted During
Inspection.



SCALE 1" = 60'





DIAGRAM FOR CAMBER ON CREST OF DAM

PUTNAM COUNTY LAKE ASSOCIATION UNIONVILLE, MISSOURI		
GENERAL PLAN OF DAM SITE		
W H KLINGNER & ASSOCIATES, CONSULTING ENGINEERS 617 BROADWAY QUINCY, ILL.		
DRAWN A B HARMAN	CHECKED E CHAMBERS	DATE MAY 1960
SHEET NO. 6 OF 6		


PLATE C

12




MAXIMUM CROSS-SECTION AT STATION 10+00
(As Measured by Inspection Team)


Scale: 1" = 25' H, 1" = 10' V.



CENTERLINE PROFILE ALONG TOP OF DAM
(As Measured by Inspection Team)

Scale: 1" = 200' H
1" = 10' V





PROFILE ALONG EMERGENCY SPILLWAY CENTERLINE
(As Measured by Inspection Team)

Scale : 1" = 50' H

1" = 5' V.

APPENDIX D
HYDRAULIC AND HYDROLOGIC DATA

HYDROLOGIC COMPUTATIONS

1. The SCS dimensionless unit hydrograph and the systemized computer program HEC-1 (Dam Safety Version), July 1978, prepared by the Hydrologic Engineering Center, U.S. Corps of Engineers, Davis, California, were used to develop the inflow hydrographs (See this Section).
 - a. Forty-eight hour, 1 percent probability rainfall for the dam location was taken from the data for the rainfall station at Kirksville, Mo. as supplied by the St. Louis District, Corps of Engineers per their letter dated 4 March 1980. The forty-eight hour probable maximum precipitation was taken from the curves of Hydrometeorological Report No. 33 and current Corps of Engineers and St. Louis policy and guidance for hydraulics and hydrology.
 - b. Drainage area = 24.34 square miles (15,580 acres). Includes area of upstream Unionville City Reservoir (1.4+ sq. mi.).
 - c. Time of concentration of runoff = 5.17 hours (computed from "Kirpich" formula, with longest length broken into three sections then totaled).
 - d. The antecedent storm conditions for the probable maximum precipitation were heavy rainfall and low temperatures which occurred on the previous 5 days (SCS AMC III). The antecedent storm conditions for the 1 percent probability precipitation were an average of the conditions which have preceded the occurrence of the maximum annual flood on numerous watersheds (SCS AMC II). The initial pool elevation was assumed at the crest of the riser. No antecedent storm was required due to the utilization of the forty-eight hour storm.
 - e. The total forty-eight hour storm duration losses for the 1 percent probability storm were 2.26 inches. The total losses for the PMF storm were 1.03 inches. These data are based on SCS runoff curve No. 79 and No. 91 for antecedent moisture conditions SCS AMC II and AMC III respectively. The watershed is composed of primarily SCS hydrologic soil groups, B, C & D. (Seymour (C) - Adair (D) - Shelby (B) soil association). Area is about 80% crops and 20% forested and pasture. Row crops are predominant with very little being contoured or terraced.
 - f. Average soil loss rates = 0.05 inch per hour approximately.
2. The discharge ratings for the principal spillway were developed using equations for orifice and weir flow. They are as follows:


- a. Orifice flow equation ($Q = CA\sqrt{2gH}$)
where C = orifice coefficient = 0.6 of weir crest, .9 at conduit entrance.
A = area of opening, $\text{ft}^2 = 121.4$
H = total head, ft.
- b. Weir flow equation ($Q_w = CLH^{1.5}$)
where C = weir coefficient = 3.0 (from SCS Engr. Memo 50)
L = length of weir, ft. = 58.6
H = total head, ft.


The emergency spillway discharge rating was developed using methods for flow over Highway Embankments in U.S.G.S. TWRI, Bk. 3, Ch. A-5 (coefficients based on h/L ratios, paved road surface, and no submergence).

The flows over the dam crest were developed using the HEC-1 (Dam Safety Version) program using the irregular top of dam option.

3. Floods were routed through the reservoir using the HEC-1 (Dam Safety Version) program to determine the capabilities of the spillway and dam embankment crest. A 24-hour PMF storm was first routed through the upstream Unionville City Reservoir dam using data obtained from plans. The upstream dam spillway passed the PMF storm so a breach was not considered necessary for routing through Thunderhead Reservoir. The upstream reservoir was then routed in series using the 48-hour storm. The input, output, and plotted hydrographs are exhibited in this Section.







[illegible]

PLATE D-7

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT 0000001
ROUTE HYDROGRAPH TO 0000002
RURFOT HYDROGRAPH AT 0000003
COMBINE 2 HYDROGRAPHS AT UM 243
ROUTE HYDROGRAPH TO 0000004
END OF NETWORK

 FLOOD HYDROGRAPH PORTLAND (REQ-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE 30/06/78.
 TIME 14.02.43.

H & H ANALYSIS OF DAM OVERTOPPING USING RATIOS OF PMF RATIOS OF PMF ROUTED THRU THE RESERVOIR

JOB SPECIFICATION									
NO	NHR	NMIN	IDAY	IDR	IMIN	METRC	IPLT	IFRT	NSTAN
144	0	30	0	0	0	0	0	3	0
			JOFFR	NUT	LROFT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

RTIOS= .20 .35 .50 .75 .80 1.00
 NPLAN= 1 NRTIO= 6 LRTIO= 1

SUB-AREA RUNOFF COMPUTATION

CALCULATION OF INFLOW HYDRO TO UNIONVILLE CITY RES

ISTAR	ICOMP	IECON	ITAFE	JPLT	JFRT	INAME	ISTAGE	IAUTO
000001	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

HYDRO	IURG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL
1	2	1.44	0.00	1.44	1.00	0.000	0	1	0

PRECIP DATA

SPFE	FMS	R6	R12	R24	R48	R72	R96
0.00	23.70	93.00	111.00	121.00	131.00	0.00	0.00

LOSS DATA

LROFT	STOR	DLTR	RTDR	LEAIN	STRES	RTDRK	STIRL	CNSTL	ALSHX	RTIME
0	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-92.00	0.00	0.00

HYDRO NO 1 -92.00 WEIRNESS = -1.00 EFFECT CN = 92.00

UNIT HYDROGRAPH DATA

TO 0.00 LAG= .82

ROUTATION DATA

STRTD	0.00	0.00	0.01	RTIOF
				1.00

THE HYDROGRAPH TO END OF PERIOD OCCURRING, TIME 0.00 HOURS, LAG= .82, RTIOF= 1.00

THE HYDROGRAPH TO END OF PERIOD OCCURRING, TIME 0.00 HOURS, LAG= .82, RTIOF= 1.00

MO. DA	HR. MIN	PERIOD	RAIN	EXC.S	LOSS	END-OF-PERIOD FLOW		MP. DA	HR. MIN	PERIOD	RAIN	EXC.S	LOSS	CUM. D
						LOW. Q	MP. DA							
1.01	1.30	1	.01	0.00	.01	0.	1.02	12.30	73	1.10	1.09	.01	89.9.	
1.01	1.00	2	.01	0.00	.01	0.	1.02	13.00	74	1.10	1.09	.01	1.35.	
1.01	1.30	3	.01	0.00	.01	0.	1.02	13.30	75	1.32	1.31	.01	177.3.	
1.01	2.00	4	.01	0.00	.01	0.	1.02	14.00	76	1.32	1.32	.01	203.7.	
1.01	2.30	5	.01	0.00	.01	0.	1.02	14.30	77	1.65	1.65	.01	237.0.	
1.01	3.00	6	.01	0.00	.01	0.	1.02	15.00	78	1.65	1.65	.01	267.3.	
1.01	3.30	7	.01	0.00	.01	0.	1.02	15.30	79	2.01	2.01	.01	293.1.	
1.01	4.00	8	.01	0.00	.01	0.	1.02	16.00	80	6.37	6.35	.01	449.4.	
1.01	4.30	9	.01	0.00	.01	0.	1.02	16.30	81	1.54	1.54	.00	62.30.	
1.01	5.00	10	.01	0.00	.01	0.	1.02	17.00	82	1.54	1.54	.00	64.30.	
1.01	5.30	11	.01	0.00	.01	0.	1.02	17.30	83	1.21	1.21	.00	39.27.	
1.01	6.00	12	.01	0.00	.01	0.	1.02	18.00	84	1.21	1.21	.00	310.6.	
1.01	6.30	13	.03	0.00	.03	0.	1.02	18.30	85	.12	.12	.00	234.6.	
1.01	7.00	14	.03	0.00	.03	0.	1.02	19.00	86	.12	.12	.00	192.9.	
1.01	7.30	15	.03	0.00	.03	0.	1.02	19.30	87	.12	.12	.00	77.4.	
1.01	8.00	16	.03	.00	.03	0.	1.02	20.00	88	.12	.12	.00	481.	
1.01	8.30	17	.03	.00	.03	1.	1.02	20.30	89	.12	.12	.00	337.	
1.01	9.00	18	.03	.00	.03	3.	1.02	21.00	90	.12	.12	.00	263.7.	
1.01	9.30	19	.03	.01	.02	5.	1.02	21.30	91	.12	.12	.00	291.	
1.01	10.00	20	.03	.01	.02	8.	1.02	22.00	92	.12	.12	.00	228.	
1.01	10.30	21	.03	.01	.02	11.	1.02	22.30	93	.12	.12	.00	232.	
1.01	11.00	22	.03	.01	.02	13.	1.02	23.00	94	.12	.12	.00	220.	
1.01	11.30	23	.03	.01	.02	15.	1.02	23.30	95	.12	.12	.00	220.	
1.01	12.00	24	.03	.01	.02	18.	1.03	0.00	96	.12	.12	.00	220.	
1.01	12.30	25	.09	.04	.05	27.	1.03	.30	97	0.00	0.00	0.00	188.3.	
1.01	13.00	26	.09	.05	.04	49.	1.03	1.00	98	0.00	0.00	0.00	111.	
1.01	13.30	27	.11	.06	.04	74.	1.03	1.30	99	0.00	0.00	0.00	62.	
1.01	14.00	28	.11	.07	.04	97.	1.03	2.00	100	0.00	0.00	0.00	62.	
1.01	14.30	29	.14	.10	.04	122.	1.03	2.30	101	0.00	0.00	0.00	62.	
1.01	15.00	30	.14	.10	.03	149.	1.03	3.00	102	0.00	0.00	0.00	62.	
1.01	15.30	31	.17	.13	.04	177.	1.03	3.30	103	0.00	0.00	0.00	62.	
1.01	16.00	32	.53	.44	.08	292.	1.03	4.00	104	0.00	0.00	0.00	62.	
1.01	16.30	33	.13	.11	.01	425.	1.03	4.30	105	0.00	0.00	0.00	62.	
1.01	17.00	34	.13	.11	.01	379.	1.03	5.00	106	0.00	0.00	0.00	62.	
1.01	17.30	35	.10	.09	.01	280.	1.03	5.30	107	0.00	0.00	0.00	62.	
1.01	18.00	36	.10	.09	.01	226.	1.03	6.00	108	0.00	0.00	0.00	62.	
1.01	18.30	37	.01	.01	.00	173.	1.03	6.30	109	0.00	0.00	0.00	62.	
1.01	19.00	38	.01	.01	.00	106.	1.03	7.00	110	0.00	0.00	0.00	62.	
1.01	19.30	39	.01	.01	.00	58.	1.03	7.30	111	0.00	0.00	0.00	62.	
1.01	20.00	40	.01	.01	.00	36.	1.03	8.00	112	0.00	0.00	0.00	62.	
1.01	20.30	41	.01	.01	.00	25.	1.03	8.30	113	0.00	0.00	0.00	62.	
1.01	21.00	42	.01	.01	.00	20.	1.03	9.00	114	0.00	0.00	0.00	62.	
1.01	21.30	43	.01	.01	.00	18.	1.03	9.30	115	0.00	0.00	0.00	62.	
1.01	22.00	44	.01	.01	.00	17.	1.03	10.00	116	0.00	0.00	0.00	62.	
1.01	22.30	45	.01	.01	.00	17.	1.03	10.30	117	0.00	0.00	0.00	62.	
1.01	23.00	46	.01	.01	.00	17.	1.03	11.00	118	0.00	0.00	0.00	62.	
1.01	23.30	47	.01	.01	.00	17.	1.03	11.30	119	0.00	0.00	0.00	62.	
1.02	0.00	48	.01	.01	.00	17.	1.03	12.00	120	0.00	0.00	0.00	62.	
1.02	.30	49	.08	.07	.01	34.	1.03	12.30	121	0.00	0.00	0.00	62.	
1.02	1.00	50	.08	.07	.01	76.	1.03	13.00	122	0.00	0.00	0.00	62.	
1.02	1.30	51	.08	.07	.01	103.	1.03	13.30	123	0.00	0.00	0.00	62.	
1.02	2.00	52	.08	.07	.01	124.	1.03	14.00	124	0.00	0.00	0.00	62.	
1.02	2.30	53	.08	.07	.01	131.	1.03	14.30	125	0.00	0.00	0.00	62.	
1.02	3.00	54	.08	.07	.00	14.	1.03	15.00	126	0.00	0.00	0.00	62.	
1.02	3.30	55	.06	.07	.00	136.	1.03	15.30	127	0.00	0.00	0.00	62.	
1.02	4.00	56	.08	.07	.00	137.	1.03	16.00	128	0.00	0.00	0.00	62.	
1.02	4.30	57	.08	.07	.00	133.	1.03	16.30	129	0.00	0.00	0.00	62.	
1.02	5.00	58	.08	.07	.00	137.	1.03	17.00	130	0.00	0.00	0.00	62.	
1.02	5.30	59	.08	.07	.00	137.	1.03	17.30	131	0.00	0.00	0.00	62.	

1.02	6.00	60	.08	.00	139.	1.03	18.00	132	0.00	0.00	62.
1.02	6.30	61	.36	.02	212.	1.03	18.30	133	0.00	0.00	62.
1.02	7.00	62	.36	.01	384.	1.03	19.00	134	0.00	0.00	62.
1.02	7.30	63	.36	.01	521.	1.03	19.30	135	0.00	0.00	62.
1.02	8.00	64	.36	.01	584.	1.03	20.00	136	0.00	0.00	62.
1.02	8.30	65	.36	.01	616.	1.03	20.30	137	0.00	0.00	62.
1.02	9.00	66	.36	.01	731.	1.03	21.00	138	0.00	0.00	62.
1.02	9.30	67	.36	.01	640.	1.03	21.30	139	0.00	0.00	62.
1.02	10.00	68	.36	.01	744.	1.03	22.00	140	0.00	0.00	62.
1.02	10.30	69	.36	.01	647.	1.03	22.30	141	0.00	0.00	62.
1.02	11.00	70	.36	.00	642.	1.03	23.00	142	0.00	0.00	62.
1.02	11.30	71	.36	.00	650.	1.03	23.30	143	0.00	0.00	62.
1.02	12.00	72	.36	.00	651.	1.04	0.00	144	0.00	0.00	62.

SUM 31.05 30.03 1.02 585.7.
(789.) (763.) (26.) (1657.58)

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
62.40.	3232.	1097.	406.	53520.
17%.	97.	31.	12.	1657.
	20.88	28.35	31.50	31.50
	530.29	720.12	800.17	800.17
	1603.	2176.	2418.	2418.
	1977.	2684.	2983.	2983.

HYDROGRAPH AT STATION 0001 FOR PLAN 1, RATIO 1

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
1246.	646.	219.	81.	11704.
35.	13.	6.	2.	331.
	4.18	5.67	6.30	6.30
	106.06	144.02	160.03	160.03
	321.	435.	484.	484.
	395.	537.	597.	597.

HYDROGRAPH AT STATION 0001 FOR PLAN 1, RATIO 2

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
2181.	1131.	384.	142.	20432.
6%.	32.	11.	4.	530.
	7.34	9.92	11.03	11.03
	185.60	252.04	280.06	280.06
	571.	762.	846.	846.
	733.	940.	1044.	1044.

HYDROGRAPH AT STATION 0001 FOR PLAN 1, RATIO 3 1/2 PMF

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
311%.	1616.	542.	203.	29720.
3%.	4%.	1%.	6%.	8%.
	102.14	14.13	1%.	1%.
	225.11	240.06	400.07	400.07
	601.	1033.	1304.	1304.
	733.	1347.	1471.	1471.

	FEAR	4-HOUR	24-HOUR	72-HOUR	TOTAL	WAVE TIME
CFS	4050.	2101.	713.	264.	384038.	384038.
CMG	115.	59.	20.	7.	1077.	1077.
INCHES		17.57	18.43	20.48	20.48	20.48
MM		344.69	468.08	520.11	520.11	520.11
AC-FT		104.2	1415.	1572.	1572.	1572.
FOOS CU M		1.35.	1745.	1939.	1939.	1939.

	FEOL	6 HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	4784.	1585.	878.	325.		46816.
CMS	141.	73.	25.	9.		1326.
INCHES		16.70	22.68	25.20		25.20
MM		424.73	576.10	640.14		640.14
AC-FM		1262.	1741.	1935.		1935.
THOUS CU M		1531.	2147.	2386.		2386.

	PEAK	4-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	62.30,	37.32,	1097,	406,	59570,	59570,
CNS	176,	92,	31,	12,	1457,	1457,
INCHES		20.88	29.35	31.50	31.50	31.50
MM		530.29	750.12	800.17	800.17	800.17
AC-FT		1603,	2176,	2418,	2418,	2418,
HOODS CU M		1977,	2684,	2983,	2983,	2983,

[illegible]

1000.

UNIT OF PERIOD HYDROGRAPH ORIGINATES

STORAGE

3001


		STATE									
30.0	9330.0	9630.0	9730.0	9830.0	9930.0	9330.0	9430.0	9530.0	9630.0	9730.0	9830.0
30.0	9330.0	9630.0	9730.0	9830.0	9930.0	9330.0	9430.0	9530.0	9630.0	9730.0	9830.0
30.0	9330.0	9630.0	9730.0	9830.0	9930.0	9330.0	9430.0	9530.0	9630.0	9730.0	9830.0
30.1	9330.1	9630.1	9730.1	9830.1	9930.1	9330.1	9430.1	9530.1	9630.1	9730.1	9830.1
30.2	9330.2	9630.2	9730.2	9830.2	9930.2	9330.2	9430.2	9530.2	9630.2	9730.2	9830.2
30.3	9330.3	9630.3	9730.3	9830.3	9930.3	9330.3	9430.3	9530.3	9630.3	9730.3	9830.3
30.4	9330.4	9630.4	9730.4	9830.4	9930.4	9330.4	9430.4	9530.4	9630.4	9730.4	9830.4
30.5	9330.5	9630.5	9730.5	9830.5	9930.5	9330.5	9430.5	9530.5	9630.5	9730.5	9830.5
30.6	9330.6	9630.6	9730.6	9830.6	9930.6	9330.6	9430.6	9530.6	9630.6	9730.6	9830.6
30.7	9330.7	9630.7	9730.7	9830.7	9930.7	9330.7	9430.7	9530.7	9630.7	9730.7	9830.7
30.8	9330.8	9630.8	9730.8	9830.8	9930.8	9330.8	9430.8	9530.8	9630.8	9730.8	9830.8
30.9	9330.9	9630.9	9730.9	9830.9	9930.9	9330.9	9430.9	9530.9	9630.9	9730.9	9830.9
31.0	9331.0	9631.0	9731.0	9831.0	9931.0	9331.0	9431.0	9531.0	9631.0	9731.0	9831.0
31.1	9331.1	9631.1	9731.1	9831.1	9931.1	9331.1	9431.1	9531.1	9631.1	9731.1	9831.1
31.2	9331.2	9631.2	9731.2	9831.2	9931.2	9331.2	9431.2	9531.2	9631.2	9731.2	9831.2
31.3	9331.3	9631.3	9731.3	9831.3	9931.3	9331.3	9431.3	9531.3	9631.3	9731.3	9831.3
31.4	9331.4	9631.4	9731.4	9831.4	9931.4	9331.4	9431.4	9531.4	9631.4	9731.4	9831.4
31.5	9331.5	9631.5	9731.5	9831.5	9931.5	9331.5	9431.5	9531.5	9631.5	9731.5	9831.5
31.6	9331.6	9631.6	9731.6	9831.6	9931.6	9331.6	9431.6	9531.6	9631.6	9731.6	9831.6
31.7	9331.7	9631.7	9731.7	9831.7	9931.7	9331.7	9431.7	9531.7	9631.7	9731.7	9831.7
31.8	9331.8	9631.8	9731.8	9831.8	9931.8	9331.8	9431.8	9531.8	9631.8	9731.8	9831.8
31.9	9331.9	9631.9	9731.9	9831.9	9931.9	9331.9	9431.9	9531.9	9631.9	9731.9	9831.9
32.0	9332.0	9632.0	9732.0	9832.0	9932.0	9332.0	9432.0	9532.0	9632.0	9732.0	9832.0
32.1	9332.1	9632.1	9732.1	9832.1	9932.1	9332.1	9432.1	9532.1	9632.1	9732.1	9832.1
32.2	9332.2	9632.2	9732.2	9832.2	9932.2	9332.2	9432.2	9532.2	9632.2	9732.2	9832.2
32.3	9332.3	9632.3	9732.3	9832.3	9932.3	9332.3	9432.3	9532.3	9632.3	9732.3	9832.3
32.4	9332.4	9632.4	9732.4	9832.4	9932.4	9332.4	9432.4	9532.4	9632.4	9732.4	9832.4
32.5	9332.5	9632.5	9732.5	9832.5	9932.5	9332.5	9432.5	9532.5	9632.5	9732.5	9832.5
32.6	9332.6	9632.6	9732.6	9832.6	9932.6	9332.6	9432.6	9532.6	9632.6	9732.6	9832.6
32.7	9332.7	9632.7	9732.7	9832.7	9932.7	9332.7	9432.7	9532.7	9632.7	9732.7	9832.7

14.	13.	14.	5.	787.
INCHES	5.41	13.01	14.95	
MM	162.93	330.50	379.82	
AC-FT	492.	999.	1143.	
MMMS CU M	607.	1232.	1416.	

2000001451

INFLOW(I), OUTFLOW(O) AND DELIVERED FLOW(N)

[illegible]



CORRELATION COEFFICIENT, PLAN 1, RATIO 6. PMF

END OF FURLO HYDROGRAPHIC COORDINATES

OUTFLOW									
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
1.	1.	2.	3.	4.	6.	8.	12.	16.	16.
20.	27.	36.	50.	77.	83.	87.	86.	84.	84.
31.	31.	75.	71.	68.	65.	60.	58.	53.	53.
50.	50.	67.	70.	74.	81.	84.	87.	90.	90.
74.	73.	139.	175.	212.	248.	311.	337.	361.	361.
84.	405.	432.	484.	568.	675.	932.	1113.	1401.	1401.
1175.	2272.	2534.	2642.	2651.	2867.	2407.	2212.	1827.	1827.
275.	1499.	1360.	1235.	1124.	1025.	953.	827.	767.	767.
711.	660.	613.	570.	530.	493.	460.	400.	374.	374.
927.	327.	306.	287.	267.	249.	233.	205.	192.	192.
131.	170.	161.	152.	144.	137.	131.	119.	114.	114.
106.	102.	99.	97.	97.	95.	93.	90.	89.	89.
87.	84.	85.	83.	81.	79.	77.	75.	73.	73.

STORAGE									
749.	749.	749.	749.	749.	749.	749.	749.	749.	749.
749.	749.	749.	749.	749.	749.	749.	749.	749.	749.
750.	751.	752.	753.	754.	755.	756.	757.	758.	759.
760.	761.	762.	763.	764.	765.	766.	767.	768.	769.
770.	771.	772.	773.	774.	775.	776.	777.	778.	779.
780.	781.	782.	783.	784.	785.	786.	787.	788.	789.
790.	791.	792.	793.	794.	795.	796.	797.	798.	799.
800.	801.	802.	803.	804.	805.	806.	807.	808.	809.
810.	811.	812.	813.	814.	815.	816.	817.	818.	819.
820.	821.	822.	823.	824.	825.	826.	827.	828.	829.
830.	831.	832.	833.	834.	835.	836.	837.	838.	839.
840.	841.	842.	843.	844.	845.	846.	847.	848.	849.
850.	851.	852.	853.	854.	855.	856.	857.	858.	859.
860.	861.	862.	863.	864.	865.	866.	867.	868.	869.
870.	871.	872.	873.	874.	875.	876.	877.	878.	879.
880.	881.	882.	883.	884.	885.	886.	887.	888.	889.
890.	891.	892.	893.	894.	895.	896.	897.	898.	899.
900.	901.	902.	903.	904.	905.	906.	907.	908.	909.
910.	911.	912.	913.	914.	915.	916.	917.	918.	919.
920.	921.	922.	923.	924.	925.	926.	927.	928.	929.
930.	931.	932.	933.	934.	935.	936.	937.	938.	939.
940.	941.	942.	943.	944.	945.	946.	947.	948.	949.
950.	951.	952.	953.	954.	955.	956.	957.	958.	959.
960.	961.	962.	963.	964.	965.	966.	967.	968.	969.
970.	971.	972.	973.	974.	975.	976.	977.	978.	979.
980.	981.	982.	983.	984.	985.	986.	987.	988.	989.
990.	991.	992.	993.	994.	995.	996.	997.	998.	999.
1000.	1001.	1002.	1003.	1004.	1005.	1006.	1007.	1008.	1009.
1010.	1011.	1012.	1013.	1014.	1015.	1016.	1017.	1018.	1019.
1020.	1021.	1022.	1023.	1024.	1025.	1026.	1027.	1028.	1029.
1030.	1031.	1032.	1033.	1034.	1035.	1036.	1037.	1038.	1039.
1040.	1041.	1042.	1043.	1044.	1045.	1046.	1047.	1048.	1049.
1050.	1051.	1052.	1053.	1054.	1055.	1056.	1057.	1058.	1059.
1060.	1061.	1062.	1063.	1064.	1065.	1066.	1067.	1068.	1069.
1070.	1071.	1072.	1073.	1074.	1075.	1076.	1077.	1078.	1079.
1080.	1081.	1082.	1083.	1084.	1085.	1086.	1087.	1088.	1089.
1090.	1091.	1092.	1093.	1094.	1095.	1096.	1097.	1098.	1099.
1100.	1101.	1102.	1103.	1104.	1105.	1106.	1107.	1108.	1109.
1110.	1111.	1112.	1113.	1114.	1115.	1116.	1117.	1118.	1119.
1120.	1121.	1122.	1123.	1124.	1125.	1126.	1127.	1128.	1129.
1130.	1131.	1132.	1133.	1134.	1135.	1136.	1137.	1138.	1139.
1140.	1141.	1142.	1143.	1144.	1145.	1146.	1147.	1148.	1149.
1150.	1151.	1152.	1153.	1154.	1155.	1156.	1157.	1158.	1159.
1160.	1161.	1162.	1163.	1164.	1165.	1166.	1167.	1168.	1169.
1170.	1171.	1172.	1173.	1174.	1175.	1176.	1177.	1178.	1179.
1180.									

[illegible][illegible]

	1 HOUR	24 HOUR	72 HOUR	TOTAL	VAL CODE
CEG	251.	212.	1027.	3390.	3390.

1598.
30.38
771.73
2332.
2877.

11.
30.38
771.73
2332.
2877.

29.
26.53
673.83
2036.
2512.


62.
14.03
356.41
1077.
1329.

75.

CMS
INCHES
MM
AC-FT
THOUS CU M

Sheet 4

STATION 00000002



11. 301 3. 10		
12. 301 3. 10		
13. 301 3. 10		
14. 301 3. 10		
15. 301 3. 10		
16. 301 3. 10		
17. 301 3. 10		
18. 301 3. 10		
19. 301 3. 10		
20. 301 3. 10		
21. 301 3. 10		
22. 301 3. 10		
23. 301 3. 10		
24. 301 3. 10		
25. 301 3. 10		
26. 301 3. 10		
27. 301 3. 10		
28. 301 3. 10		
29. 301 3. 10		
30. 301 3. 10		
31. 301 3. 10		
32. 301 3. 10		
33. 301 3. 10		
34. 301 3. 10		
35. 301 3. 10		
36. 301 3. 10		
37. 301 3. 10		
38. 301 3. 10		
39. 301 3. 10		
40. 301 3. 10		
41. 301 3. 10		
42. 301 3. 10		
43. 301 3. 10		
44. 301 3. 10		
45. 301 3. 10		
46. 301 3. 10		
47. 301 3. 10		
48. 301 3. 10		
49. 301 3. 10		
50. 301 3. 10		
51. 301 3. 10		
52. 301 3. 10		
53. 301 3. 10		
54. 301 3. 10		
55. 301 3. 10		
56. 301 3. 10		
57. 301 3. 10		
58. 301 3. 10		
59. 301 3. 10		
60. 301 3. 10		
61. 301 3. 10		
62. 301 3. 10		
63. 301 3. 10		
64. 301 3. 10		
65. 301 3. 10		
66. 301 3. 10		
67. 301 3. 10		
68. 301 3. 10		
69. 301 3. 10		
70. 301 3. 10		
71. 301 3. 10		
72. 301 3. 10		
73. 301 3. 10		
74. 301 3. 10		
75. 301 3. 10		
76. 301 3. 10		
77. 301 3. 10		
78. 301 3. 10		
79. 301 3. 10		
80. 301 3. 10		
81. 301 3. 10		
82. 301 3. 10		
83. 301 3. 10		
84. 301 3. 10		
85. 301 3. 10		
86. 301 3. 10		
87. 301 3. 10		
88. 301 3. 10		
89. 301 3. 10		
90. 301 3. 10		
91. 301 3. 10		
92. 301 3. 10		
93. 301 3. 10		
94. 301 3. 10		
95. 301 3. 10		
96. 301 3. 10		
97. 301 3. 10		
98. 301 3. 10		
99. 301 3. 10		
100. 301 3. 10		

UNIT HYDROGRAPH 33 END OF PERIOD ORIGINATES, TO= 0.00 HOURS, LAF= 3.10 VOL= 1.00

UNIT HYDROGRAPH DATA

RELIEF DATA

LOSS DATA

UNIT HYDROGRAPH DATA

RECESSION DATA

UNIT HYDROGRAPH 33 END OF PERIOD ORIGINATES, TO= 0.00 HOURS, LAF= 3.10 VOL= 1.00

HR, MN	PERIOD	RAIN	EXCS	LOSS	END OF PERIOD FLOW	MO, DA	HR, MN	PERIOD	RAIN	EXCS	LOSS	CUM, H
1.01	1.30	1	.01	0.00	.01	1.02	1.20	73	1.10	1.09	.01	0.09
1.01	1.00	2	.01	0.00	.01	1.02	13.30	74	1.10	1.09	.01	100.00
1.01	1.30	3	.01	0.00	.01	1.02	13.30	75	1.32	1.31	.01	11.241
1.01	1.00	4	.01	0.00	.01	1.02	14.00	76	1.32	1.31	.01	1.31
1.01	1.30	5	.01	0.00	.01	1.02	14.30	77	1.65	1.64	.01	1.736
1.01	1.00	6	.01	0.00	.01	1.02	15.00	78	1.65	1.65	.01	1.8934
1.01	1.30	7	.01	0.00	.01	1.02	15.30	79	2.01	2.00	.01	2.2433
1.01	1.00	8	.01	0.00	.01	1.02	16.00	80	2.37	2.35	.01	2.7417
1.01	1.30	9	.01	0.00	.01	1.02	16.30	81	1.54	1.54	.01	3.4052
1.01	1.00	10	.01	0.00	.01	1.02	17.00	82	1.54	1.54	.01	40.230
1.01	1.30	11	.01	0.00	.01	1.02	17.30	83	1.31	1.31	.01	474.32
1.01	1.00	12	.01	0.00	.01	1.02	18.00	84	1.21	1.21	.01	5.3030
1.01	1.30	13	.03	0.00	.03	1.02	18.30	85	1.12	1.12	.01	55.94%
1.01	1.00	14	.03	0.00	.03	1.02	19.00	86	1.12	1.12	.01	55.94%
1.01	1.30	15	.03	0.00	.03	1.02	19.30	87	1.12	1.12	.01	5.9412
1.01	1.00	16	.03	0.00	.03	1.02	20.00	88	1.12	1.12	.01	48.833
1.01	1.30	17	.03	0.00	.03	1.02	20.30	89	1.12	1.12	.01	4.732
1.01	1.00	18	.03	0.00	.03	1.02	21.00	90	1.12	1.12	.01	5.732
1.01	1.30	19	.03	0.00	.03	1.02	21.30	91	1.12	1.12	.01	5.732
1.01	1.00	20	.03	0.00	.03	1.02	22.00	92	1.12	1.12	.01	5.732

THICK. CU M 244.41 42186. 45905. 45905.

HYDROGRAPH AT STATION 0003 FOR PLAN 1, RATIO 1

	FEAR	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	11187.	8705.	3447.	1251.	130125.
CMS	317.	246.	98.	35.	5101.
INCHES		3.53	5.60	6.09	6.09
MM		89.78	142.26	154.81	154.81
AC-FT		4316.	6840.	7443.	7443.
THICK. CU M		5324.	8437.	9181.	9181.

HYDROGRAPH AT STATION 0003 FOR PLAN 1, RATIO 2

	FEAR	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	12581.	15233.	6035.	2189.	315217.
CMS	554.	431.	171.	62.	8926.
INCHES		6.19	9.80	10.67	10.67
MM		157.11	248.96	270.91	270.91
AC-FT		7554.	11970.	13026.	13026.
THICK. CU M		9317.	14765.	16067.	16067.

HYDROGRAPH AT STATION 0003 FOR PLAN 1, RATIO 3 $\frac{1}{2}$ PMF

	FEAR	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	27972.	21762.	8621.	3127.	450313.
CMS	772.	616.	244.	89.	12751.
INCHES		9.64	14.00	15.24	15.24
MM		244.49	355.66	387.02	387.02
AC-FT		10791.	17100.	18608.	18608.
THICK. CU M		1310.	21093.	22953.	22953.

HYDROGRAPH AT STATION 0003 FOR PLAN 1, RATIO 4

	FEAR	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	36304.	33590.	11203.	4075.	535407.
CMS	1030.	801.	317.	115.	15577.
INCHES		11.49	18.20	17.81	17.81
MM		291.77	462.36	503.13	503.13
AC-FT		14033.	22230.	24130.	24130.
THICK. CU M		17304.	27421.	29333.	29333.

HYDROGRAPH AT STATION 0003 FOR PLAN 1, RATIO 5

	FEAR	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	44774.	41377.	13754.	5003.	730301.
CMS	1367.	1037.	391.	142.	20403.
INCHES		14.14	22.40	24.23	24.23
MM		359.10	569.03	612.23	612.23
AC-FT		17777.	27777.	29777.	29777.
THICK. CU M		21304.	33333.	36234.	36234.

HYDROGRAPH AT STATION 0003 FOR PLAN 1, RATIO 6 [P.M.F.]

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	93945.	43529.	17243.	90067.
CMS	1564.	724.	288.	3553.
INCHES	17.67	8.00	30.47	30.47
MM	450.88	211.32	774.04	774.04
AC-FT	21587.	9700.	3216.	3216.
THOUS CU M	26621.	42136.	45945.	45945.

COMBINE HYDROGRAPHS

COMBINED INFLOW HYDROGRAPH TO RESERVOIR 10007

STAG	TIME	INFL	OUT	INFL	OUT	INFL	OUT
UM 243	2	0	0	2	0	1	0

SUM OF 2 HYDROGRAPHS AT UM 243 PLAN 1 RATIO 1


PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	11633.	5035.	1326.	19095.
CMS	330.	157.	38.	5407.
INCHES	3.47	5.54	6.08	6.08
MM	88.18	140.74	154.39	154.39
AC-FT	4506.	2192.	7890.	7890.
THOUS CU M	5558.	9871.	9712.	9712.


SUM OF 2 HYDROCARBONS AT UM 2+3 PLAN 1 1010 3 1/2 PMF

	FEAL	6 HOUR	24 HOUR	72 HOUR	TOTAL VOLUME
CFS	29167.	22753.	9099.	3320.	478091.
CMS	826.	644.	258.	94.	13538.
INCHES		3.69	13.90	15.22	15.22
MM		720.78	353.16	386.59	386.59
AC-FT		11202.	18047.	19756.	19756.
THOUS CUM		13917.	22261.	24368.	24368.

NO. 1

STATION 243





11.00130.1			
12.00131.1			
13.00132.1			
14.00133.1			
15.00134.1			
16.00135.1			
17.00136.1			
18.00137.1			
19.00138.1			
20.00139.1			
21.00140.1			
22.00141.1			
23.00142.1			
24.00143.1			
25.00144.1			
26.00145.1			
27.00146.1			
28.00147.1			
29.00148.1			
30.00149.1			
31.00150.1			
32.00151.1			
33.00152.1			
34.00153.1			
35.00154.1			
36.00155.1			
37.00156.1			
38.00157.1			
39.00158.1			
40.00159.1			
41.00160.1			
42.00161.1			
43.00162.1			
44.00163.1			
45.00164.1			
46.00165.1			
47.00166.1			
48.00167.1			
49.00168.1			
50.00169.1			
51.00170.1			
52.00171.1			
53.00172.1			
54.00173.1			
55.00174.1			
56.00175.1			
57.00176.1			
58.00177.1			
59.00178.1			
60.00179.1			
61.00180.1			
62.00181.1			
63.00182.1			
64.00183.1			
65.00184.1			
66.00185.1			
67.00186.1			
68.00187.1			
69.00188.1			
70.00189.1			
71.00190.1			
72.00191.1			
73.00192.1			
74.00193.1			
75.00194.1			
76.00195.1			
77.00196.1			
78.00197.1			
79.00198.1			
80.00199.1			
81.00200.1			
82.00201.1			
83.00202.1			
84.00203.1			
85.00204.1			
86.00205.1			
87.00206.1			
88.00207.1			
89.00208.1			
90.00209.1			
91.00210.1			
92.00211.1			
93.00212.1			
94.00213.1			
95.00214.1			
96.00215.1			
97.00216.1			
98.00217.1			
99.00218.1			
100.00219.1			
101.00220.1			
102.00221.1			
103.00222.1			
104.00223.1			
105.00224.1			
106.00225.1			
107.00226.1			
108.00227.1			
109.00228.1			
110.00229.1			
111.00230.1			
112.00231.1			
113.00232.1			
114.00233.1			
115.00234.1			
116.00235.1			
117.00236.1			
118.00237.1			
119.00238.1			
120.00239.1			
121.00240.1			
122.00241.1			
123.00242.1			
124.00243.1			
125.00244.1			
126.00245.1			
127.00246.1			
128.00247.1			
129.00248.1			
130.00249.1			
131.00250.1			
132.00251.1			
133.00252.1			
134.00253.1			
135.00254.1			
136.00255.1			
137.00256.1			
138.00257.1			
139.00258.1			
140.00259.1			
141.00260.1			
142.00261.1			
143.00262.1			
144.00263.1			
145.00264.1			
146.00265.1			
147.00266.1			
148.00267.1			
149.00268.1			
150.00269.1			
151.00270.1			
152.00271.1			
153.00272.1			
154.00273.1			
155.00274.1			
156.00275.1			
157.00276.1			
158.00277.1			
159.00278.1			
160.00279.1			
161.00280.1			
162.00281.1			
163.00282.1			
164.00283.1			
165.00284.1			
166.00285.1			
167.00286.1			
168.00287.1			
169.00288.1			
170.00289.1			
171.00290.1			
172.00291.1			
173.00292.1			
174.00293.1			
175.00294.1			
176.00295.1			
177.00296.1			
178.00297.1			
179.00298.1			
180.00299.1			
181.00300.1			
182.00301.1			
183.00302.1			
184.00303.1			
185.00304.1			
186.00305.1			
187.00306.1			
188.00307.1			
189.00308.1			
190.00309.1			
191.00310.1			
192.00311.1			
193.00312.1			
194.00313.1			
195.00314.1			
196.00315.1			
197.00316.1			
198.00317.1			
199.00318.1			
200.00319.1			
201.00320.1			
202.00321.1			
203.00322.1			
204.00323.1			
205.00324.1			
206.00325.1			
207.00326.1			
208.00327.1			
209.00328.1			
210.00329.1			
211.00330.1			
212.00331.1			
213.00332.1			
214.00333.1			
215.00334.1			
216.00335.1			
217.00336.1			
218.00337.1			
219.00338.1			
220.00339.1			
221.00340.1			
222.00341.1			
223.00342.1			
224.00343.1			
225.00344.1			
226.00345.1			
227.00346.1			
228.00347.1			
229.00348.1			
230.00349.1			
231.00350.1			
232.00351.1			
233.00352.1			
234.00353.1			
235.00354.1			
236.00355.1			
237.00356.1			
238.00357.1			
239.00358.1			
240.00359.1			
241.00360.1			
242.00361.1			
243.00362.1			
244.00363.1			
245.00364.1			
246.00365.1			
247.00366.1			
248.00367.1			
249.00368.1			
250.00369.1			
251.00370.1			
252.00371.1			
253.00372.1			
254.00373.1			
255.00374.1			
256.00375.1			
257.00376.1			
258.00377.1			
259.00378.1			
260.00379.1			
261.00380.1			
262.00381.1			
263.00382.1			
264.00383.1			
265.00384.1			
266.00385.1			
267.00386.1			
268.00387.1			
269.00388.1			
270.00389.1			
271.00390.1			
272.00391.1			
273.00392.1			
274.00393.1			
275.00394.1			
276.00395.1			
277.00396.1			
278.00397.1			
279.00398.1			
280.00399.1			
281.00400.1			
282.00401.1			
283.00402.1			
284.00403.1			
285.00404.1			
286.00405.1			
287.00406.1			
288.00407.1			
289.00408.1			
290.00409.1			
291.00410.1			
292.00411.1			
293.00412.1			
294.00413.1			
295.00414.1			
296.00415.1			
297.00416.1			
298.00417.1			
299.00418.1			
300.00419.1			
301.00420.1			
302.00421.1			
303.00422.1			
304.00423.1			
305.00424.1			
306.00425.1			
307.00426.1			
308.00427.1			
309.00428.1			
310.00429.1			
311.00430.1			
312.00431.1			
313.00432.1			
314.00433.1			
315.00434.1			
316.00435.1			
317.00436.1			
318.00437.1			
319.00438.1			
320.00439.1			
321.00440.1			
322.00441.1			
323.00442.1			
324.00443.1			
325.00444.1			
326.00445.1			
327.00446.1			
328.00447.1			
329.00448.1			
330.00449.1			
331.00450.1			
332.00451.1			
333.00452.1			
334.00453.1			
335.00454.1			
336.00455.1			
337.00456.1			
338.00457.1			
339.00458.1			
340.00459.1			
341.00460.1			
342.00461.1			
343.00462.1			
344.00463.1			
345.00464.1			
346.00465.1			
347.00466.1			
348.00467.1			
349.00468.1			
350.00469.1			
351.00470.1			
352.00471.1			
353.00472.1			
354.00473.1			
355.00474.1			
356.00475.1			
357.00476.1			
358.00477.1			
359.00478.1			
360.00479.1			
361.00480.1			
362.00481.1			
363.00482.1			
364.00483.1			
365.00484.1			
366.00485.1			
367.00486.1			
368.00487.1			
369.00488.1			
370.00489.1			
371.00490.1			
372.00491.1			
373.00492.1			
374.00493.1			
375.00494.1			
376.00495.1			
377.00496.1			
378.00497.1			
379.00498.1			
380.00499.1			
381.00500.1			
382.00501.1			
383.00502.1			
384.00503.1			
385.00504.1			
386.00505.1			
387.00506.1			


110VNP


SUM OF 2 HYDROGRAPHS AT						PLAN 1	RTIO 6	PMF
			6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME	
CFS	FEEL		45696.	18230.	6646.	957067.		
CMS	1659.		1294.	516.	188.	27101.		
INCHES			17.46	27.86	30.47	30.47		
MM			443.41	707.57	773.90	773.90		
AC-FT			22659.	36158.	39548.	39548.		
TOTALS CU M			27950.	44601.	48782.	48782.		

NOV 4

STATION 243

INFLOW (I), OUTFLOW (O) AND OBSERVED FLOW (F)





11. 30 174		
12. 30 174		
13. 30 174		
14. 30 174		
15. 30 174		
16. 30 174		
17. 30 174		
18. 30 174		
19. 30 174		
20. 30 174		
21. 30 174		
22. 30 174		
23. 30 174		
24. 30 174		
25. 30 174		
26. 30 174		
27. 30 174		
28. 30 174		
29. 30 174		
30. 30 174		
31. 30 174		
32. 30 174		
33. 30 174		
34. 30 174		
35. 30 174		
36. 30 174		
37. 30 174		
38. 30 174		
39. 30 174		
40. 30 174		
41. 30 174		
42. 30 174		
43. 30 174		
44. 30 174		
45. 30 174		
46. 30 174		
47. 30 174		
48. 30 174		
49. 30 174		
50. 30 174		
51. 30 174		
52. 30 174		
53. 30 174		
54. 30 174		
55. 30 174		
56. 30 174		
57. 30 174		
58. 30 174		
59. 30 174		
60. 30 174		
61. 30 174		
62. 30 174		
63. 30 174		
64. 30 174		
65. 30 174		
66. 30 174		
67. 30 174		
68. 30 174		
69. 30 174		
70. 30 174		
71. 30 174		
72. 30 174		
73. 30 174		
74. 30 174		
75. 30 174		
76. 30 174		
77. 30 174		
78. 30 174		
79. 30 174		
80. 30 174		
81. 30 174		
82. 30 174		
83. 30 174		
84. 30 174		
85. 30 174		
86. 30 174		
87. 30 174		
88. 30 174		
89. 30 174		
90. 30 174		
91. 30 174		
92. 30 174		
93. 30 174		
94. 30 174		
95. 30 174		
96. 30 174		
97. 30 174		
98. 30 174		
99. 30 174		
100. 30 174		

COUNTED FLOWS THAN RESERVOIR NO. 10007

[illegible]

DAM DATA	
CODE	EXPD
0077 4	1.5
0077 4	1.550.

[illegible]~~FAIRPLAY 006004 FLAN 1 RATIO 1~~

TEMP. OF -PERIOD HYDROGRAPH TERMINATES

FOUO

[illegible]

SECTION 000004, PLAN 1, ROLL 3

END OF THE HYPERBOFII ORDINATES

[illegible]

STORAGE

[illegible]

TABLE 1

1990	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	969.0	9
------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	---

THE UNIVERSITY OF CHICAGO

[illegible]

9.580.
10.582
267.23
13656.
16345.

65.
10.582
267.23
13656.
16345.


171.
9.29
234.76
11997.
14790.


213.
4.29
107.77
9507.
6793.

57.

CPG
INCHES
M
W - FT
1000 - CAL M

STATION 0000004





11,001,000	0	
12,001,000	0	
13,001,000	0	
14,001,000	0	
15,001,000	0	
16,001,000	0	
17,001,000	0	
18,001,000	0	
19,001,000	0	
20,001,000	0	
21,001,000	0	
22,001,000	0	
23,001,000	0	
24,001,000	0	
25,001,000	0	
26,001,000	0	
27,001,000	0	
28,001,000	0	
29,001,000	0	
30,001,000	0	
31,001,000	0	
32,001,000	0	
33,001,000	0	
34,001,000	0	
35,001,000	0	
36,001,000	0	
37,001,000	0	
38,001,000	0	
39,001,000	0	
40,001,000	0	
41,001,000	0	
42,001,000	0	
43,001,000	0	
44,001,000	0	
45,001,000	0	
46,001,000	0	
47,001,000	0	
48,001,000	0	
49,001,000	0	
50,001,000	0	
51,001,000	0	
52,001,000	0	
53,001,000	0	
54,001,000	0	
55,001,000	0	
56,001,000	0	
57,001,000	0	
58,001,000	0	
59,001,000	0	
60,001,000	0	
61,001,000	0	
62,001,000	0	
63,001,000	0	
64,001,000	0	
65,001,000	0	
66,001,000	0	
67,001,000	0	
68,001,000	0	
69,001,000	0	
70,001,000	0	
71,001,000	0	
72,001,000	0	
73,001,000	0	
74,001,000	0	
75,001,000	0	
76,001,000	0	
77,001,000	0	
78,001,000	0	
79,001,000	0	
80,001,000	0	
81,001,000	0	
82,001,000	0	
83,001,000	0	
84,001,000	0	
85,001,000	0	
86,001,000	0	
87,001,000	0	
88,001,000	0	
89,001,000	0	
90,001,000	0	
91,001,000	0	
92,001,000	0	
93,001,000	0	
94,001,000	0	
95,001,000	0	
96,001,000	0	
97,001,000	0	
98,001,000	0	
99,001,000	0	
100,001,000	0	

STATION 000004, FLAN 1, RATIO 6
END OF PERIOD HYDROGRAPH ORDINATES

OUTFLOW									
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.
0.	0.	0.	1.	2.	3.	4.	6.	8.	8.
1.	17.	24.	33.	45.	59.	85.	115.	144.	175.
106.	258.	368.	477.	592.	704.	813.	919.	1025.	1129.
334.	434.	534.	632.	728.	821.	907.	987.	1061.	1134.
474.	574.	674.	771.	866.	959.	1049.	1136.	1220.	1301.
1160.	1260.	1360.	1457.	1551.	1642.	1730.	1815.	1897.	1977.
1836.	1936.	2036.	2131.	2223.	2312.	2398.	2481.	2561.	2638.
2617.	2717.	2817.	2911.	3002.	3090.	3175.	3257.	3336.	3412.
3498.	3598.	3698.	3791.	3881.	3968.	4052.	4133.	4211.	4286.
4365.	4465.	4565.	4651.	4734.	4814.	4891.	4965.	5036.	5104.
5190.	5290.	5390.	5476.	5559.	5639.	5716.	5790.	5861.	5929.
6000.	6100.	6200.	6283.	6364.	6443.	6519.	6592.	6662.	6729.
6800.	6900.	7000.	7083.	7164.	7243.	7319.	7392.	7462.	7529.
7600.	7700.	7800.	7883.	7964.	8043.	8119.	8192.	8262.	8329.
8400.	8500.	8600.	8683.	8764.	8843.	8919.	8992.	9062.	9129.
9200.	9300.	9400.	9483.	9564.	9643.	9719.	9792.	9862.	9929.
10000.	10100.	10200.	10283.	10364.	10443.	10519.	10592.	10662.	10729.
10800.	10900.	11000.	11083.	11164.	11243.	11319.	11392.	11462.	11529.
11600.	11700.	11800.	11883.	11964.	12043.	12119.	12192.	12262.	12329.
12400.	12500.	12600.	12683.	12764.	12843.	12919.	12992.	13062.	13129.
13200.	13300.	13400.	13483.	13564.	13643.	13719.	13792.	13862.	13929.
14000.	14100.	14200.	14283.	14364.	14443.	14519.	14592.	14662.	14729.
14800.	14900.	15000.	15083.	15164.	15243.	15319.	15392.	15462.	15529.
15600.	15700.	15800.	15883.	15964.	16043.	16119.	16192.	16262.	16329.
16400.	16500.	16600.	16683.	16764.	16843.	16919.	16992.	17062.	17129.
17200.	17300.	17400.	17483.	17564.	17643.	17719.	17792.	17862.	17929.
18000.	18100.	18200.	18283.	18364.	18443.	18519.	18592.	18662.	18729.
18800.	18900.	19000.	19083.	19164.	19243.	19319.	19392.	19462.	19529.
19600.	19700.	19800.	19883.	19964.	20043.	20119.	20192.	20262.	20329.
20400.	20500.	20600.	20683.	20764.	20843.	20919.	20992.	21062.	21129.
21200.	21300.	21400.	21483.	21564.	21643.	21719.	21792.	21862.	21929.
22000.	22100.	22200.	22283.	22364.	22443.	22519.	22592.	22662.	22729.
22800.	22900.	23000.	23083.	23164.	23243.	23319.	23392.	23462.	23529.
23600.	23700.	23800.	23883.	23964.	24043.	24119.	24192.	24262.	24329.
24400.	24500.	24600.	24683.	24764.	24843.	24919.	24992.	25062.	25129.
25200.	25300.	25400.	25483.	25564.	25643.	25719.	25792.	25862.	25929.
26000.	26100.	26200.	26283.	26364.	26443.	26519.	26592.	26662.	26729.
26800.	26900.	27000.	27083.	27164.	27243.	27319.	27392.	27462.	27529.
27600.	27700.	27800.	27883.	27964.	28043.	28119.	28192.	28262.	28329.
28400.	28500.	28600.	28683.	28764.	28843.	28			

[illegible]

RECEIVED BY THE U.S. DEPT. OF THE INTERIOR

Year	Books	ed. Books	2 nd Books	Total
1970	2,400	1,000	1,000	4,400
1971	2,400	1,000	1,000	4,400
1972	2,400	1,000	1,000	4,400
1973	2,400	1,000	1,000	4,400
1974	2,400	1,000	1,000	4,400
1975	2,400	1,000	1,000	4,400
1976	2,400	1,000	1,000	4,400
1977	2,400	1,000	1,000	4,400
1978	2,400	1,000	1,000	4,400
1979	2,400	1,000	1,000	4,400
1980	2,400	1,000	1,000	4,400
1981	2,400	1,000	1,000	4,400
1982	2,400	1,000	1,000	4,400
1983	2,400	1,000	1,000	4,400
1984	2,400	1,000	1,000	4,400
1985	2,400	1,000	1,000	4,400
1986	2,400	1,000	1,000	4,400
1987	2,400	1,000	1,000	4,400
1988	2,400	1,000	1,000	4,400
1989	2,400	1,000	1,000	4,400
1990	2,400	1,000	1,000	4,400
1991	2,400	1,000	1,000	4,400
1992	2,400	1,000	1,000	4,400
1993	2,400	1,000	1,000	4,400
1994	2,400	1,000	1,000	4,400
1995	2,400	1,000	1,000	4,400
1996	2,400	1,000	1,000	4,400
1997	2,400	1,000	1,000	4,400
1998	2,400	1,000	1,000	4,400
1999	2,400	1,000	1,000	4,400
2000	2,400	1,000	1,000	4,400
2001	2,400	1,000	1,000	4,400
2002	2,400	1,000	1,000	4,400
2003	2,400	1,000	1,000	4,400
2004	2,400	1,000	1,000	4,400
2005	2,400	1,000	1,000	4,400
2006	2,400	1,000	1,000	4,400
2007	2,400	1,000	1,000	4,400
2008	2,400	1,000	1,000	4,400
2009	2,400	1,000	1,000	4,400
2010	2,400	1,000	1,000	4,400
2011	2,400	1,000	1,000	4,400
2012	2,400	1,000	1,000	4,400
2013	2,400	1,000	1,000	4,400
2014	2,400	1,000	1,000	4,400
2015	2,400	1,000	1,000	4,400
2016	2,400	1,000	1,000	4,400
2017	2,400	1,000	1,000	4,400
2018	2,400	1,000	1,000	4,400
2019	2,400	1,000	1,000	4,400
2020	2,400	1,000	1,000	4,400
2021	2,400	1,000	1,000	4,400
2022	2,400	1,000	1,000	4,400
2023	2,400	1,000	1,000	4,400
2024	2,400	1,000	1,000	4,400
2025	2,400	1,000	1,000	4,400
2026	2,400	1,000	1,000	4,400
2027	2,400	1,000	1,000	4,400
2028	2,400	1,000	1,000	4,400
2029	2,400	1,000	1,000	4,400
2030	2,400	1,000	1,000	4,400
2031	2,400	1,000	1,000	4,400
2032	2,400	1,000	1,000	4,400
2033	2,400	1,000	1,000	4,400
2034	2,400	1,000	1,000	4,400
2035	2,400	1,000	1,000	4,400

22525.
25.32
643.22
32870.
40544.

156.
25.32
643.22
32870.
40544.

431.
23.26
590.73
30188.
37230.

1006.
13.57
344.57
17408.
21720.


1287.
13.57
344.57
17408.
21720.

CMS
INCHES
MM
AC-FT
THOUS CU M

NOV 8

STATION 0000004

INFLOW (C), OUTFLOW (C) AND OBSERVED FLOW (C)



4. 30 5.20 1
 5. 00 5.30 1
 6. 30 5.40 1
 7. 00 5.50 1
 8. 30 6.00 1
 9. 00 6.10 1
 10. 30 6.20 1
 11. 00 6.30 1
 12. 30 6.40 1
 13. 00 6.50 1
 14. 30 7.00 1
 15. 00 7.10 1
 16. 30 7.20 1
 17. 00 7.30 1
 18. 30 7.40 1
 19. 00 7.50 1
 20. 30 8.00 1
 21. 00 8.10 1
 22. 30 8.20 1
 23. 00 8.30 1
 24. 30 8.40 1
 25. 00 8.50 1
 26. 30 9.00 1
 27. 00 9.10 1
 28. 30 9.20 1
 29. 00 9.30 1
 30. 30 9.40 1
 31. 00 9.50 1
 32. 30 10.00 1
 33. 00 10.10 1
 34. 30 10.20 1
 35. 00 10.30 1
 36. 30 10.40 1
 37. 00 10.50 1
 38. 30 11.00 1
 39. 00 11.10 1
 40. 30 11.20 1
 41. 00 11.30 1
 42. 30 11.40 1
 43. 00 11.50 1
 44. 30 12.00 1
 45. 00 12.10 1
 46. 30 12.20 1
 47. 00 12.30 1
 48. 30 12.40 1
 49. 00 12.50 1
 50. 30 1.00 1
 51. 00 1.10 1
 52. 30 1.20 1
 53. 00 1.30 1
 54. 30 1.40 1
 55. 00 1.50 1
 56. 30 2.00 1
 57. 00 2.10 1
 58. 30 2.20 1
 59. 00 2.30 1
 60. 30 2.40 1
 61. 00 2.50 1
 62. 30 3.00 1
 63. 00 3.10 1
 64. 30 3.20 1
 65. 00 3.30 1
 66. 30 3.40 1
 67. 00 3.50 1
 68. 30 4.00 1
 69. 00 4.10 1
 70. 30 4.20 1
 71. 00 4.30 1
 72. 30 4.40 1
 73. 00 4.50 1
 74. 30 5.00 1
 75. 00 5.10 1
 76. 30 5.20 1
 77. 00 5.30 1
 78. 30 5.40 1
 79. 00 5.50 1
 80. 30 6.00 1
 81. 00 6.10 1
 82. 30 6.20 1
 83. 00 6.30 1
 84. 30 6.40 1
 85. 00 6.50 1
 86. 30 7.00 1
 87. 00 7.10 1
 88. 30 7.20 1
 89. 00 7.30 1
 90. 30 7.40 1
 91. 00 7.50 1
 92. 30 8.00 1
 93. 00 8.10 1
 94. 30 8.20 1
 95. 00 8.30 1
 96. 30 8.40 1
 97. 00 8.50 1
 98. 30 9.00 1
 99. 00 9.10 1
 100. 30 9.20 1
 101. 00 9.30 1
 102. 30 9.40 1
 103. 00 9.50 1
 104. 30 10.00 1
 105. 00 10.10 1
 106. 30 10.20 1
 107. 00 10.30 1
 108. 30 10.40 1
 109. 00 10.50 1
 110. 30 11.00 1
 111. 00 11.10 1
 112. 30 11.20 1
 113. 00 11.30 1
 114. 30 11.40 1
 115. 00 11.50 1
 116. 30 12.00 1
 117. 00 12.10 1
 118. 30 12.20 1
 119. 00 12.30 1
 120. 30 12.40 1
 121. 00 12.50 1
 122. 30 1.00 1
 123. 00 1.10 1
 124. 30 1.20 1
 125. 00 1.30 1
 126. 30 1.40 1
 127. 00 1.50 1
 128. 30 2.00 1
 129. 00 2.10 1
 130. 30 2.20 1
 131. 00 2.30 1
 132. 30 2.40 1
 133. 00 2.50 1
 134. 30 3.00 1
 135. 00 3.10 1
 136. 30 3.20 1
 137. 00 3.30 1
 138. 30 3.40 1
 139. 00 3.50 1
 140. 30 4.00 1
 141. 00 4.10 1
 142. 30 4.20 1
 143. 00 4.30 1
 144. 30 4.40 1
 145. 00 4.50 1
 146. 30 5.00 1
 147. 00 5.10 1
 148. 30 5.20 1
 149. 00 5.30 1
 150. 30 5.40 1
 151. 00 5.50 1
 152. 30 6.00 1
 153. 00 6.10 1
 154. 30 6.20 1
 155. 00 6.30 1
 156. 30 6.40 1
 157. 00 6.50 1
 158. 30 7.00 1
 159. 00 7.10 1
 160. 30 7.20 1
 161. 00 7.30 1
 162. 30 7.40 1
 163. 00 7.50 1
 164. 30 8.00 1
 165. 00 8.10 1
 166. 30 8.20 1
 167. 00 8.30 1
 168. 30 8.40 1
 169. 00 8.50 1
 170. 30 9.00 1
 171. 00 9.10 1
 172. 30 9.20 1
 173. 00 9.30 1
 174. 30 9.40 1
 175. 00 9.50 1
 176. 30 10.00 1
 177. 00 10.10 1
 178. 30 10.20 1
 179. 00 10.30 1
 180. 30 10.40 1
 181. 00 10.50 1
 182. 30 11.00 1
 183. 00 11.10 1
 184. 30 11.20 1
 185. 00 11.30 1
 186. 30 11.40 1
 187. 00 11.50 1
 188. 30 12.00 1
 189. 00 12.10 1
 190. 30 12.20 1
 191. 00 12.30 1
 192. 30 12.40 1
 193. 00 12.50 1
 194. 30 1.00 1
 195. 00 1.10 1
 196. 30 1.20 1
 197. 00 1.30 1
 198. 30 1.40 1
 199. 00 1.50 1
 200. 30 2.00 1
 201. 00 2.10 1
 202. 30 2.20 1
 203. 00 2.30 1
 204. 30 2.40 1
 205. 00 2.50 1
 206. 30 3.00 1
 207. 00 3.10 1
 208. 30 3.20 1
 209. 00 3.30 1
 210. 30 3.40 1
 211. 00 3.50 1
 212. 30 4.00 1
 213. 00 4.10 1
 214. 30 4.20 1
 215. 00 4.30 1
 216. 30 4.40 1
 217. 00 4.50 1
 218. 30 5.00 1
 219. 00 5.10 1
 220. 30 5.20 1
 221. 00 5.30 1
 222. 30 5.40 1
 223. 00 5.50 1
 224. 30 6.00 1
 225. 00 6.10 1
 226. 30 6.20 1
 227. 00 6.30 1
 228. 30 6.40 1
 229. 00 6.50 1
 230. 30 7.00 1
 231. 00 7.10 1
 232. 30 7.20 1
 233. 00 7.30 1
 234. 30 7.40 1
 235. 00 7.50 1
 236. 30 8.00 1
 237. 00 8.10 1
 238. 30 8.20 1
 239. 00 8.30 1
 240. 30 8.40 1
 241. 00 8.50 1
 242. 30 9.00 1
 243. 00 9.10 1
 244. 30 9.20 1
 245. 00 9.30 1
 246. 30 9.40 1
 247. 00 9.50 1
 248. 30 10.00 1
 249. 00 10.10 1
 250. 30 10.20 1
 251. 00 10.30 1
 252. 30 10.40 1
 253. 00 10.50 1
 254. 30 11.00 1
 255. 00 11.10 1
 256. 30 11.20 1
 257. 00 11.30 1
 258. 30 11.40 1
 259. 00 11.50 1
 260. 30 12.00 1
 261. 00 12.10 1
 262. 30 12.20 1
 263. 00 12.30 1
 264. 30 12.40 1
 265. 00 12.50 1
 266. 30 1.00 1
 267. 00 1.10 1
 268. 30 1.20 1
 269. 00 1.30 1
 270. 30 1.40 1
 271. 00 1.50 1
 272. 30 2.00 1
 273. 00 2.10 1
 274. 30 2.20 1
 275. 00 2.30 1
 276. 30 2.40 1
 277. 00 2.50 1
 278. 30 3.00 1
 279. 00 3.10 1
 280. 30 3.20 1
 281. 00 3.30 1
 282. 30 3.40 1
 283. 00 3.50 1
 284. 30 4.00 1
 285. 00 4.10 1
 286. 30 4.20 1
 287. 00 4.30 1
 288. 30 4.40 1
 289. 00 4.50 1
 290. 30 5.00 1
 291. 00 5.10 1
 292. 30 5.20 1
 293. 00 5.30 1
 294. 30 5.40 1
 295. 00 5.50 1
 296. 30 6.00 1
 297. 00 6.10 1
 298. 30 6.20 1
 299. 00 6.30 1
 300. 30 6.40 1
 301. 00 6.50 1
 302. 30 7.00 1
 303. 00 7.10 1
 304. 30 7.20 1
 305. 00 7.30 1
 306. 30 7.40 1
 307. 00 7.50 1
 308. 30 8.00 1
 309. 00 8.10 1
 310. 30 8.20 1
 311. 00 8.30 1
 312. 30 8.40 1
 313. 00 8.50 1
 314. 30 9.00 1
 315. 00 9.10 1
 316. 30 9.20 1
 317. 00 9.30 1
 318. 30 9.40 1
 319. 00 9.50 1
 320. 30 10.00 1
 321. 00 10.10 1
 322. 30 10.20 1
 323. 00 10.30 1
 324. 30 10.40 1
 325. 00 10.50 1
 326. 30 11.00 1
 327. 00 11.10 1
 328. 30 11.20 1
 329. 00 11.30 1
 330. 30 11.40 1
 331. 00 11.50 1
 332. 30 12.00 1
 333. 00 12.10 1
 334. 30 12.20 1
 335. 00 12.30 1
 336. 30 12.40 1
 337. 00 12.50 1
 338. 30 1.00 1
 339. 00 1.10 1
 340. 30 1.20 1
 341. 00 1.30 1
 342. 30 1.40 1
 343. 00 1.50 1
 344. 30 2.00 1
 345. 00 2.10 1
 346. 30 2.20 1
 347. 00 2.30 1
 348. 30 2.40 1
 349. 00 2.50 1
 350. 30 3.00 1
 351. 00 3.10 1
 352. 30 3.20 1
 353. 00 3.30 1
 354. 30 3.40 1
 355. 00 3.50 1
 356. 30 4.00 1
 357. 00 4.10 1
 358. 30 4.20 1
 359. 00 4.30 1
 360. 30 4.40 1
 361. 00 4.50 1
 362. 30 5.00 1
 363. 00 5.10 1
 364. 30 5.20 1
 365. 00 5.30 1
 366. 30 5.40 1
 367. 00 5.50 1
 368. 30 6.00 1
 369. 00 6.10 1
 370. 30 6.20 1
 371. 00 6.30 1
 372. 30 6.40 1
 373. 00 6.50 1
 374. 30 7.00 1
 375. 00 7.10 1
 376. 30 7.20 1
 377. 00 7.30 1
 378. 30 7.40 1
 379. 00 7.50 1
 380. 30 8.00 1
 381. 00 8.10 1
 382. 30 8.20 1
 383. 00 8.30 1
 384. 30 8.40 1
 385. 00 8.50 1
 386. 30 9.00 1
 387. 00 9.10 1
 388. 30 9.20 1
 389. 00 9.30 1
 390. 30 9.40 1
 391. 00 9.50 1
 392. 30 10.00 1
 393. 00 10.10 1
 394. 30 10.20 1
 395. 00 10.30 1
 396. 30 10.40 1
 397. 00 10.50 1
 398. 30 11.00 1
 399. 00 11.10 1
 400. 30 11.20 1
 401. 00 11.30 1
 402. 30 11.40 1
 403. 00 11.50 1
 404. 30 12.00 1
 405. 00 12.10 1
 406. 30 12.20 1
 407. 00 12.30 1
 408. 30 12.40 1
 409. 00 12.50 1
 410. 30 1.00 1
 411. 00 1.10 1
 412. 30 1.20 1
 413. 00 1.30 1
 414. 30 1.40 1
 415. 00 1.50 1
 416. 30 2.00 1
 417. 00 2.10 1
 418. 30 2.20 1
 419. 00 2.30 1
 420. 30 2.40 1
 421. 00 2.50 1
 422. 30 3.00 1
 423. 00 3.10 1
 424. 30 3.20 1
 425. 00 3.30 1
 426. 30 3.40 1
 427. 00 3.50 1
 428. 30 4.00 1
 429. 00 4.10 1
 430. 30 4.20 1
 431. 00 4.30 1
 432. 30 4.40 1
 433. 00 4.50 1
 434. 30 5.00 1
 435. 00 5.10 1
 436. 30 5.20 1
 437. 00 5.30 1
 438. 30 5.40 1
 439. 00 5.50 1
 440. 30 6.00 1
 441. 00 6.10 1
 442. 30 6.20 1
 443. 00 6.30 1
 444. 30 6.40 1
 445. 00 6.50 1
 446. 30 7.00 1
 447. 00 7.10 1
 448. 30 7.20 1
 449. 00 7.30 1
 450. 30 7.40 1
 451. 00 7.50 1
 452. 30 8.00 1
 453. 00 8.10 1
 454. 30 8.20 1
 455. 00 8.30 1
 456. 30 8.40 1
 457. 00 8.50 1
 458. 30 9.00 1
 459. 00 9.10 1
 460. 30 9.20 1
 461. 00 9.30 1
 462. 30 9.40 1
 463. 00 9.50 1
 464. 30 10.00 1
 465. 00 10.10 1
 466. 30 10.20 1
 467. 00 10.30 1
 468. 30 10.40 1
 469. 00 10.50 1
 470. 30 11.00 1
 471. 00 11.10 1
 472. 30 11.20 1
 473. 00 11.30 1
 474. 30 11.40 1
 475. 00 11.50 1
 476. 30 12.00 1
 477. 00 12.10 1
 478. 30 12.20 1
 479. 00 12.30 1
 480. 30 12.40 1
 481. 00 12.50 1
 482. 30 1.00 1
 483. 00 1.10 1
 484. 30 1.20 1
 485. 00 1.30 1
 486. 30 1.40 1
 487. 00 1.50 1
 488. 30 2.00 1
 489. 00 2.10 1
 490. 30 2.20 1
 491. 00 2.30 1
 492. 30 2.40 1
 493. 00 2.50 1
 494. 30 3.00 1
 495. 00 3.10 1
 496. 30 3.20 1
 497. 00 3.30 1
 498. 30 3.40 1
 499. 00 3.50 1
 500. 30 4.00 1
 501. 00 4.10 1
 502. 30 4.20 1
 503. 00 4.30 1
 504. 30 4.40 1
 505. 00 4.50 1
 506. 30 5.00 1
 507. 00 5.10 1
 508. 30 5.20 1
 509. 00 5.30 1
 510. 30 5.40 1
 511. 00 5.50 1
 512. 30 6.00 1
 513. 00 6.10 1
 514. 30 6.20 1
 515. 00 6.30 1
 516. 30 6.40 1
 517. 00 6.50 1
 518. 30 7.00 1
 519. 00 7.10 1
 520. 30 7.20 1
 521. 00 7.30 1
 522. 30 7.40 1
 523. 00 7.50 1
 524. 30 8.00 1
 525. 00 8.10 1
 526. 30 8.20 1
 527. 00 8.30 1
 528. 30 8.40 1
 529. 00 8.50 1
 530. 30 9.00 1
 531. 00 9.10 1
 532. 30 9.20 1
 533. 00 9.30 1
 534. 30 9.40 1
 535. 00 9.50 1
 536. 30 10.00 1
 537. 00 10.10 1
 538. 30 10.20 1
 539. 00 10.30 1
 540. 30 10.40 1
 541. 00 10.50 1
 542. 30 11.00 1
 543. 00 11.10 1
 544. 30 11.20 1
 545. 00 11.30 1
 546. 30 11.40 1
 547. 00 11.50 1
 548. 30 12.00 1
 549. 00 12.10 1
 550. 30 12.20 1
 551. 00 12.30 1
 552. 30 12.40 1
 553. 00 12.50 1
 554. 30 1.00 1
 555. 00 1.10 1
 556. 30 1.20 1
 557. 00 1.30 1
 558. 30 1.40 1
 559. 00 1.50 1
 560. 30 2.00 1
 561. 00 2.10 1
 562. 30 2.20 1
 563. 00 2.30 1
 564. 30 2.40 1
 565. 00 2.50 1
 566. 30 3.00 1
 567. 00 3.10 1
 568. 30 3.20 1
 569. 00 3.30 1
 570. 30 3.40 1
 571. 00 3.50 1
 572. 30 4.00 1
 573. 00 4.10 1
 574. 30 4.20 1
 575. 00 4.30 1
 576. 30 4.40 1
 577. 00 4.50 1
 578. 30 5.00 1
 579. 00 5.10 1
 580. 30 5.20 1
 581. 00 5.30 1
 582. 30 5.40 1
 583. 00 5.50 1
 584. 30 6.00 1
 585. 00 6.10 1
 586. 30 6.20 1
 587. 00 6.30 1
 588. 30 6.40 1
 589. 00 6.50 1
 590. 30 7.00 1
 591. 00 7.10 1
 592. 30 7.20 1
 593. 00 7.30 1
 594. 30 7.40 1
 595. 00 7.50 1
 596. 30 8.00 1
 597. 00 8.10 1
 598. 30 8.20 1
 599. 00 8.30 1
 600. 30 8.40 1
 601. 00 8.50 1
 602. 30 9.00 1
 603. 00 9.10 1
 604. 30 9.20 1
 605. 00 9.30 1
 606. 30 9.40 1
 607. 00 9.50 1
 608. 30 10.00 1
 609. 00 10.10 1
 610. 30 10.20 1
 611. 00 10.30 1
 612. 30 10.40 1
 613. 00 10.50 1
 614. 30 11.00 1
 615. 00 11.10 1
 616. 30 11.20 1
 617. 00 11.30 1
 618. 30 11.40 1
 619. 00 11.50 1
 620. 30 12.00 1
 621. 00 12.10 1
 622. 30 12.20 1
 623. 00 12.30 1
 624. 30 12.40 1
 625. 00 12.50 1
 626. 30 1.00 1
 627. 00 1.10 1
 628. 30 1.20 1
 629. 00 1.30 1
 630. 30 1.40 1
 631. 00 1.50 1
 632. 30 2.00 1
 633. 00 2.10 1
 634. 30 2.20 1
 635. 00 2.30 1
 636. 30 2.40 1
 637. 00 2.50 1
 638. 30 3.00 1
 639. 00 3.10 1
 640. 30 3.20 1
 641. 00 3.30 1
 642. 30 3.40 1
 643. 00 3.50 1
 644. 30 4.00 1
 645. 00 4.10 1
 646. 30 4.20 1
 647. 00 4.30 1
 648. 30 4.40 1
 649. 00 4.50 1
 650. 30 5.00 1

11,000,000.00	
12,000,000.00	
13,000,000.00	
14,000,000.00	
15,000,000.00	
16,000,000.00	
17,000,000.00	
18,000,000.00	
19,000,000.00	
20,000,000.00	
21,000,000.00	
22,000,000.00	
23,000,000.00	
24,000,000.00	
25,000,000.00	
26,000,000.00	
27,000,000.00	
28,000,000.00	
29,000,000.00	
30,000,000.00	
31,000,000.00	
32,000,000.00	
33,000,000.00	
34,000,000.00	
35,000,000.00	
36,000,000.00	
37,000,000.00	
38,000,000.00	
39,000,000.00	
40,000,000.00	
41,000,000.00	
42,000,000.00	
43,000,000.00	
44,000,000.00	
45,000,000.00	
46,000,000.00	
47,000,000.00	
48,000,000.00	
49,000,000.00	
50,000,000.00	
51,000,000.00	
52,000,000.00	
53,000,000.00	
54,000,000.00	
55,000,000.00	
56,000,000.00	
57,000,000.00	
58,000,000.00	
59,000,000.00	
60,000,000.00	
61,000,000.00	
62,000,000.00	
63,000,000.00	
64,000,000.00	
65,000,000.00	
66,000,000.00	
67,000,000.00	
68,000,000.00	
69,000,000.00	
70,000,000.00	
71,000,000.00	
72,000,000.00	
73,000,000.00	
74,000,000.00	
75,000,000.00	
76,000,000.00	
77,000,000.00	
78,000,000.00	
79,000,000.00	
80,000,000.00	
81,000,000.00	
82,000,000.00	
83,000,000.00	
84,000,000.00	
85,000,000.00	
86,000,000.00	
87,000,000.00	
88,000,000.00	
89,000,000.00	
90,000,000.00	
91,000,000.00	
92,000,000.00	
93,000,000.00	
94,000,000.00	
95,000,000.00	
96,000,000.00	
97,000,000.00	
98,000,000.00	
99,000,000.00	
100,000,000.00	

FLOW FLOOD AND DRAINAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE FEET (SQUARE METERS)

COMPUTATION	ELEVATION	AREA	PLAN RATIO	RATIOS APPLIED TO FLOWS					
				1	2	3	4	5	6
				.20	.35	.50	.65	.80	1.00
HYDROGRAPH AT	000001	1.44 (3.73)	1	1746. (35.23)	2131. (41.75)	3115. (63.21)	4050. (114.47)	4984. (141.13)	4230. (176.42)
ROUTED TO	000002	1.44 (3.73)	1	442. (12.71)	800. (22.65)	1197. (33.08)	1641. (46.48)	2078. (58.83)	2451. (75.07)
HYDROGRAPH AT	000003	22.91 (59.34)	1	11109. (316.84)	19581. (554.46)	27972. (792.09)	36364. (1029.72)	44756. (1267.34)	55945. (1584.18)
COMPUTED	000004	24.35 (63.07)	1	11633. (429.45)	20381. (577.12)	29169. (825.97)	38006. (1076.20)	46833. (1326.18)	58596. (1659.25)
ROUTED TO	000004	24.35 (63.07)	1	1666. (47.16)	6141. (173.91)	12617. (357.27)	21296. (603.05)	31799. (900.44)	45433. (1286.66)

COMPARISON OF DAM SAFETY ANALYSIS

RATIO OF FPM	ELEVATION STORAGE OUTFLOW	INITIAL VALUE		SPILLWAY CREST	TOP OF DAM	DURATION OVER TOP HOURS	MAXIMUM OUTFLOW CFS	MAXIMUM STORAGE AC-FT	MAXIMUM DEFICIT OVER DAM	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
		74%	0.	74%	74%						
1.00	982.76	980.00	0.	980.00	983.00	0.00	449.	1014.	0.00	42.50	0.00
.75	984.02				27.28.	0.00	600.	1192.	0.00	42.50	0.00
.50	985.17				43.33.	0.00	1197.	1363.	0.00	42.50	0.00
.25	986.24					0.00	1641.	1521.	0.00	42.50	0.00
.00	987.29					0.00	2076.	1677.	0.00	42.50	0.00
1.00	988.66					0.00	2651.	1831.	0.00	42.50	0.00

SUMMARY OF DAM SAFETY ANALYSIS

RAISED TO FPM	ELEVATION STORAGE OUTFLOW	INITIAL VALUE		SPILLWAY CREST		TOP OF DAM	
		969.00	14146.	969.00	14146.	977.40	27187.
		0.	0.	0.	0.	8270.	
	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS	
.20	974.15	22385.	1666.	0.00	42.50	0.00	
.35	976.62	25975.	3141.	0.00	47.00	0.00	
.50	978.41	28306.	4617.	7.00	46.00	0.00	
.75	979.71	30298.	21296.	10.00	45.50	0.00	
.90	980.44	32633.	31799.	11.50	45.00	0.00	
1.00	981.60	34362.	45438.	13.00	44.50	0.00	

APPENDIX E
FOUNDATION, EMBANKMENT AND INSPECTION REPORTS

APPENDIX E

DIVISION I

SOILS REPORT, PUTNAM COUNTY LAKE

OCTOBER, 1964

SOILS REPORT
PUTNAM COUNTY LAKE
UNIONVILLE, MONTGOMERY

OCTOBER, 1964

Dr. Thomas S. Fry, P. E.

SOILS REPORT
PUTNAM COUNTY LAKE
UNIONVILLE, MISSOURI

THIS PAGE IS RESTRICTED TO
FROM COPY FURNISHED TO YOU

INTRODUCTION

Results of the soils investigation that has been conducted at the site of the proposed dam in Putnam County Missouri are summarized in this report. Laboratory testing and analysis has been authorized by Mr. Earle Chamness of Wm. H. Klingner and Associates, Consulting Engineers, acting in behalf of the Putnam County Lake Association, sponsors of the project. Boring and sampling operations were conducted by the Missouri Conservation Commission under the direction of the Consulting Engineers.

SITE DESCRIPTION

Site of the proposed earth dam is located in the valley of Blackbird Creek about 1000 feet west of State Route 5 north of Unionville, Missouri. The stationing used to designate the centerline of the proposed dam originates on the north abutment and terminates at Station 16 + 90 on the south abutment. Borings located on the basis of a preliminary centerline survey originated at Station 0 on the north abutment and terminated at Station 16 + 25 on the south abutment. Exact location of these two lines and of all the borings is indicated on the Soil Boring Location Plan prepared by Klingner and Associates, dated October, 1964. The valley floor at the dam site is quite level and exists

The crest elevation of the dam is 977 feet. The valley floor is about 350 feet below the crest of the proposed dam. At the north abutment the ground slope rises from the valley floor to elevation 977 between Station 7 + 60 and 0. The ground surface is somewhat steeper at the south abutment where the elevation changes from 935 to 977 between Stations 14 + 20 and 16 + 90. At the north abutment the maximum elevation is about 977.

Elevations in excess of 1020 are reported for the ground surface above the terminus of the dam at the south abutment.

Currently the main channel of Blackbird Creek is about 25 feet wide and has a maximum depth of about 7 feet. With a crest elevation of about 977 and a water elevation of 970 the impounded lake will have a surface area of about 1200 acres.

Both of the abutments at this site consist of material derived from the activities of glaciers. By means of borings and laboratory tests on representative samples the characteristics of this glacial drift have been established. The relatively flat valley bottom results from the deposition of alluvium in a valley that was carved into the glacial till. Borings have been made to determine the depth and character of the alluvium in the valley.

character of the subsoil along the centerline of the dam, the valley sediments above and below the dam, and the glacial till in the proposed borrow areas located in the abutments. Twenty-six machine auger borings were made at the locations shown on the Soil Boring Location Map. In addition, hand auger borings were made at inaccessible locations upstream from the centerline of the proposed dam. Depth of drilling varied considerably depending on the location of the boring. In general, the borings in the glacial till were drilled to a depth sufficient to insure the uniformity of the deposit. Borings in the borrow area were drilled below the maximum depth of the proposed borrow excavation.

All borings in the stream valley were drilled to the gray clayey silt glacial till that underlies the alluvium.

Standard penetration tests were performed at selected elevations as the borings progressed. This test is performed by driving a 1 3/8 inch inside--2 inch outside diameter split spoon sampler into the undisturbed soil at the bottom of the drill hole by means of a 140 pound weight falling a distance of 30 inches. The number of blows required to drive this sampler a distance of 12 inches is known as the "N" value of the soil and is recorded on the boring logs. The "N" values are a reliable measure of the relative density of cohesionless soils and can be used to estimate the consistency of cohesive soils.

Samples from the split spoon sampler were placed in glass jars for laboratory tests. Disturbed samples were taken from the borings in the borrow areas.

THIS DOCUMENT IS NOT
FROM COPY FURNISHED TO DOD

Undisturbed samples from the alluvium were obtained by pressing 3-inch diameter seamless tube samplers into the undisturbed soil bottom of the drill hole located near Station 12 + 95. These samples were sealed in the field and transported to the laboratory for extrusion and testing.

LABORATORY TESTING

Laboratory tests on samples obtained from the borings included visual descriptions, moisture content determinations, unconfined compression tests, Atterberg limit determinations, Standard Proctor moisture-density tests, and compression tests on compacted samples. All of these tests were performed during September and October by experienced engineers. Results of these tests are summarized in Tables I, II and III, the boring logs, and on the Standard Proctor curves appended to this report. Test data coupled with the field boring logs are used as a basis for delineating and describing the different soil strata encountered at this site.

SOIL CONDITIONS

It is convenient to divide the deposits at this site into three separate groups when describing the subsoil conditions. The three groups include the glacial till in the abutment areas, the alluvium in the stream valley and the glacial till in the borrow area. The glacial till in the abutment area is the same as the till in the borrow area. However, it is convenient to

discuss the behavior of the till as an embankment foundation separate from the function of the material as a compacted embankment. Specific details pertaining to use of the borrow material will be discussed in a later section of the report.

Soils encountered in the abutment areas consist of very stiff to hard compact glacial till. "N" values from the standard penetration test conducted on these soils range from 14 to 65, and the unconfined compressive strength varies from 5 to 10 tons per square foot. Natural water content ranges from 12 to 15 percent. Near the surface the predominant color is brown, but the color changes gradually with depth, and below a depth of about 25 feet the color is predominantly gray. Throughout the profile this till is characterized by the presence of coarse sand grains and small pebbles. Grain size tests on four representative samples of this material are shown in Table I. Nearly all of the soil passes the Number 10 sieve, and more than 70 percent passes the Number 200 sieve. Grain size tests on the four samples from the borrow areas (also shown in Table I) indicate the same grain size distribution for the glacial till in the borrow area near the south abutment.

The variable character of the alluvium in the stream is indicated on the soil profile shown in Figure 1 and on the individual boring logs. A layer of stratified gray silt clay and clayey silt was encountered near the ground surface in some of the borings. The thickness of this layer varied from about 10 feet at boring 9 + 00 to 25 feet in the vicinity of boring 13 + 00.

PHARM CORP FORMERLY TUDOR

The strata underlying the layer described in the previous paragraph consists of gray silty sand. Most of the logs indicate the grain size increases with depth, and in some holes the sand varied from fine near the top of the layer to coarse near the bottom. There is some evidence of stratification in this strata. The permeability of the sandy alluvium is sufficient to cause seepage losses beneath the dam as well as giving rise to the danger of piping due to seepage. Grain size determinations on samples of the sand indicate that this material would be classified as silty sand, SM. There was an appreciable silt content in most of the samples obtained from this sandy layer. Thickness of the sand layer varies from a few feet near the north abutment to a maximum of 25 feet at Station 13 + 00.

All of the alluvial sediments in the valley bottom are underlain by a strata of gray clayey silt which contains some coarse sand and pebbles. This stiff cohesive material is of glacial origin and is similar to the glacial till of the abutment and borrow areas. The distance from ground surface to the top of this impermeable strata is about 32 feet between Stations 7 + 00 and 12 + 00. Between 12 + 00 and 13 + 50 the average depth to the glacial till is variable and reaches a maximum of 45 feet in the vicinity of Station 13 + 50.

In addition to the primary strata that have been described several distinct minor lenses or strata were encountered in several of the borings. In general these layers were thin and their extent was limited in size in a lateral direction and they were not continuous between borings. The nature of these strata

the fact that the sediments in the valley are heterogeneous and that they may vary considerably from point to point in the profile.

Borings made both upstream and downstream from the centerline of the proposed dam are quite similar to the series of borings made along the centerline.

Ground water level in the valley bottom varies from 10 to 15 feet below the ground surface. Average depth to the free water was about 13 feet when the borings were made during the month of August. It is anticipated that this water level will be encountered at somewhat higher elevations during the wet season of the year. Excavation of a cut-off trench below the water table will require special de-watering considerations in order to maintain stability of the slopes during construction operations.

It has been noted already that the subsoil in the borrow areas is essentially the same as that in the abutment areas. Two separate borrow areas were investigated in the course of this investigation. A total of four borings were drilled in the area south of the dam. These borings are designated 1 through 4, and the location is indicated on the Soil Boring Location Map. Borings 5, 6, 7 and C-372 were drilled in the borrow area at the north abutment. A large representative sample of the soil encountered in each hole was tested in the laboratory. The results of the tests are summarized in Tables I.

II, and III and on the Standard Proctor curves.

The results of the Atterberg Limit tests and grain size determinations indicate that the physical properties of the glacial till are quite uniform. The range in liquid limit is from 29 to 43 with an average of about 35. All of the samples tested are classified as CL, inorganic clays of low to medium plasticity, according to the Unified Soil Classification.

It is noted that the average optimum moisture content at the south area is several percent lower than the north area, and the maximum dry density in the south area is about 5 pounds per cubic foot greater than the samples from the north area. This difference in moisture-density values may be attributed to the fact that the borings in the south area were nearly 45 feet deep whereas all of the borings in the north area were terminated at a depth of 25 feet. This fact that the samples in the north area are from a shallower depth may give an explanation for the somewhat higher liquid limit values for samples from borings 5 and 6.

Several water bearing sand or silty sand pockets were encountered in the borings. Pockets of this type are typical of glacial till deposits. They may range from a few inches to several feet in size and may occur at random locations in rather irregular shapes. If extensive sand lenses are encountered during construction, it will be necessary to waste this permeable material or place it at the outer edges of the dam in such a manner that seepage through the dam will not occur.

This report is the property of the U.S. Army Corps of Engineers and is loaned to you. It is to be returned to the U.S. Army Corps of Engineers when requested.

A series of tests were performed on selected compacted samples of the borrow material to measure the unconfined compressive strength of the soil when compacted at different water contents. The results of these tests are summarized in Table III. The percent compaction reported in this table is the relationship between the dry density of the unconfined compression test sample and the maximum dry density at optimum moisture content. An inspection of this data indicates that it is possible to obtain more than 95 percent of standard proctor maximum density for a wide range of moisture contents. The effect of variations in moisture content on the shear strength is a more critical feature, and therefore careful consideration of this item is essential. It should be noted that the maximum shear strength was obtained at a water content slightly less than that associated with the maximum dry density. Also it is noted that a noticeable reduction in shear strength occurs as the moisture content is increased above that required for maximum density.

Placing of material dry of optimum is undesirable because of the danger of low density, increased permeability and excessive softening and settlement on saturation by the reservoir resulting in possible cracking of the fill. The moisture content should not be appreciably greater than optimum for Proctor maximum density because of the difficulty in placing, subsequent settlement and instability due to the lower shear strength. These considerations lead to the conclusion that it is most desirable to place

the material close to the optimum moisture content at Proctor maximum dry density. A range of ± 2 percent from this optimum value appears to be reasonable for the borrow material proposed for this homogenous dam.

TREATMENT OF EMBANKMENT FOUNDATION

The permeable stratified sediments in the stream valley require special consideration in order to insure that the seepage losses beneath the dam are not excessive and the danger of a piping failure is eliminated. Several methods of intercepting the seepage beneath the dam have been considered by the writer and the consulting engineers. Among these methods are a cut-off trench, a partial cut-off trench, sheet piling, grouting and the use of an upstream blanket. The two most favorable treatments from a cost standpoint are the use of a cut-off wall or an upstream blanket. The most positive method of controlling the amount of seepage beneath the dam and insuring that no difficulty will be encountered due to piping through the foundation or by uplift pressures at the toe is by the installation of an impervious cut-off trench from the existing ground surface to the impermeable glacial till which underlies the alluvium. Use of a drainage blanket upstream from the dam would not be as satisfactory as a cut-off trench because of danger of leaks in the blanket and because of the amount of stripping and material required for a satisfactory cover.

The relatively high water table coupled with the

permeability of the alluvium requires that a well point dewatering system be installed to lower the water table during construction. The water table must be lowered in order to maintain stability of the slopes and to insure that the rolled fill in the core trench will be constructed in the dry. A single stage of well points is capable of lowering the water table about 15 feet. It will be necessary to lower the water table nearly 30 feet throughout most of the trench, and in the area from Station 12 + 0 to 13 + 50 it will be necessary to lower the water table in excess of 40 feet. In order to accomplish the dewatering required it will be necessary to use a multiple stage well point installation where separate rows of well points are driven from benches cut in the side slopes of the core trench. The vertical distance between these benches should not exceed 15 feet, and it would be desirable to limit this distance to 13 feet. The benches should be at least 6 feet wide, and a slope of 0.5 feet horizontal to 1 foot vertical is considered satisfactory because this will result in an average slope of about 1 foot horizontal to 1 foot vertical for the entire depth of the excavation.

The dewatering operation will cause some consolidation of the loose sediments and will cause an increase in effective stress in the foundation material. These two factors also will contribute to the stability of the excavation slopes. The width of the core trench should be at least 20 feet to provide a positive barrier, and the bottom of the cut-off wall should extend at least 2 feet into the impermeable glacial till. The centerline of the bottom of the core trench should be about

50 feet upstream from the centerline of the dam and should parallel the dam across the main portion of the valley. In the abutment areas a key trench should be provided to insure a water tight bond between the rolled fill and the natural ground.

The material excavated from the core trench can be used as a stabilizing fill on the lower portions of the slopes of the rolled fill dam. It may be possible to use some of the granular material from the trench for the pervious toe drain required in the embankment. A decision concerning the use of this material cannot be made until the excavation has advanced to the point where careful inspection and grain size determinations can be made on representative samples of the material.

EMBANKMENT CONSIDERATIONS

There are several factors that must be considered in the evaluation of the slopes selected for the rolled homogeneous dam. Among these are the shear strength of the compacted fill, the shear strength of the foundation, and the seepage through the embankment.

Shear strength determinations on the compacted specimens indicate that an upstream slope of 3:1 and a downstream slope of $2\frac{1}{2}$:1 is satisfactory provided that the dam is not subject to a drawdown rate of more than 6 inches per day after the maximum reservoir level has been maintained for a sufficient length of time to saturate the embankment.

Foundation material beneath this proposed area has an average "N" value between 4 and 10, and as a result the consistency of the material would be classified as medium. An increase in the overall safety can be accomplished by using the excess of material excavated from the core trench as a stabilizing fill or toe berm on the lower portions of the embankment. This stabilizing fill will be used to provide weight only and consequently, no special methods of construction or compaction requirements are needed for the placement of this material. Use of the excavated material for this purpose will provide for a satisfactory method of disposing of this waste material.

It is anticipated that some settlement of the embankment will occur due to the consolidation of the alluvium as the result of the increase in stress due to the embankment. Because of the permeable nature of the silty sand, most of the consolidation will occur during the construction of the embankment, and very little settlement due to consolidation of the foundation will occur after the embankment is completed. It is estimated that the total settlement due to consolidation in the foundation during construction will not exceed one foot. Also it is anticipated that another foot of settlement will occur within the compacted embankment even though the placement moisture and compaction procedures are carefully controlled. A major portion of the embankment consolidation also will occur during the construction operations.

Even though the embankment will be constructed of carefully compacted cohesive material, there will be some seepage through the embankment. It will take some time for the seepage through the dam to reach a steady state of flow. This steady state condition which determines the phreatic surface of seepage through the dam will establish the maximum saturation of the embankment and is the most critical post-construction condition for the stability of the downstream slope. If the phreatic surface intercepts the slope above the base of the dam a general softening of the fill will occur, and as a result the stability of the slope may become critical. In order to maintain the stability of the downstream slope it is essential that a toe drain be installed to intercept the flow through the embankment in such a manner that the phreatic surface is kept well within the compacted embankment.

The toe drain can consist of a filter drain that starts at the downstream toe of the embankment and extends upstream to a point about 60 feet from the centerline of the dam. This toe drain should be extended across the valley and up the abutments to the maximum storage elevation. The minimum thickness of the toe drain should not be less than 2 feet. A perforated pipe underdrain should be installed in a trench about 20 feet upstream from the toe of the dam to collect the water from the toe drain.

A satisfactory alternate to the toe drain would be

AD-A105 254

HOSKINS-WESTERN-SONDEREGGER INC LINCOLN NE
NATIONAL DAM SAFETY PROGRAM, LAKE THUNDERHEAD DAM (MO 10007), G--ETC(U)
MAY 80 R S DECKER, G JAMISON, G ULMER
DACW43-80-C-0071


F/G 13/13

UNCLASSIFIED

NL

3 OF 3

AD A
105254



END

DATE
FILMED
10-81
DTIC

the installation of a strip drain within the embankment. This drain should have a cross section of 6 x 12 feet across the main valley and 4 x 12 feet in the abutment areas. Granular discharges having dimensions of 4 x 6 feet should be spaced at about 100 foot centers and should extend from the strip drain to the downstream slope. The centerline of this strip drain should be located about 60 feet downstream from the axis of the dam. It is believed that the use of a strip drain would result in a saving of granular material but would require some extra effort during construction.

Several other features of the embankment design such as crest width, freeboard, upstream slope protection, downstream slope protection and surface drainage have an effect on the stability of the embankment. Since these features require considerations other than soils, they are considered to be beyond the scope of this report.

Grain Size Data

Boring No.	Depth	Percentage Passing			Unified Classification
		#10	#40	#200	
14 + 73	10'	94.5	88.5	70.2	CL
16 + 25	10'	97.7	93.0	73.5	CL
3 + 35	5'	99.8	96.6	78.6	CL
5 + 58	10'	99.8	97.7	72.8	CL
12 + 96	12'	100	96.9	41.9	SM
12 + 96	18'	99.9	98.5	33.7	SM
1		99.0	90.2	63.0	CL
2		97.8	91.6	70.0	CL
3		99.4	91.4	70.2	CL
4		99.6	95.3	76.0	CL

Table I

THIS PAGE IS BEST QUALITY PRINTED
FROM COPY FILM MADE TO DDC

Summary of Data for Borrow Area North

Sample Number	Moisture Limit	Plasticity Limit	Soil Classification	Moisture Content, %	Maximum Dry Density pcf
1	30	13	CL	12.3	113.3
2	36	15	CL	15.1	112.8
3	35	14	CL	12.8	116.8 <i>So.</i>
4	33	14	CL	12.3	118.2
5	40	15	CL	15.9	110.6
6	43	15	CL	17.4	111.3 <i>No.</i>
7	36	15	CL	16.0	110.8
0-372	29	14	CL	12.6	121.3

Table II

$\frac{8}{114.4}$ $\frac{8}{910.1}$
 Ave 14.3 113.7

Borings 5, 6, 7 - 0-372 in Borrow Area North.

ave optimum Moisture = 15.5%

Ave Max. Density = 111.0 pcf.

Borings 1, 2, 3, 4 in Borrow Area South

ave optimum Moisture = 13.1%

Ave Max. Density = 116.5 pcf

Summary of Test Data
Selected Compacted Samples


<u>Borrow Sample No.</u>	<u>Moisture Content w, %</u>	<u>Compressive Strength q_u, tsf</u>	<u>Percent Compaction</u>
1	8.0	2.73	
	8.5	4.56	
	9.8	4.93	
	12.6	3.61	
	14.5	2.10	
2	9.9	4.56	96.0
	13.7	2.69	97.7
	15.9	2.55	100.0
	20.2	1.28	94.4
3	10.9	2.62	95.2
	13.1	3.84	100.0
	16.8	1.88	95.5
4	9.6	4.20	94.7
	12.2	3.80	99.7
	14.6	2.30	98.5
	17.0	1.45	95.1
5	11.0	3.95	97.0
	13.4	3.0	98.8
	16.1	2.10	100.0
	19.4	1.08	97.0
6	12.0	4.13	95.9
	15.0	3.50	98.8
	17.8	2.20	99.6
	19.9	1.15	95.7
7	11.5	2.2	94.7
	13.8	2.6	99.3
	17.0	2.76	97.6
	18.9	1.45	98.2
0-372	11.9	4.2	99.9
	15.4	2.35	99.3
	17.9	1.3	97.9

Table III

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 3+35




Date of boring: Started Aug 27, 1964 Finished _____ Date of tests Oct. 3, 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by TSE
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 5+58



Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____


FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964

BORING NO. 7+00



Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964

Type of drilling Machine Auger Sampling tools used Split Spoon

Size and depth of casing _____ Fixed datum used _____

Boring Contractor _____ Foreman _____

Classification by _____


Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 9+00




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 10+00




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 11-20




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 12+00



NATURAL WATER CONTENT (% Dry weight) 10 20 30 40

Date of boring: Started Aug 1964 Finished _____ Date of tests OCT 1964

Type of drilling Machine Auger Sampling tools used Split Spoon

Size and depth of casing _____ Fixed datum used _____

Boring Contractor _____ Foreman _____

Classification by _____


Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE Oct 1964
BORING NO. 12-53




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE Oct 1964
BORING NO. 13+06




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE Oct 1964
BORING NO. 13+50




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 14+00



NATURAL WATER CONTENT (% Dry weight) 0 10 20


Date of boring: Started Aug 1964 Finished _____ Date of tests OCT 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE Oct 1964
BORING NO. 15+72




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used split spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 14125



NATURAL WATER CONTENT (% Dry weight) 0 10 20


Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used split spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE Oct 1964
BORING NO. A




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used split spoon
Size and depth of casing _____ Fixed datum used _____
Boring Cor. _____ Foreman _____
Classification _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE Oct 1964
BORING NO. L Fork




Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1964
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE OCT 1964
BORING NO. 3




Date of boring: Started AUG 1964 Finished _____ Date of tests OCT 1964
Type of drilling MACHINE AUGER Sampling tools used SPLIT SPOON
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____

THOMAS S. FRY PH.D
CONSULTING ENGINEER

TEST BORING DATA

JOB NO. _____ LOCATION PUTNAM COUNTY LAKE DATE Oct 1964
BORING NO. 9




0 10 20 30 40
NATURAL WATER CONTENT (% Dry weight)


Date of boring: Started Aug 1964 Finished _____ Date of tests Oct 1
Type of drilling Machine Auger Sampling tools used Split Spoon
Size and depth of casing _____ Fixed datum used _____
Boring Contractor _____ Foreman _____
Classification by _____
Remarks _____

FIGURE NO. _____


Putnam County Lake
Standard Proctor Test
Boring No 1
October, 1964




Putnam County Lake
Standard Proctor Test
Boring No 2
October, 1964




Putnam County Lake
Standard Proctor Test
Boring No 3
October, 1964




Putnam County Lake
Standard Proctor Test
Boring No 4
October, 1964




Putnam County Lake
Standard Proctor Test
Boring No 5
October, 1964




Putnam County Lake
Standard Proctor Test
Boring No 6
October, 1964




Putnam County Lake
Standard Proctor Test
Boring No 7
October, 1964



Putnam County Lake
Standard Proctor Test
Station 0-372
October, 1964



Putnam County Lake
Standard Proctor Test
Station 0-372
October, 1964



APPENDIX E

DIVISION II

SOIL ANALYSIS, LOG OF SOUNDINGS

AUGUST & SEPTEMBER, 1964

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 1

Project UNIONVILLE LAKE (Official)
(Unofficial)

Job No. _____
Purpose _____

Location _____
County FITZGERALD

Soundings by V. DOUGHTY
Date AUG. 27, 1969

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
<u>12.12'</u> <u>3+35</u>			<u>0-10</u>		<u>BROWN CLAY STIFF</u>
			<u>10-26</u>		<u>BROWN SANDY CLAY - STIFF</u>
					<u>PENETRATION TEST</u>
			<u>2'</u>		<u>18 BLOWS PER FOOT</u>
			<u>5'</u>		<u>41 "</u>
			<u>10'</u>		<u>56 "</u>
<u>21.71'</u> <u>5+58</u>			<u>0-14</u>		<u>BROWN CLAY</u>
			<u>14-18</u>		<u>BROWN SANDY CLAY</u>
			<u>18-24</u>		<u>BROWN VERY SANDY CLAY</u>
			<u>24-56</u>		<u>GRAY CLAY</u>
					<u>PENETRATION TESTS</u>
			<u>2'</u>		<u>12 BLOWS PER FOOT</u>
			<u>5'</u>		<u>20 "</u>
			<u>10'</u>		<u>15 "</u>
			<u>15'</u>		<u>20 "</u>
			<u>20'</u>		<u>65 " SMALL ROCK & SANDY CLAY</u>

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 2

Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location _____

Soundings by V. DOUGHTY

County PULASKI

Date AUG 19, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
7+00			0-13		GRAY SILTY CLAY LOAM
			13-15		GRAY SAND, COARSE GRAVEL & WATER 13'
			15-28		GRAY CLAYEY SAND, SILTY - SOFT & WET
			28-41		GRAY CLAY - STIFF
					PENETRATION TESTS
			2'		11 BLOWS PER FOOT
			5'		7 "
			10'		7 "
			15'		7 "
			20'		5 " SLIGHT RECOVERY

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

SOIL ANALYSIS

Data Sheet No. 3

Job No.

Soundings by V. DOUGHTY

Date AUG 18, 1964

Station	Loc.†	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
9+00			0-4		BROWN TO BLACK SILT LOAM - DRY
			4-20		GRAY SANDY SILT - WATER - 7.5'
			20-31		BLACK & GRAY CLAYEY SAND, SILTY - SOFT & WET
			31-41		GRAY CLAY - STIFF
					PENETRATION TESTS
			2'		7 BLOWS PER FOOT
			5'		3 "
			10'		3 "
			15'		3 " SLIGHT RECOVERY
			20"		5 "

Miscellaneous Data

- + Distances given from centerline are perpendicular thereto unless otherwise noted.
- * Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings.

Data Sheet No. 4

Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location _____

Soundings by V. DOUGHTY

County PUTNAM

Date AUG 29, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
10+00			0-5		BROWN SILT LOAM - DRY
			5-10		BROWN SILTY SAND
			10-25		GRAY SILTY SAND
			25-31		GRAY COARSE SAND, GRAVELLY
			31-41		GRAY CLAY
					PENETRATION TESTS
			2'		6 BLOWS PER FOOT
			5'		3 "
			10'		6 "
			15'		3 "
			20'		6 "

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 5Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location 3.5 MILES N. UNIONVILLE ON HWY 5Soundings by V. DOUGHTYCounty FULTONDate AUG 18, 1967

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
11+00			0-4		BROWN TO BLACK SILT LOAM - DRY
			4-9		BLACK SILT LOAM - MOIST - WATER 8'
			9-21		GRAY SANDY SILT - WET
			21-22		GRAY CLAYEY SAND, SILTY - SOFT & WET
			22-34		COARSE GRAY SAND
			34-51		GRAY CLAY - STIFF
					PENETRATION TESTS - STD. SPLIT-SPOON
			2'		7 BLOWS PER FOOT
			5'		8 "
			10'		3 "
			15'		3 "
			20'		5 "
			25'		8 "
			30"		NO RECOVERY - SAND FILLED IN HOLE 2'

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 8

Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location _____

Soundings by V. DOUGHTY

County PUTNAM

Date AUG. 21, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
13+06			0-5		BROWN SILT LOAM - DRY
			5-10		BROWN SILT LOAM - MOIST-WATER 2'
			10-20		BROWN & GRAY SAND - SILTY
			20-46		GRAY SAND, FINE & SILTY, COARSE 38-46
			46-60		GRAY CLAY
					PENETRATION TESTS
			2'		8 BLOWS PER FOOT
			5'		7 "
			10'		4 "
			15'		4 "
			20'		6 "
12+95					SHELBY TUBE - 3" - SAMPLES
			6'		BROWN SILT LOAM
			12		GRAY SILTY SAND
			18		GRAY SAND
			28		NO RECOVERY - HOLE CLOSED IN 95'

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 10Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location _____

Soundings by V. DAUGHTYCounty PITMANDate AUG. 19, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
15+00			0-8		BROWN SANDY CLAY LOAM
			8-14		BROWN SANDY CLAY - WATER 13.5'
			14-15		BROWN SAND & WATER
			15-18		BROWN CLAY
			18-20		BROWN & GRAY CLAY
			20-41		GRAY CLAY
					PENETRATION TESTS
			2'		NO RECOVERY - TREE ROOTS
			5'		7 Blows PER FOOT
			10'		14 "
			15'		15 "
			20'		19 "
			26'		100 " FOR 9" - GRAY CLAY

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 11

Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location _____

Soundings by K. DOUGHTY

County PITMAN

Date SEPT. 3, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
14+73	ABT. -2'		0-26		BROWN CLAY - STIFF
			26-41		GRAY SILTY CLAY
					PENETRATION TESTS
			2'		32 BLOWS PER FOOT
			5'		27 "
			10'		14 "
			15'		21 "
			20'		21 "
16+25	ABT. -2'		0-36		BROWN CLAY
					PENETRATION TEST
			2'		25 BLOWS PER FOOT
			5'		25 "
			10'		20 "

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

SOIL ANALYSIS

Data Sheet No. 12.

Job No.

Purpose

Soundings by W. DOUGHTY

Date AUG 31, 1968

[illegible]

Miscellaneous Data

- + Distances given from centerline are perpendicular thereto unless otherwise noted.
- * Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 13

Project UNIONVILLE LAKE (Official)
(Unofficial)

Job No. _____

Purpose _____

Location _____

Soundings by V. DOUGHERTY

County PITMAN

Date AUG. 31, 1962

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
7					WEST. BY CREEK TIMBER - EAST OF FEUSE
110 LEFT			0-3		BROWN & GRAY CLAY LOAM
FORK			3-12		BROWN & GRAY CLAY - STIFF
			12-14		BROWN SILTY CLAY - MED. SOFT
			14-17		LAYERS BROWN & GRAY CLAY & SAND - WATER 14
			17-21		GRAY CLAY - MED. SOFT
			21-26		GRAY SANDY CLAY
					PENETRATION TESTS
			5'		5 BLOWS PER FOOT
			10'		4 "
			15'		3 "
			24'-25'		3 " - SOME GRAY SAND CAVED IN
					ABT. 1' & GRAY SANDY CLAY

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 14

Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location _____

Soundings by V. DAUGHTY

County PUTNAM

Date SEPT. 1, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
STA. A					RT. OF 11+00 ² <u>UPSTREAM</u>
			0-6		BROWN SILT LOAM - DRY
			6-9		BROWN SILT LOAM - MOIST
			9-14		GRAY CLAYEY SAND - WATER 9'
			14-40		GRAY SILTY SAND - ROCKS & GRAVEL 26 TO 32
			40-46		GRAY SILTY CLAY - SOFT
			46-51		GRAY CLAY - STIFF
					PENETRATION TESTS
			2'		8 BLOWS PER FOOT
			5'		4 " " "
			10'		4 " " "
			15'		2 " " "
			20'		4 " " "

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

SOIL ANALYSIS

Data Sheet No. 15

Job No. _____

Soundings by V. DOUGHTY

Date SEPT 1, 1964

Miscellaneous Data _____

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 16Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose _____

Location _____

Soundings by V. DOUGHTYCounty POTOMACDate SEP 2, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
"9"					
			0-6		BROWN SILT LOAM - DRY
			6-11		BROWN SILTY CLAY LOAM - WATER 11'
			11-20		GRAY SILTY CLAY
			20-30		GRAY CLAYEY SAND
			30-41		GRAY CLAY
					PENETRATION TESTS
			2'		6 BLOWS PER FOOT
			5'		4 "
			10'		4 "
			20'		5 "

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 17

Project UNIONVILLE LAKE (Official)

Job No. _____

(Unofficial)

Purpose FOR AREA

Location _____

Soundings by V. DOUGHTY

County PITMAN

Date AUG. 25, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
NO. 1			0-50		BROWN CLAY, SLIGHTLY SANDY - SMALL SAND POCKETS APT. 12 & 26
NO. 2			0-46		BROWN CLAY, SLIGHTLY SANDY
NO. 3			0-46		BROWN CLAY, SLIGHTLY SANDY
NO. 4			0-20		BROWN CLAY, SLIGHTLY SANDY
			20-24		BROWN SAND - WET
			24-30		BROWN CLAY
			30-34		BROWN SAND - WET
			34-40		BROWN CLAY

Miscellaneous Data VERY SMALL AMOUNT OF GRAY CLAY IN NO. 4

SOMEWHERE APT. 24-35, POSS. ONLY FEW INCHES THICK.

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

DEVELOPMENT SECTION

SOIL ANALYSIS

Log of Soundings

Data Sheet No. 18

Project WINDMILL LAKE (Official)

Job No. _____

(Unofficial)

Purpose FOR SEEDS

Location _____

Soundings by V. D. DUNN

County JOHN

Date SEPT. 5, 1964

Station	Loc. +	Surf. Elev.	Depth	Bott. Elev.	Log of Materials*
0-372					ON & IN FILLER SPILLWAY
			0-11		BROWN CLAY
			11-13		BROWN SANDY CLAY
			13-16		BROWN CLAY
			16-25		BROWN CLAYEY SAND - WET
'5'			0-25		BROWN CLAY
'6'			0-25		BROWN CLAY - SANDY & TO 1/2
'7'			0-25		BROWN CLAY

Miscellaneous Data _____

+ Distances given from centerline are perpendicular thereto unless otherwise noted.

* Persons using this information are cautioned that the materials shown are determined by the equipment noted and accuracy of the "Log of Material" is limited thereby and by judgment of the operator. Log of operations is an integral part of this information.

APPENDIX E

DIVISION III

GEOLOGIC REPORT, MISSOURI GEOLOGICAL SURVEY

1963

INSPECTION REPORT, MISSOURI GEOLOGICAL SURVEY

1972

ENGINEERING GEOLOGIC REPORT, MISSOURI

GEOLOGICAL SURVEY

1978

*Prepared by James A. Martin and James H. Williams
Missouri Geological Survey - 1963*

GEOLOGIC REPORT ON THE PROPOSED PUTNAM COUNTY LAKE SITES
NEAR UNIONVILLE, MISSOURI

A surface geologic study of two lake sites near Unionville, Missouri, was made for the Putnam County Jaycees. Of the two sites, the most favorable is the North Site located on Blackbird Creek north of Unionville. The dam site is upstream (west) of Missouri Highway 5. The South Site on South Blackbird Creek west of Highway 129 is less suitable since bedrock openings and mine drifts indicate exploration and construction costs would be greater than at the North Site. Each lake site would have approximately 1200 surface acres of water.

North Site: *This site used 1200*

Both the abutments and the impoundment area will be in glacial drift. An examination of the area showed bedrock to be buried at depth by glacial drift. A water height of 60 feet at the dam site will create a lake area of about 1200 acres. The drainage area is estimated to be 18,000 acres. The location of the dam site is in the SW 1/4, SE 1/4, Section 10 and NE 1/4, NE 1/4, Section 15, T. 66 N., R. 19 W. All geologic features point to a safe lake at this site with regards to possible water loss to the bedrock.

Water loss hazards at the site are related to the glacial drift and alluvium. Possible loss would be through sand bodies in the abutment and underflow through the alluvium or glacial sands in Blackbird Creek. Random, isolated sand bodies are known to be present in glacial drift. Although none were observed, it is recommended that the abutments be augered to determine the glacial drift characteristics. Exploration along

EXHIBIT "B"

the center line across Blackbird Creek should be made to determine the characteristics of the valley alluvium. Because the valley alluvium has been deposited by running water there may be sand and gravel zones interlayered with silt and clay beds. Therefore, underflow through pervious sands and gravels beneath the dam is a major hazard if not intercepted by the core trench or a cut off curtain. Support characteristics of the foundation material may vary across the valley because of its alluvial origin.

South Site:

The dam site is in the NE 1/4, SW 1/4, SW 1/4, Section 22, and NW 1/4, NW 1/4, NW 1/4, Section 27, T. 65 N., R. 18 W., on South Blackbird Creek, west of Missouri Highway 129. Bedrock, exposed upstream and downstream from the damsite, dips toward the northeast. Limestone, shale and coal beds are covered by a thin veneer of soil on the abutments. Bedrock belongs to the Pennsylvanian system and includes formations from the Fort Scott-Higginsville limestone-up to and including the Altamont-Worland limestone. The section is a series of alternating thin limestone beds 1 to 4 feet in thickness interlayered with shale and coal beds. A number of mine drifts were observed along the valley of the lake and in Kinney valley to the north of the left abutment. Small underground mining operations are presently active in the area.

Potential water loss from the lake to the bedrock may occur at the abutments and in the upstream area. Such loss would be via bedding planes and joints in the limestone units. Because of the intensified

ADDENDUM TO LAKE THUNDERHEAD

Putnam County, Missouri

Inspection of Lake Thunderhead on 8 May 1972, indicates the following:

- 1) Seepage on the left abutment slope is apparently more extensive than previous times of investigation. An area approximately 100 feet square is water saturated. The water is present as surface flow gradually seeping through what is apparently a lense of sandy loam soil that makes up at least a portion of the left abutment.
- 2) The lagoons, although water filled, apparently are severely affected by subsurface water seepage. Water in the lagoons seems to be mostly that which would be derived from the water bearing gravels and sands that were exposed during lagoon construction.
- 3) The interception ditches do not appear to be functioning. Consequently, seepage from the dam has water saturated much of the upstream portion of the lagoon levees outside of the lagoon as well as contributed to a portion of the water within the lagoons.
- 4) A significant amount of water seepage is welling up in the manhole present where the sewer line has been constructed under the dam.



James H. Williams
Geologist and Chief
Engineering Geology Section
Missouri Geological Survey and
Water Resources
May 17, 1972

FOR FILE ONLY


ENGINEERING GEOLOGIC REPORT ON LAKE THUNDERHEAD

PUTNAM COUNTY, MISSOURI

LOCATION: NW $\frac{1}{4}$, NE $\frac{1}{4}$, NE $\frac{1}{4}$, Sec. 15, T. 66 N., R. 19 W., Seymour Quadrangle.

The dam site was selected by J.A. Martin-J.H. Williams in 1963. It has served the purpose well except for financial problems of the developers.

One point not observed in the original investigation and later drilling by the Conservation Commission and engineers was the significance of a terrace on the left, north, abutment. A line of seepage has persisted on the eastern portion of this terrace some 200-300 feet from the lake. Water movement is being controlled by the stratified terrace deposits. Leakage has remained unchanged for the past 5 to 6 years. It does not appear to pose a threat to the dam.


Dr. J. Hadley Williams, Chief
Applied Engineering & Urban Geology
Geology & Land Survey
August 23, 1978

**DATE
LMED**